

Guan Auto Service

Business Reg No.:53230297D

Blk 7 Sin Ming Industrial Estate Sector C #01-80/82 Singapore 575642
TEL: 9388 4210 Fax: 64511706 Email: guanautoservice@gmail.com

China Taiping Insurance (S) Pte Ltd
3 Anson Rd
16-00 Springleaf Tower
Singapore 079909

Attention : Motor Claims Department

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Estimate : ES1908003

Date : 2/8/2019

Vehicle Num. : SLV6894M

Make/Model : Kia Forte K3

Chassis Num. : KNAFX411MJ5752057

/N	Quantity	Particular	Unit Price	Amount \$\$
LIST ITEMS :				
1	1	FRONT BONNET / Buc.	835.00	835.00
2	2	FRONT BONNET HINGE / BT.	35.00	70.00
3	1	FRONT BONNET LOCK / OT.	65.00	65.00
4	1	FRONT BONNET INSULATOR / Clamp	141.00	141.00
5	10	FRONT BONNET INSULATOR CLIP / N/C	2.00	20.00
6	4	FRONT BONNET STOPPER / MIS	4.00	16.00
7	1	FRONT BUMPER / MIS.	639.00	639.00
8	2	FRONT BUMPER RETAINER / RL	16.00	32.00
9	2	FRONT BUMPER BRACKET ?	16.00	32.00
10	1	FRONT BUMPER SPONGE / MIS	84.00	84.00
11	1	FRONT BUMPER REINFORCEMENT / FR	496.00	496.00
12	1	FRONT BUMPER LOWER GRILLE / MIS	70.00	70.00
13	12	FRONT BUMPER CLIP / N/C.	2.00	24.00
14	1	FRONT BUMPER LID ?	55.00	55.00
15	2	FRONT BUMPER AIR DUCT ?	33.00	66.00
16	2	FRONT BUMPER AIR DUCT CURTAIN ?	45.00	90.00
17	1	FRONT BUMPER LOGO / N/C	32.00	32.00
18	2	FOGLAMP ?	241.00	482.00
19	1	FRONT GRILLE / MIS / Art	328.00	328.00
20	1	FRONT GRILLE TOP GARNISH / Art	59.00	59.00
21	1	FRONT GRILLE TOP RUBBER ?	29.00	29.00
22	1	LICENSE PLATE BASE / MIS	18.00	18.00
23	2	FRONT FENDER / Buc.	396.00	792.00
24	2	FRONT FENDER INNERSHIELD / MIS	95.00	190.00
25	16	FRONT FENDER INNERSHIELD CLIP / N/C	2.00	32.00
26	2	FRONT FENDER BRACE BRACKET X	35.00	70.00
27	2	FRONT FENDER INSULATOR X / SN	28.00	56.00
28	2	HEADLAMP / CPL	1,523.00	3,046.00
29	1	SUPPORT PANEL / BT	675.00	675.00
30	2	SUPPORT AIR GUIDE / RL.	19.00	38.00
31	1	A/C CONDENSER / BT	687.00	687.00
32	1	A/C LIQUID PIPE ?	601.00	601.00
33	1	A/C DISCHARGE PIPE ?	122.00	122.00
34	1	RADIATOR / BT	492.00	492.00
35	1	RADIATOR TOP HOSE / TR	36.00	36.00

Guan Auto Service

Business Reg No.:53230297D
 Blk 7 Sin Ming Industrial Estate Sector C #01-80/82 Singapore 575642
 TEL: 9388 4210 Fax: 64511706 Email: guanautoservice@gmail.com

China Taiping Insurance (S) Pte Ltd
 100A Thomson Rd
 #00 Springleaf Tower
 Singapore 079909

Attention : Motor Claims Department

Estimate : ES1908003

Date : 2/8/2019

Vehicle Num. : SLV6894M

Make/Model : Kia Forte K3

Chassis Num. : KNAFX411MJ5752057

	Quantity	Particular	Unit Price	Amount \$S
LIST ITEMS :				
6	1	RADIATOR BOTTOM HOSE ?	38.00	38.00
7	2	RADIATOR TOP BRACKET ?	22.00	44.00
8	1	RADIATOR FILLER NECK ?	49.00	49.00
9	1	RADIATOR FILLER CAP ?	25.00	25.00
0	1	AIR INTAKE MANIFOLD ?	906.00	906.00
1	1	AIR INTAKE THROTTLE BODY ?	636.00	636.00
2	1	AIR FILTER BOX ASSY ?	139.00	139.00
3	1	AIR INTAKE AIR DUCT / CRA.	177.00	177.00
4	1	AIR INTAKE AIR DUCT SHIELD / DR.	10.00	10.00
5	1	AIR INTAKE AIR RESONATOR BOX / CRA.	144.00	144.00
6	1	ENGINE UNDER COVER / MS	77.00	77.00
7	2	ENGINE UNDER SIDE COVER ?	25.00	50.00
8	12	ENGINE UNDER COVER CLIP / AC.	3.00	36.00
9	3	ENGINE MOUNTING ?	713.00	2,139.00
10	1	A/T VALVE BODY COVER (OIL PAN) ?	132.00	132.00
11	1	A/T SWITCH INHIBITOR ?	115.00	115.00
12	1	FUSE BOX TOP COVER / COT.	26.00	26.00
13	1	FUSE BOX ASSY X NN	534.00	534.00
14	1	WIPER WASHER TANK / CRA	88.00	88.00
15	1	WASHER MOTOR X NN	54.00	54.00
16	1	WASHER TANK WATER LEVEL SENSOR X NN	28.00	28.00
17	1	WASHER TANK CAP X NN	6.00	6.00
18	1	FRONT LH SHOCK ABSOBER /	280.00	280.00
19	1	FRONT LH SHOCK ABSOBER TOP MOUNTING / { HT	85.00	85.00
20	1	FRONT LH LOWER ARM /	338.00	338.00
21	1	FRONT LH KNUCKLE ARM /	350.00	350.00
22	1	FRONT LH WHEEL BEARING /	131.00	131.00
23	1	FRONT LH STABIL LINKAGE ?	72.00	72.00
24	1	FRONT LH WHEEL RIM / COT	290.00	290.00
25	1	REAR BOOT LID / BAC	1,073.00	1,073.00
26	1	REAR BOOT LOCK X NN	112.00	112.00
27	1	REAR BOOT WEATHERSTRIP / TOT.	100.00	100.00
28	2	REAR BOOT HINGE X REPAIR.	68.00	136.00
29	1	REAR BOOT LOCK X NN	435.00	435.00
30	1	REAR BOOT TRIM X NN	82.00	82.00

Guan Auto Service

Business Reg No.:53230297D

Blk 7 Sin Ming Industrial Estate Sector C #01-80/82 Singapore 575642

TEL: 9388 4210 Fax: 64511706 Email: guanautoservice@gmail.com

ng Insurance (S) Pte Ltd

d

ingleaf Tower
079909

Motor Claims Department

Estimate : ES1908003

Date : 2/8/2019

Vehicle Num. : SLV6894M

Make/Model : Kia Forte K3

Chassis Num. : KNAFX411MJ5752057

Quantity	Particular	Unit Price	Amount \$S
LIST ITEMS :			
8	REAR BOOT TRIM CLIP / <i>MC</i>	3.00	24.00
1	REAR BOOT LOGO /	37.00	37.00
1	REAR BOOT EMBLEM - CERATO / / <i>MC</i>	35.00	35.00
1	REAR BOOT EMBLEM - K3 / /	48.00	48.00
1	REAR BUMPER / <i>TN</i>	668.00	668.00
1	REAR BUMPER REINFORCEMENT / <i>CIA</i>	313.00	313.00
2	REAR BUMPER REINFORCEMENT BRACKET ?	120.00	240.00
1	REAR BUMPER LOWER LID / <i>NR</i>	347.00	347.00
2	REAR BUMPER RETAINER / <i>CH DE</i> , <i>RH X NN</i>	29.00	58.00
2	REAR BUMPER LOWER BEAM BRACKET ?	5.00	10.00
2	REAR BUMPER UPPER BEAM BRACKET ?	3.00	6.00
10	REAR BUMPER CLIP / <i>MC</i>	2.00	20.00
1	REAR LH FENDER / <i>Bne</i>	1,133.00	1,133.00
1	REAR LH FENDER INNERSHIELD ?	75.00	75.00
6	REAR LH FENDER INNERSHIELD CLIP / <i>MC</i>	2.00	12.00
1	REAR LH FENDER AIR DUCT / <i>BL</i>	32.00	32.00
1	REAR LH FENDER INNER TRIM / <i>BL</i>	161.00	161.00
1	LH TAILAMP / <i>CIA</i> . X2	788.00	788.00 <i>1576</i>
1	LH BOOTLAMP / <i>CIA</i> .	710.00	710.00
1	REAR END PANEL ?	274.00	274.00
1	REAR END PANEL TOP GARNISH ?	58.00	58.00
1	REAR WINDSCREEN GLASS MOULDING / <i>MC</i> .	27.00	27.00
List Total \$S :			
			24,533.00
10% Discount \$S :			
			2,453.30
			22,079.70

SPECIAL NETT ITEMS :

1	LICENSE PLATE & CASING / <i>PL</i>	45.00	45.00
5	A/T FLUID X 5 LITERS / <i>BL</i>	32.00	160.00
1	REVERSE SENSOR ?	250.00	250.00
1	WINDSCREEN GLASS SEALANT / <i>MC</i>	40.00	40.00
4	HOSE CLAMP X4 ?	8.00	32.00

Guan Auto Service

Business Reg No.:532302970

Blk 7 Sin Ming Industrial Estate Sector C #01-80/82 Singapore 575642

TEL: 9388 4210 Fax: 64511706 Email: guanautoservice@gmail.com

China Taiping Insurance (S) Pte Ltd
3 Anson Rd
#16-00 Springleaf Tower
Singapore 079909

Estimate : ES1908003

Date : 2/8/2019

Vehicle Num. : SLV6894M

Make/Model : Kia Forte K3

Chassis Num. : KNAFX411MJ5752057

Attention : Motor Claims Department

S/N	Quantity	Particular	Unit Price	Amount \$S
		SPECIAL NETT ITEMS :		
6	1	COOLANT X 1LITER	20.00	20.00
7	1	FRONT LH WHEEL TYRE	150.00	150.00
				697.00

LABOUR :

1	To knock jackout damaged parts, panel beating , welding, align, remove and refix accident parts.	2,800.00	1600.
2	To spray paint on affected portions.	2,200.00	1800
3	To change front lh suspension parts.	180.00	150
4	To conduct wheel alignment.	65.00	60.
5	To remove and install a/c components and recharge a/c gas.	100.00	?
6	To remove and install engine mounting , A/T valve body cover.	220.00	180 ?
7	To remove and refit rear trims , seats and upholstery.	180.00	60.
8	To remove and refit rear wind/creen glass.	150.00	100.
9	To supply panel sealant to seal off all weld spot seam and gap.	90.00	X } NN
10	To remove and refit fuel filler pipe and hose.	80.00	X }
11	To spray rubberized under-coating.	120.00	80.
12	To remove out engine , gearbox , driveshaft , front cross member and fix back the same .	400.00	?
13	To pull and realign chassis member.	350.00	200.
14	To remove and install fuse box assy.	160.00	X NN
15	To check lighting and wiring.	60.00	30
16	To use diagnostic computer to check and reset the system. To provide Towing Services charge malaysian to Singapore	250.00	X NN 900.00 ?
		7,405.00	8205

14 Days -	Excess \$ 3500	Total \$S:	30,181.70
P/P Repair	Not Authorised		30,181.70
before/After repair photos.	08/8/19.		31,690.90
Gua Chai - 82880282			