

13/2011

ASS. REC. BY:

REF: CS/C12 MO 13908 / Kt P3 ⁿ²

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ong chin kiat

of C11

Date/Time: 8.2.19 11.42a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGT 37112

Insured: SP 4 97557

at Workshop m/s Tat Hung Motor

Tel: 64837103

of BLK 10 AMK Ind Park 24 A02-09

Policy No: DMPCSN30097119066

Claim No: SNM19122329302

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. C.2-19

CA / REV / REP. / REV 24 HRS

10.00am 14/1/19

H.O.D. Endorsement:

Date/Time: 6.8.19 11.48 p.m

Person Contacted: Ginn

Vehicle-IN/OUT

Date/Time	Action/Instruction (✓) Estimate:
	SGT 37112 - C3/A1614011261/KE63W2 DOA - 11/02/2014
	SP4 97557 - 1

REF: C11

ASSIGNMENT

From:

Date:

14.8.2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGT 3711Z

at Workshop m/s TAT Hung motor

of BIK 10 MKK Ind Park 24 # 02-09

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

10.000.000.000 morning owner making

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days Res.: Yes or No

Lum Sum:

20

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

4/22

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SGT 3711Z

Yr Regn:

04 / 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

707 Altis

c.c

1598

Colour:

M. Green

N/C: Insured / Std / NI / NA

Sp. Reading

187416

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR0538EC107141859

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Maxxis 175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

4

mm

L/Bal.

9

mm

L/Bal.

4

mm

D.O.A.

6 18 119

D.O.I.

1418119

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/8

L1 Lm @ 2750l email

(Red: 2259.40; 45%)

RECEIVED 20 SEP 2019

Date/Time, File Pass to?



: Preli. Report

2019 Typist



: Final Report

Date/Time, File Return to?

2)

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Format:

TP

Lump sum / I.B.I. (\$) 2750/-

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Aug 2019		08 Aug 2019 11:42 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:		LIM PUAY GEK @ KOH POH CHOO, ID: S0112518D							
Main Claimant:		SODEXO KIM YEW PTE.LTD., Co. Reg. No.: 199606507M							
Vehicle Reg. No.:		SGT3711Z	Date of Loss:	06/08/2019 08:00 - :59					
Claim Type:		TP / SNM19D203693C02	Policy/Cover Note No.:	DMPCSN30097119066					
Vehicle Reg. No. (Insured):		SFY9755T	Policy No. (Claimant):	2100363881					
		Excess:	S\$0.00						
Repairer:		Tat Heng Motor Works (HQ) Blk 10 Ang Mo Kio Ind Park 2A, #02-09 AMK Autopoint, 568047 Ang Mo Kio - Tel: 64837103							
Handling Insurer:		China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]							
Claimant's Insurer:		AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000							
Adjuster:		LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/08/2019]							
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAuto)

From: georgina mei kuan <gina_tatheng@yahoo.com.sg>
Sent: Thursday, 19 September 2019 6:06 PM
To: Denise Tay (LKKAuto)
Subject: Re: finalization for SGT 3711Z / DOA: 6/8/2019 / CHINA TAIPING
Attachments: img-190919180247.pdf

Dear Denise

We acknowledged and confirmed your offer as per attached.
Thank you.

Your Sincerely,

Georgina Soong

Tat Heng Motor Works
10 Ang Mo Kio Industrial Park 2A
#02-09 AMK Autopoint, Singapore 568047
t: 6483 7103
m: 9113 5112

On Monday, 16 September 2019, 06:57:33 pm GMT+8, Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

Dear Sir/Madam,

Please check and confirm lump sum \$2750, 5days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/08/2019 11:43
Date Of Accident	06/08/2019 08:20
Exact Location Of Accident	TAGORE DRIVE TO TAGORE IND. AVE
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SGT3711Z
Insured/Policyholder	
Name Of Registered Owner	SODEXO KIM YEW PTE.LTD.
Co Reg No	199606507M
Email Address	YE.LYE.SKY@SODEXO.COM
Mobile Phone No	
Alternative Phone No	OFFICE-97770563
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	2100363881
Cover Note Number	
Driver	
Name of Driver	LYE YEW EAN
NRIC No	S0223818G
Date Of Birth	05/11/1951
Occupation	INDOOR
Date Of Driving Pass	28/11/1987
Driving Experience	31 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97770563
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 638 CHOA CHU KANG ST. 64 #11-37
Postcode	680638
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO REPORT ATTACHED


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFY9755T
Vehicle Make/Model/Colour	NISSAN
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	IGGY
NRIC/Passport Number	
Contact Number	98762021
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

At 8:30am on 6-Feb-19, I was driving in from Upper Thomson Road to Tagore Drive and at the junction of Tagore Drive and Tagore Industrial Ave when I stopped to allow the on-coming vehicle to drive pass me before I turned to Tagore Industrial Ave. The vehicle behind me suddenly bang into the back of my vehicle. The driver of the vehicle no. SFY975ST (Nissan Latte) admitted his mistake and agreed to pay for the repair. The name of the driver (SFY975ST) is Wu Zhuming,

DECLARATION

I/We declare the foregoing particulars are true in every respect.



6/8/19 L.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TAT HENG MOTOR WORKS PTE LTD

BLK 10, ANG MO KIO IND PK 2A

02-09 AMK AUTOPOINT

SINGAPORE 568047

TEL : 6483 7103 FAX : 6481 7732

Not Authorized

Call @ 2750h

Respray After Paint

THIRD PARTY CLAIM

VEHICLE NO : SGT3711Z

MODEL : TOYOTA ALTIS - 1.6 CVT (A)

CHASSIS : MR053ZEC107141859

Kennerth (LKK)

5 days

96910663

Kennerth.Kanjer@lkkauto.com

No	Description	Qty	U/Price	Total Price
1	Bootlid	1	833.00	<i>Bu</i> 833.00
2	Bootlid lock	1	89.00	<i>n</i> 89.00
3	Bootlid weatherstrip	1	155.00	<i>sn</i> 155.00
4	Rear bumper	1	496.50	<i>Bu</i> 496.50
5	Rear bumper bracket	2	126.00	<i>R</i> 252.00
6	Rear end panel	1	778.00	<i>Bu</i> 778.00
7	Rear end panel top garnish	1	149.00	<i>sn</i> 149.00
8	Spare tyre panel	1	545.00	<i>n</i> 545.00
9	Spare tyre side panel	2	59.00	<i>n</i> 118.00
10	Spare tyre board	1	72.00	<i>sn</i> 72.00
11	Taillamp LH	1	181.00	181.00
12	Taillamp base panel LH	1	96.00	<i>Bu</i> 96.00
				3,764.50
				Less 25% (941.10)
				2,823.40
				<i>37</i>
Nett Items				
13	Rear fender inner liner clip	1	56.00	<i>sn</i> 56.00
14	Rear number plate	1	45.00	<i>sn</i> 45.00
15	Rear bumper clip	1	35.00	<i>n</i> 35.00
16	Reverse sensor	1	350.00	350.00
Labour and Miscellaneous				
17	To check rear wiring for proper function.			100.00
18	To remove & replace reverse sensor.			100.00
19	To replace, repair, straighten & re-align all damaged parts.			700.00
20	To spray paint on all affected areas.			800.00
				5,009.40

LKK Auto Consultants hereby notify the Repairer of the following:

- To respray before/after spray painting
- To display damaged parts during inventory
- To provide parts and labour for repair
- To provide parts and labour on 'as required' basis
- To provide parts and labour on 'as required' basis
- To provide parts and labour on 'as required' basis
- To provide parts and labour on 'as required' basis

Acknowledged by Repairer
Signature:
Date:

Shan

2005n

200

500

600

650

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19013908/KTF3N2

Date: 23/09/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30097119066	
Claimant Vehicle No :	SGT3711Z	Insured Vehicle No :	SFY9755T	
Date of Loss:	06/08/2019	Nature of Claim:	TP	Claim No: SNM19D203693C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT3711Z	Engine No:	3ZZ4632577
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CVT (A)	Chassis No:	MR053ZEC107141859
Reg. Date:	10/04/2007 (Man. Year: 2006)	Odometer:	187416 km
Colour:	Metallic Green		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Maxxis 9 mm	Rear Left Side:	Yokohama 4 mm
Front Right Side:	Maxxis 9 mm	Rear Right Side:	Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,309.37	2,135.12	1,174.25	35.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,700.00	1,320.00	380.00	22.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,009.37	3,455.12	1,554.25	31.03
Approved Total (Overridden) (\$\$)		2,750.00		
Nett Amount (\$\$)	5,009.37	2,750.00	2,259.37	45.10

INSPECTION

Date of Assignment:	08/08/2019	
Date Inspected:	14/08/2019	Inspected At:
		Tat Heng Motor Works (HQ)
		Blk 10 Ang Mo Kio Ind Park 2A, #02-09
		AMK Autopoint
		Singapore 568047

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2019)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT3711Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Buckled	833.00 FL	*833.00 FL
2	1		*BOOTLID LOCK	Repair	89.00 FL	*- FL
3	1		*BOOTLID WEATHERSTRIP	Serviceable	155.00 FL	*- FL
4	1		*REAR BUMPER	Buckled	496.50 FL	*496.50 FL
5	2		*REAR BUMPER BRACKET	Repair	252.00 FL	*- FL
6	1		*REAR END PANEL	Bent	778.00 FL	*778.00 FL
7	1		*REAR END PANEL TOP GARNISH	Dented	149.00 FL	*149.00 FL
8	1		*SPARE TYRE PANEL	Repair	545.00 FL	*- FL
9	2		*SPARE TYRE SIDE PANEL	Repair	118.00 FL	*- FL
10	1		*SPARE TYRE BOARD	Serviceable	72.00 FL	*- FL
11	1		*TAILLAMP LH	Mtg Distorted	181.00 FL	*181.00 FL
12	1		*TAILLAMP BASE PANEL LH	Bent	96.00 FL	*96.00 FL
13	1		*REAR FENDER INNER LINER CLIP	Not Necessary	56.00 FS	*- FS
14	1		*REAR NUMBER PLATE	Serviceable	45.00 FS	*- FS
15	1		*REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
16	1		*REVERSE SENSOR	Shorted	350.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,250.50	2,768.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	941.13	633.38
Total Parts (\$\$)	3,309.37	2,135.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK REAR WIRING FOR PROPER FUNCTION	New	100.00	20.00
2	TO REMOVE & REPLACE REVERSE SENSOR	New	100.00	50.00
3	TO REPLACE,REPAIR,STRAIGHTEN & RE-ALIGN ALL DAMAGED PARTS	New	700.00	600.00
4	TO SPRAY PAINT ON ALL AFFECTED AREAS	New	800.00	650.00
Gross Labour Cost (S\$)			1,700.00	1,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >