

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

7-Aug-19

ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SJL 9013 L

1 pc	Front bumper	- <i>one</i>	\$	452.00
1 pc	Front bumper reinforcement	- <i>But</i>	\$	279.00
1 pc	Front bumper sponge	- <i>one</i>	\$	124.00
1 pc	Front bumper n/s side bracket	- <i>one</i>	\$	20.50
1 pc	Front bumper n/s fog lamp	- <i>one</i>	\$	150.00
1 pc	Front bumper centre grille	- <i>one</i>	\$	167.50
1 pc	Front bumper lower lip	- <i>one</i>	\$	750
1 pc	n/s headlamp	- <i>one</i>	\$	456.60
1 pc	Support panel	- <i>one</i>	\$	791.30
1 pc	Bonnet	- <i>Painted</i>	\$	992.00
2 pcs	Bonnet hinge	x <i>repair</i>	\$	128.00
1 pc	Bonnet grille	x <i>one</i>	\$	366.00
1 pc	Front n/s fender	- <i>Painted</i>	\$	477.60
1 pc	Front n/s fender inner shield	- <i>one</i>	\$	47.50
1 pc	Front n/s wheel housing	- <i>Painted</i>	\$	464
1 pc	Front n/s wheel cover	- <i>one</i>	\$	104.00
1 pc	Front n/s tyre	x <i>one</i>	\$	
1 pc	Front n/s lower arm	x <i>one</i>	\$	297.00
1 pc	Front n/s shock absorber	x <i>one</i>	\$	349.60
1 pc	Front n/s wheel hup	x <i>one</i>	\$	192.80
1 pc	Front n/s knuckle arm	x <i>one</i>	\$	376.40
1 pc	Front n/s bearing	x <i>one</i>	\$	
1 pc	Front n/s door	x <i>repair</i>	\$	1,258.00
			\$	2,577.80
		Less 20%	\$	746.70
			\$	2,240.10
S/NETT				
1 set	Front bumper clips	- <i>one</i>	\$	35.00
1 set	Front fender clips	- <i>one</i>	\$	28.00
1 pc	Battery	- <i>one</i>	\$	150.00

AC

7-Aug-19

ESTIMATE REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SJL 9013 L

Towing Fee	\$	50.00	/
Sundry	\$	50.00	20
To check headlamp wiring	\$	40.00	20
To top up air con	\$	120.00	80
To check wheel alignment	\$	80.00	60
To lift engine to facilitate repair on the front n/s wheel housing	\$	450.00	150
To dismantle dashboard to facilitate repair on the front n/s wheel housing	\$	450.00	x 47
To labour charge for dismantle and renew the accident damaged parts. To heat/weld and cut off the front n/s wheel house. Including knock-out, straighten, repair, reshape and adjust of the front n/s chassis member	\$	1,800.00	1000
To putty and spray painting on the Front bumper, bonnet, front n/s fender, front n/s fender wheel house, front n/s door, front n/s chassis member	\$	1,500.00	1080
To apply rustproofing on the repaired and replaced panels.	\$	250.00	50
	\$	<u>7,243.10</u>	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kahin 10/11/19
7/8/19 1705 hrs.
5 Pags
V/S
After Rep't photo

Warranty

• For use only on vehicles with a valid warranty survey

• Subject to the terms and conditions of the warranty and is subject to the terms and conditions of the insurance company

Acknowledged by Repairer

Signature:

Date:

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

27-Aug-19

SUPPLEMENTARY REPAIR BILL FOR HYUNDAI AVANTE REGN NO: SJL 9013 L

1 pc	Bonnet lock	- Band	\$	49.30
1 pc	Aircon condensor	- Band	\$	847.60
1 pc	Radiator Assy	- Band	\$	568.00
1 pc	Air duct	- or	\$	82.70
1 pc	Blower Assy	- or	\$	419.30
1 pc	Front n/s fender insulator	- for	\$	50.00
			\$	2,016.90
			Less 20%	\$ 403.38
			\$	1,613.52

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.



28/8/19
about 1/5 of 6750 / 7/20

