



FALCON-AIR

AXA INSURANCE SINGAPORE PTE LTD
NO. 8 SHENTON WAY,
#24-01 AXA TOWER, 068811
SINGAPORE

Attention : Motor Claim Department

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-E
GST REG. NO.: 19-9501140-E

Cecilia

Estimate : ES003510

Date : 08/08/2019
Vehicle Num : SCP810J
Make/Model : HONDA INSIGHT-2012
Chassis/Eng# : JHMZE2850CS203886
Accident Date : 07/08/2019
Claim No. :
Reference : TP NTUC VS AXA
Policy No. :

S/N Quantity Particular Unit Price Amount S\$

1.	1	LIST ITEMS : REAR BUMPER TOP		681.20	<i>do</i>
2.	1	REAR BUMPER LOWER		399.80	<i>ant</i>
3.	1	REAR BUMPER SIDE RETAINER RH		30.10	<i>no X</i>
List Total S\$:				1,111.10	
20.00% Discount S\$:				222.22	
				888.88	

1.	1	SPECIAL NETT ITEMS : REVERSE SENSOR		200.00	<i>nw</i>
Special Nett Total S\$:				200.00	
LABOUR :					
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				100.00	<i>30</i>
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				600.00	<i>400</i>
TO REPAIR REAR END PANEL, INCLUDES KNOCKING & REPLACEMENT OF PARTS				450.00	<i>300</i>
Labour Total S\$:				1,150.00	

SingDollars : Two Thousand Two Hundred Thirty-Eight & Cents Eighty-Eight Only

E. & O.E.

Total S\$: 2,238.88



for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-11

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Taufik 97495719
WP
9/9/19 @ 230pm
Repair after repair
45 to %
No 2nd hand part.
3 days
Taufik Intertek

Before After
** End panel take photo*

AXA INSURANCE SINGAPORE PTE LTD
 NO. 8 SHENTON WAY,
 #24-01 AXA TOWER, 068811
 SINGAPORE

Attention : Motor Claim Department

Estimate : ES003510

Date : 02/09/2019
 Vehicle Num. : SCP810J
 Make/Model : HONDA INSIGHT-2012
 Chassis/Eng# : JHMZE2850CS203886
 Accident Date : 07/08/2019
 Claim No. : *
 Reference : TP NTUC VS AXA
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BUMPER TOP		681.20
2.	1	REAR BUMPER LOWER		399.80
3.	1	REAR BUMPER SIDE-RETAINER-RH X		X
List TotalS\$:				1,081.00
20.00% Discount S\$:				216.20
				<hr/>
				864.80
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR		200.00
Special Nett Total S\$:				<hr/>
				200.00
LABOUR :				
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING				30.00
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER				400.00
TO REPAIR REAR END PANEL, INCLUDES KNOCKING & REPLACEMENT OF PARTS				300.00
Labour Total S\$:				<hr/>
				730.00

SingDollars : One Thousand Seven Hundred Ninety-Four & Cents Eighty Only

E. & O.E.

Total S\$: 1,794.80

for FALCON AIR AUTO SERVICES PTE LTD

L/S less 10% - 179.48
 1615.32

L/S 1600.00

3 DAYS