

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3085A

DATE 8/8/2019 16:06

MAKE :

MODEL : MERCEDES

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt — cm			\$ 1,890.50
	Radiator Grille (E6) — 09			\$ 1,220.00
	Radiator Grille Star Logo x 1			\$ 170.00
	Radiator Grille Adjuster Bracket x 5			\$ 685.70
	Bonnet Assy — Rmkk			\$ 2,850.60
	Bonnet Mercedes Star Logo — 11			\$ 112.00
	Bonnet Stopper Spring (LH/RH) x 5	\$	385.00	\$ 770.00
	Bonnet Lock Sensor (LH/RH) x 5	\$	285.50	\$ 571.00
	Bonnet Centre Lock x 5			\$ 95.00
	Bonnet Lock, Top x 5			\$ 94.00
	Bonnet Lock Lower (2-pcs) x 5	\$	92.00	\$ 184.00
	Bonnet Catch Handle x 5			\$ 29.50
SUB TOTAL				\$ 8,672.30
LESS 10%				\$ 1,734.46
DISCOUNTED TOTAL				\$ 6,937.84
Labour Charge				
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Towing Charges			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Radiator			\$ 90.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
TOTAL LABOUR				\$ 1,790.00
ESTIMATE TOTAL				\$ 8,727.84
				9595.07

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be determined after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants hence notify the Repaired of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer