

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMJ 6814 Y

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. To repair bonnet. To inspect front lock carrier. Re-organise crash management components. Reinstall all parts removed.	\$ 2,800.00	1375 1250
3	To respray front bumper, bonnet and lhs front fender.	\$ 3,000.00	1500 1650
4	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ <u>6,352.00</u>	

Telefax

Material List for Accident Vehicle Regn No. SMJ 6814 Y

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>du ✓</i>	\$	1,830.00
2	FRONT BUMPER FIXING PART <i>?</i>	\$	170.00
3	FRONT BUMPER GUIDE SECTION - LH <i>?</i>	\$	35.00
4	FRONT BUMPER GRILLE - CENTER <i>X</i>	\$	146.00
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER <i>X</i>	\$	488.00
6	FRONT BUMPER CLOSING ELEMENT - LH <i>X</i>	\$	270.00
7	FRONT BUMPER COVER TRIM - LH <i>X</i>	\$	148.00
8	FRONT WHEEL HOUSING LINER ADAPTER - LH <i>du ✓</i>	\$	34.00
9	RADIATOR GRILLE <i>du ✓</i>	\$	1,301.00
10	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	\$	174.00
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>du ✓</i>	\$	171.00
12	FRONT BUMPER IMPACT BAR <i>?</i>	\$	660.00
13	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	\$	172.00
14	IMPACT BEAM COVER <i>?</i>	\$	111.00
15	AIR CON STICKER <i>X</i>	NEC \$	7.00
16	CAUTION STICKER <i>X</i>	NEC \$	13.00
17	FRONT FENDER - LH <i>du ✓</i>	\$	778.00
18	POP RIVET <i>du ✓</i>	NEC \$	15.00
19	FENDER ATTACHMENT PARTS <i>?</i>	\$	65.00
20	FENDER BRACKET - LH <i>du ✓</i>	\$	35.00
SUB- TOTAL SPARE PARTS		\$	6,623.00

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Telefax

Material List for Accident Vehicle Regn No.SMJ 6814 Y

S/N	Parts Description	<u>Damage Parts & Prices</u>	
		S/NETT	REMARKS
21	FENDER SUPPORT ?	\$ 88.00	
22	WHEEL HOUSING LINER SEAL STRIP - LH <i>see</i>	\$ 31.00	
23	WHEEL HOUSING LINER - LH <i>see</i>	\$ 158.00	
24	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 81.00	
25	LED HEADLIGHT - LH <i>Bo</i>	\$ 5,029.00	
26	MAIN LIGHT POWER MODULE ?	\$ 693.00	
27	LIGHT CONTROL MODULE ?	\$ 508.00	
28	LED UNIT - LH ?	\$ 666.00	
29	HEADLIGHT HOSE ?	\$ 36.00	
30	LIFT CYLINDER - LH ?	\$ 128.00	
31	LIFT CYLINDER HOSE ?	\$ 61.00	
32	LIFT CYLINDER PUMP ?	\$ 147.00	
33	WINDSCREEN WASHER PUMP ?	\$ 118.00	
34	WINDSCREEN WATER RESERVOIR <i>X</i>	\$ 189.00	
35	STRAINER ?	\$ 19.00	
36	RESERVOIR CAP <i>X</i>	\$ 19.00	
37	RADIATOR AIR GUIDE - LH ?	\$ 22.00	
38	FRONT NO. PLATE <i>bt</i>	S/N \$ 40.00	
39	SUNDRIES ?	\$ 300.00	
TOTAL SPARE PARTS		: \$ 14,956.00	
TOTAL LABOUR CHARGES		: \$ 6,352.00	
GRAND TOTAL		: <u>\$ 21,308.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Rasu - Hp 9001ms 68

Surveyed Date

: 13/02/19 @ 1000

Authorised Date

:

Excess Cost

:

6 days

Liability

:

P/P

Remarks

:

EXCESS: TBC

REVERT

Ready before paid

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant