



S THREE AUTOMOTIVE RECOVERY PTE LTD

TO :
 ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. :

ESTIMATE REPORT 1st QUOTATION

JOB NO : _____

OWNER'S PARTICULAR

NAME : **SELVA BRYAN RAYNAM**
 ADDRESS :

CONTACT :

LICENSE NO. : **SBR8268Z TRANS.**
 MAKE / MODEL : **LEXUS CT200**
 OWNER'S INSURER **CHINA INSURANCE**
 JOB-CODE : **OD** S/A : **JOEY**

CHASSIS NO : **JTHKD5BHX02018831**
 ENGINE NO :

ACCIDENT DATE : **2-Aug-19**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC +15%	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	1.00	420.00	15.00	483.00	Y	_____
2 FRONT BUMPER TOP INNER RUBBER SEAL	1.00	50.00	15.00	57.50	Y	_____
3 FRONT BUMPER INNER GARNISH	1.00	190.00	15.00	218.50	Y	_____
4 FRONT BUMPER LOWER GRILLE	1.00	145.00	15.00	166.75	Y	_____
5 FRONT BUMPER FOGLAMP LH	1.00	140.00	15.00	161.00	Y	_____
6 FRONT BUMPER FOGLAMP COVER LH	1.00	50.00	15.00	57.50	Y	_____
7 FRONT BUMPER FOGLAMP RH	1.00	180.00	15.00	207.00	Y	_____
8 FRONT BUMPER FOGLAMP COVER RH	1.00	50.00	15.00	57.50	Y	_____
9 FRONT BUMPER SPONGE	1.00	110.00	15.00	126.50	Y	_____
10 FRONT BUMPER RETAINER RH	1.00	35.00	15.00	40.25	Y	_____
11 FRONT BUMPER RETAINER LH	1.00	35.00	15.00	40.25	Y	_____
12 FRONT BUMPER LOWER COVER	1.00	35.00	15.00	40.25	Y	_____
13 FRONT BUMPER REINFORCEMENT	1.00	290.00	15.00	333.50	Y	_____
14 FRONT BUMPER BRACKET RH	1.00	60.00	15.00	69.00	Y	_____
15 FRONT BUMPER BRACKET LH	1.00	60.00	15.00	69.00	Y	_____
16 FRONT NUMBER PLATE GARNISH	1.00	115.00	15.00	132.25	Y	_____
17 FRONT FENDER INNER GARNISH LH	1.00	120.00	15.00	138.00	Y	_____
18 FRONT FENDER INNER GARNISH RH	1.00	120.00	15.00	138.00	Y	_____
19 FRONT FENDER SIDE RUBBER LH	1.00	50.00	15.00	57.50	Y	_____
20 FRONT FENDER SIDE RUBBER RH	1.00	50.00	15.00	57.50	Y	_____
21 FRONT HEADLAMP HID LH	1.00	1200.00	15.00	1380.00	Y	_____

22	FRONT HEADLAMP HID RH	1.00	1200.00	15.00	1380.00	Y	_____
23	FRONT HEADLAMP NOZZLE CHROME COVER RH	1.00	280.00	15.00	322.00	Y	_____
24	FRONT HEADLAMP NOZZLE CHROME COVER LH	1.00	280.00	15.00	322.00	Y	_____
25	RADIATOR GRILLE	1.00	330.00	15.00	379.50	Y	_____
26	RADIATOR GRILLE CHROME	1.00	120.00	15.00	138.00	Y	_____
27	RADIATOR GRILLE LOGO	1.00	185.00	15.00	212.75	Y	_____
28	HORN - HIGH	1.00	75.00	15.00	86.25	Y	_____
29	HORN - LOWER	1.00	75.00	15.00	86.25	Y	_____
30	BRACE PANEL	1.00	105.00	15.00	120.75	Y	_____
31	BONNET	1.00	790.00	15.00	908.50	Y	_____
32	BONNET LOCK	1.00	105.00	15.00	120.75	Y	_____
33	BONNET HINGE LH	1.00	50.00	15.00	57.50	Y	_____
34	BONNET HINGE RH	1.00	50.00	15.00	57.50	Y	_____
35	BONNET SEAL	1.00	25.00	15.00	28.75	Y	_____
36	BONNET STOPPER 2PCS	2.00	20.00	15.00	23.00	Y	_____
37	WIPER SIDE COVER	1.00	95.00	15.00	109.25	Y	_____
38	ENGINE LOWER COVER	1.00	200.00	15.00	230.00	Y	_____
39	RADIATOR ASSY	1.00	680.00	15.00	782.00	Y	_____
40	RADIATOR FAN COWLING	1.00	120.00	15.00	138.00	Y	_____
41	RADIATOR FAN MOTOR	1.00	190.00	15.00	218.50	Y	_____
42	RADIATOR FAN BLADE	1.00	110.00	15.00	126.50	Y	_____
43	RADIATOR SIDE AIR GUARD LH	1.00	60.00	15.00	69.00	Y	_____
44	RADIATOR SIDE AIR GUARD RH	1.00	60.00	15.00	69.00	Y	_____
45	AIRCON FAN BLADE	1.00	120.00	15.00	138.00	Y	_____
46	AIR CON CONDENSOR	1.00	680.00	15.00	782.00	Y	_____
47	AIR CON FAN MOTOR	1.00	190.00	15.00	218.50	Y	_____
48	AIR CON PIPE (CONDENSOR TO COMPRESSOR)	1.00	160.00	15.00	184.00	Y	_____
49	AIR CON PIPE (CONDENSOR TO COILING COIL)	1.00	350.00	15.00	402.50	Y	_____
50	AIRCON CONDENSOR	1.00	690.00	15.00	793.50	Y	_____
51	AIRCON WATER COOLER	1.00	380.00	15.00	437.00	Y	_____
52	AIRCON CONDENSOR COWLING	1.00	180.00	15.00	207.00	Y	_____
53	SUPPORT PANEL ASSY	1.00	700.00	15.00	805.00	Y	_____
TOTAL (PARTS) :			12160.00		13984.00		

SPECIAL NETT ITEM

1	FRONT PARKING SENSOR	1.00	280.00	0.00	280.00	Y	_____
2	FRONT FENDER INNER SHIELD CLIPS LH	1.00	100.00	0.00	100.00	Y	_____
3	FRONT FENDER INNER SHIELD CLIPS RH	1.00	100.00	0.00	100.00	Y	_____
4	FRONT FENDER INNER GARNISH CLIPS (1SET)	1.00	50.00	0.00	50.00	Y	_____
5	FRONT RADIATOR GRILLE CLIPS	1.00	50.00	0.00	50.00	Y	_____
6	FRONT BUMPER CLIPS	1.00	50.00	0.00	50.00	Y	_____
7	FRONT BUMPER INNER GARNISH CLIPS	1.00	50.00	0.00	50.00	Y	_____
8	COOLANT	1.00	80.00	0.00	80.00	Y	_____
9	FRONT ENGINE COVER AND SIDE COVER CLIPES RH	1.00	80.00	0.00	80.00	Y	_____
10	FRONT ENGINE COVER AND SIDE COVER CLIPES LH	1.00	80.00	0.00	80.00	Y	_____

TOTAL (PARTS) : 920.00 920.00

LABOUR

1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	_____
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	_____
3	RESET FRONT PARKING SENSOR SYSTEM	1.00	120.00	0.00	120.00	Y	_____
4	CHECK & REPAIR WIRING SYSTEM	1.00	180.00	0.00	180.00	Y	_____
5	R&R RADIATOR ASSY	1.00	180.00	0.00	180.00	Y	_____
6	CONDUCT FULL COMPUTER ALIGNMENT	1.00	120.00	0.00	120.00	Y	_____
7	R&R AIRCON CONDENSOR & CHARGE UP GAS	1.00	180.00	0.00	180.00	Y	_____
8	RESET & CALIBRATE HEADLAMP SYSTEM	1.00	120.00	0.00	120.00	Y	_____

TOTAL (LABOUR) : 3500.00 3500.00

TOTAL PARTS & LABOUR 16580.00 18404.00

NO. OF DAY : _____

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : ____/____/____

SURVEY BY : _____

CONTACT NO: _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.