

*Hennrich*



*Not Authorized  
1/1/19 & ?  
Returning After Pain*

*Ex @ 7501*

*Fax 62564315*



**S THREE AUTOMOTIVE RECOVERY PTE LTD**

*Hennrich.Hong@lkkauto.com*

TO :  
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO.:

ESTIMATE REPORT 1st QUOTATION

JOB NO.:

OWNER'S PARTICULAR

CONTACT:

NAME : SELVA BRYAN RAYNAM  
ADDRESS :

LICENSE NO. : SBR8268Z TRANS.  
MAKE / MODEL : LEXUS CT200  
OWNER'S INSURER CHINA INSURANCE  
JOB-CODE : OD S/A : JOEY

CHASSIS NO : JTHKD5BHX02018831  
ENGINE NO :

ACCIDENT DATE : 2-Aug-19

CLAIM DETAIL

MATERIALS		QTY	QUO-PRICE	DISC OUNT	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRONT BUMPER	<i>Bu</i>	1.00	991.36	10.00	892.22	Y	<u>✓</u>
2 FRONT BUMPER TOP INNER RUBBER SEAL	<i>M</i>	1.00	78.02	10.00	70.22	Y	<u>✓</u>
3 FRONT BUMPER INNER GARNISH		1.00	312.00	10.00	280.80	Y	<u>?</u>
4 FRONT BUMPER LOWER GRILLE		1.00	278.30	10.00	250.47	Y	<u>?</u>
5 FRONT BUMPER FOGLAMP LH	<i>Sm</i>	1.00	323.70	10.00	291.33	Y	<u>X</u>
6 FRONT BUMPER FOGLAMP COVER LH	<i>Sm</i>	1.00	105.60	10.00	95.04	Y	<u>X</u>
7 FRONT BUMPER FOGLAMP RH	<i>Sm</i>	1.00	323.70	10.00	291.33	Y	<u>X</u>
8 FRONT BUMPER FOGLAMP COVER RH	<i>Sm</i>	1.00	105.60	10.00	95.04	Y	<u>X</u>
9 FRONT BUMPER SPONGE	<i>CM</i>	1.00	182.75	10.00	164.48	Y	<u>✓</u>
10 FRONT BUMPER RETAINER RH	<i>Sm</i>	1.00	60.25	10.00	54.23	Y	<u>X</u>
11 FRONT BUMPER RETAINER LH	<i>Sm</i>	1.00	60.25	10.00	54.23	Y	<u>X</u>
12 FRONT BUMPER LOWER COVER	<i>Sm</i>	1.00	186.20	10.00	167.58	Y	<u>X</u>
13 FRONT BUMPER REINFORCEMENT	<i>R</i>	1.00	692.75	10.00	623.48	Y	<u>✓</u>
14 FRONT BUMPER BRACKET RH	<i>K</i>	1.00	343.60	10.00	309.24	Y	<u>X</u>
15 FRONT BUMPER BRACKET LH		1.00	343.60	10.00	309.24	Y	<u>?</u>
16 FRONT NUMBER PLATE GARNISH	<i>CM</i>	1.00	155.70	10.00	140.13	Y	<u>✓</u>
17 FRONT FENDER INNER GARNISH LH	<i>Sm</i>	1.00	221.60	10.00	199.44	Y	<u>X</u>
18 FRONT FENDER INNER GARNISH RH	<i>Sm</i>	1.00	221.60	10.00	199.44	Y	<u>X</u>
19 FRONT FENDER SIDE RUBBER LH	<i>Sm</i>	1.00	71.60	10.00	64.44	Y	<u>X</u>
20 FRONT FENDER SIDE RUBBER RH	<i>Sm</i>	1.00	71.60	10.00	64.44	Y	<u>X</u>
21 FRONT HEADLAMP HID LH		1.00	2447.80	10.00	2203.02	Y	<u>?</u>

22	FRONT HEADLAMP HID RH	<i>Mjcm</i>	1.00	2447.80	10.00	2203.02	Y	<u>✓</u>
23	FRONT HEADLAMP NOZZLE CHROME COVER RH	<i>Sm</i>	1.00	521.70	10.00	469.53	Y	<u>X</u>
24	FRONT HEADLAMP NOZZLE CHROME COVER LH	<i>Sm</i>	1.00	521.70	10.00	469.53	Y	<u>X</u>
25	RADIATOR GRILLE	<i>CM</i>	1.00	621.70	10.00	559.53	Y	<u>✓</u>
26	RADIATOR GRILLE CHROME	<i>CM</i>	1.00	223.80	10.00	201.42	Y	<u>✓</u>
27	RADIATOR GRILLE LOGO	<i>Sm</i>	1.00	303.90	10.00	273.51	Y	<u>✓</u>
28	HORN - HIGH		1.00	120.70	10.00	108.63	Y	<u>?</u>
29	HORN - LOWER	<i>Sm</i>	1.00	120.70	10.00	108.63	Y	<u>X</u>
30	BRACE PANEL	<i>R</i>	1.00	155.70	10.00	140.13	Y	<u>✓</u>
31	BONNET	<i>R</i>	1.00	1421.80	10.00	1279.62	Y	<u>✓</u>
32	BONNET LOCK	<i>Dix</i>	1.00	143.95	10.00	129.56	Y	<u>✓</u>
33	BONNET HINGE LH	<i>R</i>	1.00	69.70	10.00	62.73	Y	<u>X</u>
34	BONNET HINGE RH	<i>R</i>	1.00	69.70	10.00	62.73	Y	<u>X</u>
35	BONNET SEAL	<i>Sm</i>	1.00	51.70	10.00	46.53	Y	<u>X</u>
36	BONNET STOPPER 2PCS	<i>Sm</i>	2.00	40.00	10.00	36.00	Y	<u>X</u>
37	WIPER SIDE COVER	<i>Sm</i>	1.00	125.00	10.00	112.50	Y	<u>X</u>
38	ENGINE LOWER COVER	<i>Sm</i>	1.00	422.65	10.00	380.39	Y	<u>X</u>
39	RADIATOR ASSY		1.00	1377.80	10.00	1240.02	Y	<u>?</u>
40	RADIATOR FAN COWLING	<i>Sm</i>	1.00	201.60	10.00	181.44	Y	<u>X</u>
41	RADIATOR FAN MOTOR	<i>Sm</i>	1.00	457.60	10.00	411.84	Y	<u>✓</u>
42	RADIATOR FAN BLADE	<i>Sm</i>	1.00	196.30	10.00	176.67	Y	<u>X</u>
43	RADIATOR SIDE AIR GUARD LH		1.00	122.60	10.00	110.34	Y	<u>?</u>
44	RADIATOR SIDE AIR GUARD RH		1.00	122.60	10.00	110.34	Y	<u>?</u>
45	AIRCON FAN BLADE	<i>Sm</i>	1.00	200.95	10.00	180.86	Y	<u>X</u>
46	AIR CON CONDENSOR	<i>Sm</i>	1.00	1671.90	10.00	1504.71	Y	<u>X</u>
47	AIR CON FAN MOTOR	<i>Sm</i>	1.00	506.90	10.00	456.21	Y	<u>X</u>
48	AIR CON PIPE ( CONDENSOR TO COMPRESSOR )		1.00	411.60	10.00	370.44	Y	<u>?</u>
49	AIR CON PIPE ( CONDENSOR TO COILING COIL )		1.00	661.97	10.00	595.77	Y	<u>?</u>
50	AIRCON CONDENSOR		1.00	1377.65	10.00	1239.89	Y	<u>?</u>
51	AIRCON WATER COOLER		1.00	877.65	10.00	789.89	Y	<u>?</u>
52	AIRCON CONDENSOR COWLING	<i>Sm</i>	1.00	720.50	10.00	648.45	Y	<u>X</u>
53	SUPPORT PANEL ASSY	<i>Buz</i>	1.00	2021.70	10.00	1819.53	Y	<u>✓</u>
TOTAL (PARTS) :				25889.10		23300.19		

SPECIAL NETT ITEM

1	FRONT PARKING SENSOR	<i>sm</i> 1.00	280.00	0.00	280.00	Y	<u>X</u>
2	FRONT FENDER INNER SHIELD CLIPS LH	<i>nn</i> 1.00	100.00	0.00	100.00	Y	<u>X</u>
3	FRONT FENDER INNER SHIELD CLIPS RH	<i>nn</i> 1.00	100.00	0.00	100.00	Y	<u>X</u>
4	FRONT FENDER INNER GARNISH CLIPS (1SET)	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
5	FRONT RADIATOR GRILLE CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>✓</u>
6	FRONT BUMPER CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>✓</u>
7	FRONT BUMPER INNER GARNISH CLIPS	<i>nn</i> 1.00	50.00	0.00	50.00	Y	<u>X</u>
8	COOLANT	<i>nn</i> 1.00	80.00	0.00	80.00	Y	<u>205ml</u>
9	FRONT ENGINE COVER AND SIDE COVER CLIPES RH	1.00	80.00	0.00	80.00	Y	<u>?</u>
10	FRONT ENGINE COVER AND SIDE COVER CLIPES LH	1.00	80.00	0.00	80.00	Y	<u>?</u>
TOTAL (PARTS):			920.00		920.00		

LABOUR

1	STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	<u>600l</u>
2	SPRAY PAINTING ON ACCIDENT AREA	1.00	1400.00	0.00	1400.00	Y	<u>720l</u>
3	RESET FRONT PARKING SENSOR SYSTEM	1.00	120.00	0.00	120.00	Y	<u>50l</u>
4	CHECK & REPAIR WIRING SYSTEM	1.00	180.00	0.00	180.00	Y	<u>20l</u>
5	R&R RADIATOR ASSY	1.00	180.00	0.00	180.00	Y	<u>50l</u>
6	CONDUCT FULL COMPUTER ALIGNMENT	1.00 <i>nn</i>	120.00	0.00	120.00	Y	<u>X</u>
7	R&R AIRCON CONDENSOR & CHARGE UP GAS	1.00	180.00	0.00	180.00	Y	<u>100l</u>
8	RESET & CALIBRATE HEADLAMP SYSTEM	1.00	120.00	0.00	120.00	Y	<u>?</u>
TOTAL (LABOUR):			3500.00		3500.00		
TOTAL PARTS & LABOUR			30309.10		27720.19		

NO. OF DAY : 05

PART-BY-PART OR LUMP-SUM : \$ \$ \_\_\_\_\_

DATE OF SURVEY : 13/ 8/ 19

SURVEY BY : Hansen

CONTACT NO: 96910663

FAX NO : 62564315

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: