

FORM 100

ASS. REC. BY:

Signature: RASHI

REF: cs/u0119013977/Rsd321

Special Instructions:

ASSIGNMENT (Office)

From (Person): Jerry Jew

of UOI

Date/Time: 13/8/19 @ 10:25am

Estimated Cost:

Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLC 1453L

Insured:

at Workshop m/s

Tan chong Motor

Tel:

67038916

of

913 Bukit Timah Road

Policy No:

Claim No:

M12D11231408

Sum Insured:

Excess:

\$750.00

Make of Veh:

(Client's Record)

D.O.A. 08/10/08/2019

CA / ☒ REV

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:47am @ 13/8/19

Person Contacted:

Zuhri

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

Ishtiyak ✓

SLC 1453L - X

13/8/19

@ 4:04 pm revised IA & requested authority repair to Jerry via email.

13/8/19

@ 11:19 pm authority approved by Jerry via email.

13/8/19

@ 12:51 pm inform C/A to Zuhri via email.

ASS. REC. 1/1/19

REF: CS100119013977/RISd3

114F

ASSIGNMENT

From: _____ Date: _____
 Estimator/Out: _____
 () TP / WS / TP RES / QD RES / EVA / INV / MY

To inspect Vehicle No: **SLC 1453L**
 at Workshop no: **TAN CHONG**
 of **913, BURK 71MXX1 R7**
 Insured **W01**

Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **750**

(Client's Record)

Make of Velt: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Marked Value: **58K**

ID/C Accident Rpt. Consistent? : Yes or No

GLN / PR Seen: Consistent? : Yes or No

Ert. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / (REV) REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SLC 1453L** Yr Reg: **2016 MAY**
 Type: () MCar / MLCycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **NISSAN SYLPHY 1.6 car** **1558**

Colour: **RED** A/C: Insured / Std / NI / NA

Sp. Reading: **.68811** Tilt/Incl: Insured / Std / NI / NA

Eng/No: _____

C/No: **MNT BBAB1720027213**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: () Morder / Jammed / Leaked / Burnt or

Brake: () Morder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F: **195/60R16**

R: _____

BS: () DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: **6** mm

L/Bal: **6** mm

D.O.A. **08/08/19** D.O.I. **13/08/19**

Survey held at: **TAN CHONG**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

013 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
21/10/19	Cont. and P/P \$ 7,628.88 (\$ 3,346.82 Red - 31%) @ 7 days with Resu!

RECEIVED 21 OCT 2019

21/10/2019

Date/Time, File Pass to:

21/10/19 Typ. 4

Date/Time, File Return to:

21

Report Format:

Lump Sum / L.B.P. \$ **7,628.88**

☐ : Prelim. Report
☒ : Final Report

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Acid Fee: ☐ Site Insp (5)
☐ Interview (5)
☐ Tech. Insp (5)
☐ Weekend (5)

Survey Fee

Transportation

Taxi Fee

Other

22/10/19

22/10/19

22/10/19

250 + 25

60

80

81

496

ASS. REF. Paul

REF

147

ASSIGNMENT

Team: _____ Date: _____
Estimated Cost: _____
☒ O/T / TP / WS / TP RES / OO RES / EVA / INV / MV

To Inspect Vehicle No: SLC 1453L
at Workshop/s: TAN CHONG
of: 913, BURCH TIMOTHY for
Insured: UOI

Policy No:

Chassis No:

Sum Insured: _____ Excess: 750

(Client's Record)

Make of Veh:

(Policy Condition)

Remarks: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: 58K

ID/C Accident Report: _____ Consistent? Yes or No

GLN / PR Seen: _____ Consistent? Yes or No

Est. Repairs: _____ days Res: Yes or No

Limit Sum: _____ % 3 Val: Yes or No

CA / ☒ REV REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC 1453L Yr Reg: 2016 MAY
Type: ☒ M Car / M Cycle / Bus / Van / Lorry / Taxi / Pilote Motor /
Truck / Trailer or

Make: NISSAN SYLPHY 1.6 car Cr: 1558

Colour: RED A/C: Insured / Std / N / NA

Sp Reading: 68811 T/Taxi: Insured / Std / N / NA

Eng No:

C/Nr: MNT BBAB1720027213

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Mod: Nil / ☒ STD Air / STD Air / or

Tyre Size: F: 195/60R16
R: _____

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIG / QHTSU / PIRI / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal: <u>6</u> mm	R/Bal: <u>6</u> mm
L/Bal: <u>6</u> mm	L/Bal: <u>6</u> mm

D.O.A. 08/08/19 P.O.I. 13/08/19

Survey held at: TAN CHONG

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S FRT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: _____ Action / Instruction: _____

Order/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

Resurvey No. of Trip:

0. _____

☐ : Final Report

Date/Time, File Return to?

Add Fee: ☐ Site Insp. (\$)

☐ Interview (\$)

☐ Tech. Insp. (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

1. \$ + 100.00

1. 100.00

1. 100.00

Report Format:

Limit Sum / L.B.L. (\$)

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	114F
Vehicle Details	
Vehicle No.:	SLC1453L
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Aug 2019
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HR16989400B
Chassis No.:	MNTBBAB17Z0027213
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,807.00
Original Registration Date:	03 May 2016
First Registration Date:	03 May 2016
Transfer Count:	0
Actual ARF Paid:	\$16,807.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 May 2026
PARF Rebate Amount:	\$12,605.00
Intended COE Rebate Details	
COE Expiry Date:	02 May 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$31,782.00
Total Rebate Amount:	\$44,387.00

The information contained herein is correct as at 13 Aug 2019

OK

Shirley Hiew (LKK Auto)

From: Muhammad Zuhri <zuhri@tanchong.com>
Sent: Monday, 21 October 2019 8:50 am
To: Rasul (LKKAuto); Ng Li Ting
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SLC1453L OD (UOI) DOA - 08/08/2019

Dear Rasul ,

Noted .

Aside to Li Ting ,

Fyi.

Best Regards,
ZUHRI
Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472
Email: zuhri@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: 18 October 2019 18:05
To: Muhammad Zuhri <zuhri@tanchong.com>
Cc: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Subject: RE: SLC1453L OD (UOI) DOA - 08/08/2019

Hi Zuhri,

Finalised amount confirmed as per your attachment

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 Public Consultants Pte Ltd *Save the Earth. Print only when necessary.*

From: Muhammad Zuhri [<mailto:zuhri@tanchong.com>]
Sent: Friday, 18 October, 2019 8:55 AM
To: Rasul (LKKAuto)

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 13 August 2019 10:25 AM
To: Muhammad Zuhri; assignments; SUR
Subject: RE: Survey SLC1453L OD Recovery Claim
Attachments: EST.zip

Dear Zuhri,

We will arrange LKK to survey the vehicle.

Dear Shiau Chan,

Please arrange to survey the vehicle at Tan Chong Motor Sales Pte Ltd.
Excess: S\$ 750.00

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Muhammad Zuhri [mailto:zuhri@tanchong.com]
Sent: Tuesday, 13 August, 2019 9:58 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Subject: FW: Survey SLC1453L OD Recovery Claim
Importance: High

Dear Jenny ,

Kindly refer the attached file & below email.

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Muhammad Zuhri
Sent: 13 August 2019 09:42
To: 'claims@uoi.com.sg' <claims@uoi.com.sg>

Subject: FW: Survey SLC1453L OD Recovery Claim
Importance: High

Hi,

Kindly assist to arrange survey as follows:
The vehicle in.

Please revert with confirmation.

Best Regards,
ZUHRI
Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472
Email: zuhri@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

From: Muhammad Zuhri
Sent: 10 August 2019 10:11
To: claims@uoi.com.sg
Subject: Survey SLC1453L OD Recovery Claim
Importance: High

Hi,

Kindly assist to arrange survey as follows:
The vehicle in.

Please revert with confirmation.

Best Regards,
M.ZUHRI
Tan Chong Motor Sales Pte Ltd
913 Bukit Timah Road
Singapore 589622
Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472
Email: zuhri@tanchong.com
Website: www.tanchong.com :: www.nissan.com.sg

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 August 2019 1:30 PM
To: 'Muhammad Zuhri'
Cc: SUR
Subject: RE: SLC1453L OD (UOI) DOA - 08/08/2019
Attachments: SUPP.pdf

Dear Zuhri,

Supplementary approved by UOI.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Zuhri [mailto:zuhri@tanchong.com]
Sent: Wednesday, 14 August 2019 8:37 AM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SLC1453L OD (UOI) DOA - 08/08/2019

Hi Shirley ,

Noted .

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: 13 August 2019 17:31
To: Muhammad Zuhri <zuhri@tanchong.com>
Cc: SUR <sur@lkkauto.com>
Subject: SLC1453L OD (UOI) DOA - 08/08/2019

Dear Zuhri,

As instructed by our client , please proceed to repair the insured vehicle SLC 1453L (Excess S750/-).

Shirley Hiew (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Friday, 16 August 2019 10:27 AM
To: Shirley Hiew (LKK Auto)
Cc: assignments; SUR
Subject: RE: Survey SLC1453L OD Recovery Claim

Dear Shirley,

Please authorise the repair up to S\$8,624.90 incl supp.items.
Excess: S\$750.00

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Friday, 16 August, 2019 9:35 AM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey SLC1453L OD Recovery Claim

Dear Jenny,

Enclosed preliminary revised of vehicle SLC 1453L.
Date of survey: 13/08/2019
Number of days : 7 days

Please let us have your supplementary approval please.

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 August 2019 9:35 AM
To: 'LEW JENNY'
Cc: assignments; SUR
Subject: RE: Survey SLC1453L OD Recovery Claim
Attachments: SLC 1453L - Preli Advise 2.pdf

Dear Jenny,

Enclosed preliminary revised of vehicle SLC 1453L.
Date of survey: 13/08/2019
Number of days : 7 days

Please let us have your supplementary approval please.

Kindly provide us the claim no.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: LEW JENNY [mailto:jennylew@uoi.com.sg]
Sent: Tuesday, 13 August 2019 5:19 PM
To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey SLC1453L OD Recovery Claim

Dear Shirley,

Please proceed with the repair authorisation up to S\$8,310.00
Excess: S\$750.00

Enclose the discharge voucher for client due execution.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 13 August 2019 5:31 PM
To: zuhri@tanchong.com
Cc: SUR
Subject: SLC1453L OD (UOI) DOA - 08/08/2019
Attachments: OD Template.zip

Dear Zuhri,

As instructed by our client , please proceed to repair the **insured vehicle SLC 1453L (Excess S750/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shirley Hiew (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Tuesday, 13 August 2019 5:19 PM
To: Shirley Hiew (LKK Auto)
Cc: assignments; SUR
Subject: RE: Survey SLC1453L OD Recovery Claim
Attachments: OD Template.zip

Dear Shirley,

Please proceed with the repair authorisation up to S\$8,310.00
Excess: S\$750.00

Enclose the discharge voucher for client due execution.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #26-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]
Sent: Tuesday, 13 August, 2019 5:04 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey SLC1453L OD Recovery Claim

Dear Jenny,

Enclosed preliminary revised of vehicle SLC 1453L.
Date of survey: 13/08/2019
Number of days : 7 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 13 August 2019 5:04 PM
To: 'LEW JENNY'
Cc: 'assignments'; 'SUR'
Subject: RE: Survey SLC1453L OD Recovery Claim
Attachments: SLC 1453L- Preli Advise.pdf

Dear Jenny,

Enclosed preliminary revised of vehicle SLC 1453L.
Date of survey: 13/08/2019
Number of days : 7 days

We have Not authorise repair.

Kindly let us have your approval please.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Muhammad Zuhri [mailto:zuhri@tanchong.com]
Sent: Tuesday, 13 August 2019 11:16 AM
To: LEW JENNY <jennylew@uoi.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey SLC1453L OD Recovery Claim

Hi Jenny ,

Noted .

Best Regards,

ZUHRI

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

Tel: +65-64694091 :: DID: +65-67038916 :: Fax: +65-64697472

Email: zuhri@tanchong.com

Website: www.tanchong.com :: www.nissan.com.sg

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: 13 August 2019 10:25
To: Muhammad Zuhri <zuhri@tanchong.com>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Survey SLC1453L OD Recovery Claim



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 16 August 2019

Our Ref: CS/UOI19013977/R1sd3

The Motor Claims Department
UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 1453L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/08/2019 at the premises of M/s Tan Chong Motor Sales Pte Ltd and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,975.70</u>	(inclusive supp)
Revised Estimate Amount	: <u>S\$ 7,181.84</u>	(inclusive supp)
"Check" Items Amount	: <u>S\$ 1,443.06</u>	
<u>Total</u>	: <u>S\$ 8,624.90</u>	
Market Value	: <u>S\$ 58,000.00</u>	
LTA Reimbursement Value	: <u>S\$ 44,387.00</u>	
Nett Value	: <u>S\$ 13,613.00</u>	

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair cost economical. Supplementary amount is \$ 314.96.

Repair days: 7 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 13 August 2019

Our Ref: CS/UOI19013977/R1sd3

The Motor Claims Department
UNITED OVERSEAS INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 1453L

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/08/2019 at the premises of M/s Tan Chong Motor Sales Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,660.74</u>
Revised Estimate Amount	: S\$ <u>6,866.88</u>
"Check" Items Amount	: S\$ <u>1,443.06</u>
Total	: S\$ <u>8,310.00</u>
Market Value	: S\$ <u>58,000.00</u>
LTA Reimbursement Value	: S\$ <u>44,387.00</u>
Nett Value	: S\$ <u>13,613.00</u>

Description of Damage:

The vehicle sustained damages at the o/s front portion.



Comments/ Present Status:

Damages Consistent.

Repair cost economical, we have not authorise repair

Repair days: 7 Days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

S/C

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2019 12:07
Date Of Accident	08/08/2019 08:15
Exact Location Of Accident	EXIT OF SILAT ROAD SIKH TEMPLE X JLN BUKIT MERAH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLC1453L
Insured/Policyholder	
Name Of Registered Owner	HARBANS SINGH
NRIC No	S0031114F
Email Address	SANGHAR@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-97483052
Alternative Phone No	OTHERS-97483052

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY-1.6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	UNITED OVERSEAS INSURANCE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DH0M120028651701
Cover Note Number	

Driver

Name of Driver	HARBANS SINGH
NRIC No	S0031114F
Date Of Birth	05/11/1954
Occupation	INDOOR
Date Of Driving Pass	18/11/1974
Driving Experience	44 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97483052
Fax Number	
Contact Number	OTHERS-97483052
EMail Address	SANGHAR@HOTMAIL.COM

Address	654 YISHUN AVE 4 #12-441
Postcode	760654
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER THE ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN9359L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SANDHU BALKAR SINGH
NRIC/Passport Number	G8314456X
Contact Number	83812569
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANVehicle No: SLC 1453 LIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 3/8/19 12:30 hrs

Driver's Signature

(if driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: SLC 1453 L

Accident Location: Exit of Silai Road Sikh Temple x Jln Bukit Merah	
Accident Date: 8 Aug 2019	Time: 8:15 am / pm
- Brief Details Of Accident -	
On 8 Aug 2019 at about 8:15 am, I was driving out of the carport of Silai Road Sikh Temple, Jln Bukit Merah. I noticed a small truck parked on the right side of the road. As I was passing by it, he suddenly turned left and hit into the front right side of my car, causing heavy damage to the right side of my car. Please see photos on the extent of damage. There was only minimal damage to the side of the truck.	
- Other Vehicle Involve Details -	
(B) Veh No: YN 9359 L	Hp: 8381 2569 Pax: / Driver Name: Sandhu Balkar Singh
(C) Veh No: /	Hp: / Pax: / Driver Name: (8314456X)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature
 Date & Time: 8/8/19 12:20 pm

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Certificate of Insurance

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

ORIGINAL

CERTIFICATE NO.	DHOM120028651701	Excess:	\$1500/-OTHERS \$3000/-APPL TO <25 YRS & OR <3YRS EXP \$100/-WINDSCREEN DAMAGE CLAIM \$750/-NAMED DRIVERS - OPTION 2
Type of Cover	COMPREHENSIVE		
Vehicle Number	SLC1453L		
Name of Insured	HARBANS SINGH		
Restricted Driver(s)	NOT APPLICABLE		

Period of Insurance 3 May 2019 to 2 May 2021

Engine# HR16989400B
Chassis# MNTBBAB17Z0027213

Hire Purchase UNITED OVERSEAS BANK LIMITED

PRIVATE CAR - INDIVIDUAL OWNERSHIP [MX 1]
AUTHORISED DRIVER

- (1) The Insured
- (2) Any other person who is driving on the Insured's order or with his permission
- (3) In the event of the death of the Insured
 - (a) any member of the Insured's family or a paid driver who has been driving the car during the lifetime of the Insured and permission to drive had not been withdrawn prior to the death of Insured and
 - (b) any other person who has been given permission to drive the vehicle prior to the death and such permission had not been withdrawn by the Insured

LIMITATIONS AS TO USE

Use only for social domestic and pleasure purposes and for the Insured's business

THE POLICY DOES NOT COVER

Use for hire or reward or racing pace-making reliability trial or speed-testing or the carriage of goods (other than samples) in connection with any trade or business or use for any purposes in connection with the Motor Trade

The carriage of passengers pursuant to car pooling arrangements and payments or any of them made by the passengers thereunder towards the running expenses of any vehicle described in the Schedule shall not be deemed to constitute use for hire or reward


Provided that the person is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

*Limitation rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles(Third-Party Risks and Compensation) Act (Chapter 189) and part IV of the Road Transport Act, 1987 (Malaysia).

UNITED OVERSEAS INSURANCE LTD

FCTTS Date : 08/08/2019


For the Company

S/NO PARTS DESCRIPTION

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 ROD-STABILIZER ?	54518-CY00A	36.80			
2 HUB ASSY-ROAD W ?	40202-3RA0B			391.30	
3 SPDL-KNUCKLE,RH ?	40014-1KA1A			435.00	
4 LINK COMPL,RH ?	54500-1ST0A	220.10			
5 STAUT KIT-FRONT ?	E4302-1ST0A			411.40	
6 BRKT BRKR RH <i>new</i>	62224-1ST1A	19.80			
7 SUNDRIES	MPH				<i>40.00 20</i>
8 LAMP ASSY-RH <i>can</i>	26010-1SB1C	535.60			
9 LAMP ASSY-LH <i>can</i>	26060-1SB1C	535.60			
10 SUPPORT UPR CONE RH <i>repair</i>	F2512-1DBMA	186.70			
11 GUIDE-RH <i>can</i>	62822-1RA0A	196.40			
12 FENDER-FRONT RH <i>bt</i>	F3100-1SBMB	722.60			
13 PROTR FRT <i>de</i>	61840-1EU0A	58.00			
14 CLIP-WOOD(1.3X10) <i>new</i>	45846-40F00	12.00			
15 HUB-SEAL WOOD F <i>new</i>	65810-1SU0A	55.50			
16 HOOD <i>bt</i>	F510W-1SBMA	911.40			
17 EMBLEM RAD GRIL <i>new</i>	62890-1FA0A	64.90			
18 GRILLE-RADIATOR <i>can</i>	62322-1ST0A	404.40			
19 RAD GRILLE <i>can</i>	62312-1SB0A	764.90			
20 BRKT LIC X	36210-1ST0A	142.20			
21 FINISHER FRT RH X	62256-1ST0B	124.80			
22 REINFORCE-BUMPE <i>repair</i>	F2032-1STMH	572.30			
23 ENERGY ABSORBER <i>cut</i>	62090-1ST0A	234.78			
24 CLIP(1.3X10) <i>new</i>	01553-10501	13.00			
25 GROMMET(1.3X2) <i>new</i>	01201-01431	2.60			

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SKOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SIC1453L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
24 FACE-FR BUMPER <i>der</i>	62022-35T1B	554.70		
SUB TOTAL		6408.80	0.00	1277.70
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1281.74	0.00	0.00
GRAND TOTAL		5127.04	0.00	1277.70
OVERALL TOTAL		6404.74		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120
3	RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE	480.00	?
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	100
5	WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	91.00	/
6	ZZ/001	CONDUCT WHEEL BALANCING & RENEW S/MIN FRT RH SIDE	15.00	/
7	ZZ/002	RPAIR CORE UPR LH, CORE PHL RH, FNDR LH, HOODLEDGE RH RNEW UPR CORE RH, UPR PANEL, HOOD&FRT BMPR	1680.00	1120
8	ZZ/003	S/PAINT FRT BUMPER, HOOD, FRT FENDER RH & LH SIDE, FRT PANEL ASSY, HOODLEDGE RH	1500.00	1250
TOTAL LABOUR CHARGES			4256.00	

CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLC1453L

TOTAL LABOUR CHARGES	4256.00
TOTAL SPARE PARTS CHARGES	6404.74
GRAND TOTAL	10660.74 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

RASUL - 14p 90010068
7 days

EXCESS : 750

REVERT
13/08/19 @ 1230

Resurvey before print

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 389623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/SHR/0403/2019
DATE : 10-AUG-2019

NG KUN QUAN C/O UNITED OVERSEAS INSURANCE LTD

3 ANSON ROAD #28-01

SPRINGLEAF TOWERS

S(079909)

TEL : 62227733/64909318

FAX : 63273869 / 72

ATTN:MOTOR CLAIM MANAGER

OWNER'S NAME : MR HARBAHS SINGH
ADDRESS : BLK 654 YISHUN AVE 4
#12-441
S(760654)
TELEPHONE NO : 97483052

TYPE OF CLAIM : OD OR OD RECOVERY CLAIM
POLICY NO : D88M120028651701
VEHICLE NO : SLC1453L
MODEL CODE : BDTARCEB17ENA----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR169894008
CHASSIS NO : MNTBBAB17R0027213
MILEAGE : 1 KM
DATE IN : 10/08/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD EHHRI
ACCIDENT DATE : 10/08/2019

OD Recovery 10.8.19
The Vehicle In

3/5/2016

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120
3 RRDC	REMOVE/REPAIR WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE	480.00	? X 17
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	100
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	/
6 ZZ/001	CONDUCT WHEEL BALANCING & RENEW S/RIM FRT RH SIDE	15.00	/
7 ZZ/002	REPAIR CORE UPR LH, CORE PNL RH, FNDR LH, HOODLEDGE RH RNEW UPR CORE RH, UPR PANEL, HOOD&FRT BMPR	1680.00	1120
8 ZZ/003	S/PAINT FRT BUMPER, HOOD, FRT FENDER RH & LH SIDE, FRT PANEL ASSY, HOODLEDGE RH	1500.00	1250
TOTAL LABOUR CHARGES		4256.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SKOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	ROD-STABILISER ?	54618-CY00A	36.60	X	su	
2	HUB ASSY-ROAD W ?	40202-3RA0B				391.30 X su
3	SPDL-KNUCKLE,RH ?	40014-1KA1A				435.00 X su
4	LINK COMPL,RH ?	54500-3ST0A	220.10	X	su	
5	STRUT KIT-FRONT ?	E4302-3ST0A				411.40 X su
6	BRKT BMFR RH neu/	62224-3ST1A	19.80			
7	SUNDRIES	NPN				40.00 20
8	LAMP ASSY-RH ca/	26010-3SB1C	535.60	815		
9	LAMP ASSY-LH ca/	26060-3SB1C	535.60	815		
10	SUPPORT UPR CORE RH repair	F2512-3DBMA	186.70	X		
11	GUIDE-RH ca/	62822-3RA0A	196.40			
12	FENDER-FRONT RH bt/	F3100-3SBMB	722.60			
13	PROTR FRT de/	63840-3SU0A	98.00			
14	CLIP-HOOD(1.2X10) neu/	65846-40F90	12.00			
15	RUB-SEAL HOOD F neu/	65810-3SB0A	55.50			
16	HOOD bt/	F510H-3SBMA	911.40			
17	EMBLEM RAD GRIL neu/	62890-1KA0A	64.90			
18	GRILLE-RADIATOR ca/	62322-3ST0A	404.40			
19	RAD GRILLE ca/	62312-3SB0A	764.90			
20	BRKT LIC X su	96210-3ST0A	142.20	X		
21	FINISHER FRT RH X su	62256-3ST0B	124.80	X		
22	REINFORCE-BUMPE repair	F2032-3STMH	572.30	X		
23	ENERGY ABSORBER cut/	62090-3ST0A	234.70			
24	CLIP(1.3X10) neu/	01553-10501	13.00			
25	GROMMET(1.3X2) neu/	01281-01431	2.60			

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	FACE-FR BUMPER <i>de</i>	62022-3B71R	554.70		
SUB TOTAL			6408.80	0.00	1277.70
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1281.76	0.00	0.00
GRAND TOTAL			5127.04	0.00	1277.70
OVERALL TOTAL			6404.74		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO ELC14531

TOTAL LABOUR CHARGES	4256.00
TOTAL SPARE PARTS CHARGES	6404.74
GRAND TOTAL	10660.74 *

10975.70

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
 SURVEYED DATE :
 AUTHORIZED DATE :
 EXCESS CLAUSE : 0.00
 LIABILITY : 0.00
 REMARKS :

Rasul - Hp 90010068
 7 days

EXCESS : 750

Repeat
 13/08/19 @ 1230

Resurvey before paint

11477.24

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from Insurers

Accepted/Noted by Repairer
 Signature:
 Date:

15-Aug-2019

INS/IC/ZHR/0403/2019

NG KUN QUAN C/O UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD #28-01
SPRINGLEAF TOWERS
S(079909)

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLC1453L
POLCY NO. : DH0M120029651701

Further to our claim INS/IC/LAW/0999/2007 we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items

- 1 ALLOY RIM *SCA*
2 HINGE RH *bt - 20%*

\$280.00 S/NETT
\$43.70 NETT

TOTAL \$323.70

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully
TAN CHONG MOTOR SALES PTE LTD

[Signature]
MZUHR
Insurance Claim Dept

Cc: Surveyor RASUL(LKK-AUTO)

Auto Consultants hence notify
Repairer of the following:

- Resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 389621

FINALISED : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : IMS/IC/ZHR/0403/2019
DATE : 10-AUG-2019

ODR => Rasu (LKK)

UNITED OVERSEAS INSURANCE LTD
3 ARSON ROAD #28-01
SPRINGLEAF TOWERS
S(079909)
TEL : 62227733/64909318
FAX : 63273869 / 72
ATTN: MOTOR CLAIM MANAGER

ZHR

OWNER'S NAME : MR HARDANG SINGH
ADDRESS : BLK 654 YISHEN AVE 4
#12-441
S(760654)
TELEPHONE NO : 97483052

Recommend Repair
7 Days.

TYPE OF CLAIM : OO OR OO RECOVERY CLAIM
POLICY NO : DNGM120028651701
VEHICLE NO : SLCL453L
MODEL CODE : BDTANC2817EWA-----A
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT)
ENGINE NO : HR169894008
CHASSIS NO : MKTBRAB1720027213
MILEAGE : 1 KM
DATE IN : 10/08/2019
LIABILITY : 0.00
EXCESS CLAUSE : 750.00
ESTIMATE BY : MUHAMMAD TUNRI
ACCIDENT DATE : 10/08/2019

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FRI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	48.00
2 RPI	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL	240.00	120.00
3 RRUC	REMOVE/REFIN WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE	480.00	.00
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL	200.00	100.00
5 WAPI	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION- PASSENGER	93.00	93.00
6 22/001	CONDUCT WHEEL BALANCING & REWREN 5/RIM FRT RH SIDE	15.00	15.00
7 22/002	REPAIR CORE UPN LH,CORE PHL RH,FRON LH,HOODLEDGE RH REWEN UPN CORE RH,UPN PANEL,HOOD&FRT BUMP	1680.00	1120.00
8 22/003	2/PAINT FRT BUMPER,HOOD,FRT FENDER RH & LH SIDE, FRT PANEL ASSY,HOODLEDGE RE	1500.00	1250.00
TOTAL LABOUR CHARGES		4256.00	2746.00

IAN CHONG MOTOR SALES PTE. LTD.
SUNIT TIMAR W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 ALLOY RIM(G11/B17)16X5.5(SUPPLIER)	40300-SBW166			280.00	OK ✓
2 HINGE HOOD(SUPPLIER)	F5400-3RAMA	43.70			OK ✓
3 LAMP ASSY-LH(CONFIRM AMOUNT)	26060-3SB0D	815.00			OK ✓
4 LAMP ASSY-RH(CONFIRM AMOUNT)	26010-3SB0D	815.00			OK ✓
5 LAMP ASSY-RH(WRONG AMOUNT)	26010-3SB1C	535.60			X
6 LAMP ASSY-LH(WRONG AMOUNT)	26060-3SB1C	535.60			X
7 SUPPORT UPR CORE RH	F2512-3DBHA	186.70			X
8 GUIDE-RH	E1822-3HA0A	196.40			OK ✓
9 FENDER-FRONT RH	F3100-3SBMB	722.60			OK ✓
10 SUNDRIES	NPN			20.00	OK
11 PROTR FRT	63840-3BU0A	98.00			OK ✓
12 CLIP-HOOD(1.2X10)	65846-40F00	12.00			OK ✓
13 RUB-SEAL HOOD F	65810-3SB0A	55.50			OK ✓
14 HOOD	F510N-3SBMA	911.40			OK ✓
15 EMBLEM RAD GRIL	62890-1KA0A	64.90			OK ✓
16 GRILLE-RADIATOR	62322-3ST0A	404.40			OK ✓
17 RAD GRILLE	62312-3SB0A	764.50			OK ✓
18 MUXT LIC	96210-3ST0A	142.20			X
19 FINISHER FRT RH	62256-3HT00	124.80			X
20 REINFORCE-BUMPER	F2032-3STHE	372.30			X
21 ENERGY ABSORBER	62090-3HT0A	236.70			OK
22 CLIP(1.3X10)	01553-10501	13.00			OK ✓
23 GROMMET(1.3X2)	01281-01431	2.60			OK ✓
24 FACE-FR BUMPER	62022-3ST1H	554.70			OK ✓
25 ROD-STABILIZER	54618-CY00A	36.60			X

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLC1453L

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 HUB ASSY-ROAD W	40202-33A08			391.30 X ✓
27 LINK COMPL,RH	54500-38T0A	220.10		X ✓
28 STRUT KIT-FRONT	54302-38T0A			411.40 X ✓
29 BRKT DMFR RH	62224-38T1A	19.00		OK ✓
30 SPOL-KNUCKLE,RH	40014-18A1A			635.00 X ✓
SUB TOTAL		5720.60	0.00	300.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1145.72	0.00	0.00
GRAND TOTAL		4582.88	0.00	300.00
OVERALL TOTAL		4992.88		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TINAH ROAD

SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE BOOK NO SLC1453L

NETT ITEM	5729.60
LESS 20.00%	-1145.72
NETT AMOUNT	4582.88

LIST ITEM	0.00
LESS 20.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	300.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	300.00

TOTAL LABOUR CHARGES	2746.00
TOTAL SPARE PARTS CHARGES	4582.88

TOTAL CHARGES	7628.88
LESS EXCESS	750.00

TOTAL	6878.88
ADD 7 % GST	481.52

GRAND TOTAL	7360.40
-------------	---------

15-Aug-2019

INS/IC/ZHR/0403/2019

NG KUN QUAN C/O UNITED OVERSEAS INSURANCE LTD
3 ANSON ROAD #28-01
SPRINGLEAF TOWERS
S(079909)

Attn : Motor Claim Manager
Claim Dept

Dear Sir

SUPPLEMENTARY CLAIM

REGN. NO. : SLC1453L
POLCY NO. : DHDM120028651701

Further to our claim INS/IC/LAW/0999/2007 we are submitting a supplementary claim for the below mentioned items which were found damaged during the course of repairs.

Replacement of Damaged Items

- 1 ALLOY RIM
- 2 HINGE RH

\$280.00 S/NETT
\$43.70 NETT

wt ✓
bt ✓

TOTAL \$323.70

We trust the above supplementary claim will meet with your kind approval and we will forward to you the final repair bill together with the satisfaction note on completion repairs.

Yours faithfully

TAN CHONG MOTOR SALES PTE LTD

M. ZUHYRY
Insurance Claim Dept

Cc: Surveyor RASUL(LKK-AUTO)

Signature
15/8/19
Spm



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19013977/R1sd3e2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 07-11-2019	
		Code : UOI2	
1. Policy Particulars :- OWN DAMAGE			
Insured Veh.		Veh. Inspected	SLC 1453L
Policy No.	DH0M120028651701	Coverage (\$)	0.00
Claim No.	M12D11231908	Excess (\$)	750.00
Assign From	JENNY LEW	Assign Date	13/08/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN SYLPHY 1.6 CVT	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MNTBBAB17Z0027213	Colour	RED
Odometer	68811	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	195/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	195/60 R16	BRIDGESTONE	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/08/2019	Inspection Date	13/08/2019
Survey held at	913 BUKIT TIMAH		
Repairer	TAN CHONG MOTOR SALES PTE LTD		
5a. Remarks			
A)THE MARKET VALUE IS S\$58,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 1453L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ROD-STABILIZER (N)	SERVICEABLE	36.60	-
1	LINK COMPL. RH (N)	SERVICEABLE	220.10	-
1	BRKT BMPR RH (N)	NECESSARY	19.80	19.80
1	LAMP ASSY - RH (N)	CRACKED	815.00	815.00
1	LAMP ASSY - LH (N)	CRACKED	815.00	815.00
1	SUPPORT UPR CORE RH (N)	TO REPAIR SEE LABOUR	186.70	-
1	GUIDE - RH (N)	CRACKED	196.40	196.40
1	FENDER-FRONT RH (N)	BENT	722.60	722.60
1	PROTR FRT (N)	DEFORMED	98.00	98.00
10	CLIP-HOOD @\$1.20 (N)	NECESSARY	12.00	12.00
1	RUB-SEAL HOOD F (N)	NECESSARY	55.50	55.50
1	HOOD (N)	BENT	911.40	911.40
1	EMBLEM RAD GRIL (N)	NECESSARY	64.90	64.90
1	GRILLE-RADIATOR (N)	CRACKED	404.40	404.40
1	RAD GRILLE (N)	CRACKED	764.90	764.90
1	BRKT LIC (N)	SERVICEABLE	142.20	-
1	FINISHER FRT RH (N)	SERVICEABLE	124.80	-
1	REINFORCE-BUMPE (N)	TO REPAIR SEE LABOUR	572.30	-
1	ENERGY ABSORBER (N)	CUT	234.70	234.70
10	CLIP @\$1.30 (N)	NECESSARY	13.00	13.00
2	GROMMET @\$1.30 (N)	NECESSARY	2.60	2.60
1	FACE-FR BUMPER (N)	DEFORMED	554.70	554.70
1	HINGE RH (N) (ADDITIONAL)	BENT	43.70	43.70
	LESS 20% DISCOUNT		-1,402.26	-1,145.72
			5,609.04	4,582.88
SPECIAL NETT ITEMS				
1	HUB ASSY-ROAD W (SN)	SERVICEABLE	391.30	-
1	SPDL-KNUCKLE, RH (SN)	SERVICEABLE	435.00	-
1	STRUT KIT-FRONT (SN)	SERVICEABLE	411.40	-
1	SUNDRIES (SN)	NECESSARY	40.00	20.00
1	ALLOY RIM (SN) (ADDITIONAL)	SCRATCHED	280.00	280.00
			1,557.70	300.00

Report Ref No. CS/UOI19013977/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION.		48.00	48.00
	PERFORM RUST PROOFING & TREATMENT FOR 2X AFFECTED PANEL.		240.00	120.00
	REMOVE / REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE.	NOT NECESSARY	480.00	-
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY 2X AREA PANEL.		200.00	100.00
	ELECTRONIC 4 WHEEL ALIGNMENT & ADJUST STRG ANGLES TO STANDARD SPECIFICATION - PASSENGER.		93.00	93.00
	CONDUCT WHEEL BALANCING & RENEW S/RIM FRT RH SIDE.		15.00	15.00
	RPAIR CORE UPR LH, CORE PNL RH, FNDR LH, HOODLEDGE RH RNEW UPR CORE RH, UPR PANEL, HOOD & FRT BMPR. INCLUSIVE OF THE REPAIR OF SUPPORT UPR CORE RH AND REINFORCE-BUMPE.		1,680.00	1,120.00
	S/PAINT FRT BUMPER, HOOD, FRT FENDER RH & LH SIDE, FRT PANEL ASSY, HOODLEDGE RH.		1,500.00	1,250.00
			4,256.00	2,746.00
	GRAND TOTAL		11,422.74	7,628.88
	RECOMMENDED COST OF REPAIRS			7,628.88
	LESS EXCESS			-750.00
	NETT LIABILITY			6,878.88

Report Ref No. CS/UOI19013977/R1sd3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.