

ASS. REC. BY:

REF:

CS/EQI 19013982/6vd301

Special Instruction:

Surveyor: GA

ASSIGNMENT (Office)

From (Person): Tan Wei Yin

of

EQI

Date/Time: 8/8/19 @ 9:30am

Estimated Cost:

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHK 4394L

Insured:

SLW 4088H

at Workshop m/s

Siang Hui

Tel:

6744 4605

of

BLK 3006 ubi Road 1 # 01-338

Policy No:

Claim No:

DM19H002210

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A 7/8/2019

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time: 9:08am @ 13/8/19

Person Contacted:

Siang Hui

Vehicle IN/OUT

Date/Time

Action/Instruction

Ishtingli ✓

SHK 4394L - X

SLW 4088H - X.

15/8/19

@ 1202pm Siang Hui said pass to lawyer

Nivitha (LKK Auto)

From: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Sent: Thursday, 8 August 2019 9:30 PM
To: Admin A; assignments
Subject: EQ REF:DM19HO02210, PRI - Acc Inv: SLK 4394 L & SLW 4088 H ON 7 AUGUST 2019
Attachments: SAS2648213.pdf; SAS2648460.pdf

Dear Sir,

Please attend as SJE.

Thank you.


Regards,


Tan Wei Yin
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 64969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, August 8, 2019 5:33 PM
To: Tan Wei Yin <weiyin.tan@eqinsurance.com.sg>
Subject: Re: PRI - Acc Inv: SLK 4394 L & SLW 4088 H ON 7 AUGUST 2019

Dear Wei Yin,

We refer to your email dated 8 August 2019.

Our client has no objection of appointing the motor surveyor LKK Auto consultants Pte Ltd stated in your said list to conduct the joint pre-repair survey as a single joint expert.

Regards,

June



On Thu, 8 Aug 2019 at 11:22, Tan Wei Yin <weiyin.tan@eqinsurance.com.sg> wrote:

Without Prejudice

Save As To Costs

Dear Sir,

We shall be appointing our surveyor to attend to the pre-repair survey of your client's vehicle.

Below is a list of motor surveyors in our panel. Please revert within 2 working days if you agree or have any objections to the appointment of any of the motor surveyors. If we do not hear from you, you are deemed to have agreed to the appointment of any of the motor surveyors listed by us. Alternatively, please specify one or more of our proposed motor surveyors to the said assignment.

1) AJAX Inspection Services Pte Ltd Tel: 6255 0808 Fax: 6849 9155	2) Automobile Inspection Services Pte Ltd Tel: 6286 0155 Fax: 6284 1539 Contact Person: Sophia
3) LBS Automotive Appraisal Pte Ltd L.B.S. Auto Consultants Pte Ltd Tel: 6281 6690 / 62832866 Fax: 6281 8748 Contact Person: Amy/ Grace	4) Priority Services Tel: 62934822 Fax: 62963283 Contact Person: Sharon
5) RT Appraisal Pte Ltd Tel: 67486076 Fax: 67480361 Contact Person: Elson/Elgene	6) LKK Auto Consultants Pte Ltd Tel: 6256-3561 Fax: 6741-4108

7) Kelvin Automotive Appraising Services Tel: 81825263 Fax: 67461148 Contact Person: Kelvin	8) Automotive Appraiser & Surveying Services Tel: 96623655 Fax: 67655662 Contact Person: Mr Chee
9) JP Knights Pte Ltd Tel: 63450068 Fax: 63445328	10) Appraisals Associates Pte Ltd Tel : 67472822 Fax: 67470070
11) Infiniti Appraisal Service Tel : 96684818/90099001 Fax: 64587432	12) Formteam Adjusters Pte Ltd Tel: 65091788 Fax: 65096221

If you object to all the motor surveyors as proposed by us, please provide a list of at least 10 motor surveyors whom you consider as suitable to appoint for our consideration. We shall revert to you within 2 working days.

Meanwhile, we reserve our rights on Post-Repair Inspection, kindly contact us or our appointed surveyor before you return your client's vehicle to him/her.

Thank you.

Regards,

Tan Wei Yin

Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110

did 65 64969882 | tel 65 6223 9433 ext 882 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender immediately and delete all copies of this message.

From: bonnie kwok [mailto:litigation@bonniekwok.com]
Sent: Thursday, August 8, 2019 11:07 AM
To: EQI PRS <EQIPRS@eqinsurance.com.sg>
Subject: PRI - Acc Inv: SLK 4394 L & SLW 4088 H ON 7 AUGUST 2019

Dear Sir,

We refer to the above matter.

I hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SLK 4394 L at M/s Siang Hui Motor Works, Block 3006 Ubi Road 1 #01-338 Singapore 568047. Contact number 67444605.

Regards,
June

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



Virus-free. www.avg.com

--

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	758F
Vehicle Details	
Vehicle No.:	SLK4394L
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	CITY 1.5 SV CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	L15Z14113438
Chassis No.:	MRHGM6660HP000412
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$17,760.00
Original Registration Date:	17 Jan 2017
First Registration Date:	17 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$12,760.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2027
PARF Rebate Amount:	\$9,570.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$36,925.00
Total Rebate Amount:	\$46,495.00

The information contained herein is correct as at 14 Aug 2019

OK

MKFS10103600 / Kan Fook Sing Motor Workshop - Defu
ENTRY DATE & TIME: 07/08/2019 17:05
SUBMITTED BY: Margaret Lee

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 07/08/2019 17:05
Date Of Accident 07/08/2019 07:30
Exact Location Of Accident DEFU LANE 11
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLK4394L
Insured/Policyholder
Name Of Registered Owner KWEK SIAK MING
NRIC No S1686758F
Email Address JES.LIMKK@GMAIL.COM
Mobile Phone No (LOCAL) +65-91195510
Alternative Phone No OFFICE-91195510
Vehicle Particulars
Manufacturer HONDA
Model CITY
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number D19MTPV01000761
Cover Note Number

Driver

Name of Driver KWEK SIAK MING
NRIC No S1686758F
Date Of Birth 15/04/1965
Occupation OUTDOOR
Date Of Driving Pass 13/02/1986
Driving Experience 33 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91195510
Fax Number
Contact Number OFFICE-91195510
EMail Address JES.LIMKK@GMAIL.COM

Address BLK 301B ANCHORVALE DR #13-61 S542301
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1

NAME: JESLIN LIM

GENDER: FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED REPORT

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLW4088H
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver JOSEPH LEONARD SEBASTIAN
 NRIC/Passport Number
 Contact Number 94870771
 Address NA
 Postcode NA
 Insurance Company Name
 Nature Of Damage

1 1 1 1 1

I was standing at the beam crossing in the
underground in 1973. Suddenly I felt an impact from
behind a railroad vehicle & two kid cars my
reaction.



LKK Auto Consultants hence notify
the Repairer the following:

- To resurvey before after spray painting
- To display of repair parts in a display
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

Acknowledged by Repairer

Signature:

Date:

Vehicle No: SLK 4394L Honda city

Date:

13/8/19

1	IPC Boot lid / blue		\$ 495.80 ✓
2	IPC Boot lid w/strip / Twi		\$ 86.10 ✓
3	IPC Boot lid inner lock / BT	96	\$ 156.70 ✓
4	IPC Boot lid moulding / ORA	95	\$ 183.40 ✓
5	2PCS Boot lid reflector @ \$ 201.90 ✓	scr	\$ 403.80 24
6	IPC City emblem		\$ 54.30 35
7	IPC "H" emblem	✓	\$ 53.80 35
8	IPC 1VTEC emblem	✓	\$ 64.70 42
9	IPC Rear bumper	✓	\$ 483.70 ✓
10	2PCS Rear bumper retainer @ \$ 17.10 ✓	de	\$ 34.20 ✓
11	2PCS Reverse Sensor 7, DM @ \$ 183.30		\$ 366.60 200
12	7PC End panel 7 / blue		\$ 368.90 ✓
13	IPC End panel garnish 7 / re		\$ 86.40 ✓
14	6PCS Bumper clip @ \$ 4.50 ✓	ML	\$ 27.00 ✓
15	2PCS Bumper reflector @ \$ 68.30 X		\$ 136.60 X
225.1			
20% : 1700.08			
Less 20%			
		NN	\$ 3002.00
			\$ 600.40
16	IPC Rear No plate with bracket		\$ 2401.60
17	IPC Tail lamp (LH) 7 / Cut		\$ 38.00 S/Net
Labour Charges:-			\$ 328.00 235
To remove, replace reverse sensor & check wiring			\$ 80.00 400
To spray painting			\$ 980.00 600
To remove, replace all accident parts to same			\$ 980.00 600
5 Days			\$ 4479.60 1240
umpson repair			
After repair photos			
Gm Chp - 82 88 0282			
15/8/19			
14/8/19			
90% : 2700			
17/12			




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CS/EQI19013982/Gvd3e2	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 19-08-2019	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLW 4088H	Veh. Inspected	SLK 4394L	
Policy No.		Coverage (\$)	0.00	
Claim No.	DM19HO02210	Excess (\$)	0.00	
Assign From	TAN WEI YIN	Assign Date	08/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CITY	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHGM6660HP000412	Colour	GREY	
Odometer	70948	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R16	MICHELIN	6 mm	
L/H Front Tyre	185/55 R16	MICHELIN	6 mm	
R/H Rear Tyre	185/55 R16	MICHELIN	6 mm	
L/H Rear Tyre	185/55 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2019	Inspection Date	14/08/2019	
Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLK 4394L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID	BUCKLED	495.80	495.80
1	BOOT LID W/STRIP	TWISTED	86.10	86.10
1	BOOT LID INNER LOCK	BENT	156.70	96.00
1	BOOT LID MOULDING	CRACKED	183.40	95.00
2	BOOT LID REFLECTOR @\$201.90	SCRATCHED	403.80	240.00
1	CITY EMBLEM	NECESSARY	54.30	35.00
1	'H' EMBLEM	NECESSARY	53.80	35.00
1	IVTEC EMBLEM	NECESSARY	64.70	42.00
1	REAR BUMPER	DEFORMED	483.70	483.70
2	REAR BUMPER RETAINER @\$17.10	DEFORMED	34.20	34.20
1	END PANEL	BUCKLED	368.90	368.90
1	END PANEL GARNISH	DEFORMED	86.40	86.40
6	BUMPER CLIP @\$4.50	NECESSARY	27.00	27.00
2	BUMPER REFLECTOR @\$68.30	NOT NECESSARY	136.60	-
1	TAIL LAMP (LH)	CUT	328.00	235.00
	LESS 20% DISCOUNT		-592.68	-472.02
			2,370.72	1,888.08
2	REVERSE SENSOR @\$183.30 (SN)	DAMAGED	366.60	200.00
	LESS 20% DISCOUNT		-73.32	-
			293.28	200.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR NO PLATE WITH BRACKET (SN)	CUT	38.00	38.00
			38.00	38.00
<u>LABOUR</u>				
	TO REMOVE, REPLACE REVERSE SENSOR & CHECK WIRING.		80.00	40.00
	TO SPRAY PAINTING.		980.00	600.00
	TO REMOVE, REPLACE ALL ACCIDENT PARTS TO SAME.		980.00	600.00
			2,040.00	1,240.00

Report Ref No. CS/EQ19013982/Gvd3e2



GRAND TOTAL		4,742.00	3,366.08
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,700.00

Report Ref No. CS/EQI19013982/Gvd3e2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.