

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 21 Aug 2019

Preliminary Advice

Vehicle No	: FZ2999Y	Accident Date	: 07/08/2019
Make	: HONDA CB400	Policy No.	: 1800146880
Assignment Date	: 13/08/2019	Excess	: S\$500.00
Date of Inspection	: 20/08/2019	Est. Duration of Repair	: 4.00
Inspection At	: BIKE PRODUCTION PIE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,382.00
Revised Amount	:S\$	2,532.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,532.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	2,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Vehicle repair on Lump Sum basis