

1 (04/2018)

ASS. REC. BY:

REF: C/TPD 17013990/NC

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kamalish Kamis of SPF

Date/Time: 5/8/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: JNF 9548

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPE06000022888/1

Claim No: TP/IP/43851/2019

Sum Insured:

Excess:

Make of Veh:

D.O.A. 15/7/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle IN/OUT

Date/Time Action/Instruction ( ) Estimate

JNF 9548 - X

450/9

**Sherwin Beh (LKK Auto)**

---

**From:** Kamaliah KAMIS (SPF) <Kamaliah\_KAMIS@spf.gov.sg>  
**Sent:** Monday, 5 August, 2019 1:06 PM  
**To:** Sherwin Beh (LKK Auto); Naz (LKKAuto); Bryan Ang (LKKAuto)  
**Cc:** SPF-TP FAIT  
**Subject:** Mechanical Inspection Report Request

Dear Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 10 vehicles below:

**a) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, FBM4907R (TP/IP/42471/2019)**

On 8 July 2019 (Monday) sometime before 5.44 pm, the Deceased was travelling straight along Tampines Expressway towards the direction of Seletar Expressway, 7km on lane 2 of the 3-lanes road when he ran over a stone on the road, causing him to lose control, self-skidded and landed on lane 3. Due to the accident, the Deceased who was reported to be unconscious and sustained multiple injuries was conveyed to Khoo Teck Puat Hospital by an ambulance. However on 9 July 2019 at 9.56 am, the Deceased succumbed to his injuries and he was pronounced dead by Dr Li Qi Jonathan Ricky.

**Vehicles to be inspected:** FBM4907R - Rider (Deceased)

IO In-Charge: SIO Kamaliah

**b) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, JNF9548 (TP/IP/43851/2019)**

On 15 July 2019 (Monday) sometime before 7.49 am, the Deceased was travelling straight along Pioneer Road towards the direction of Jalan Buroh when he lost control of the motorcycle, veered to the left, collided into the left curb side of the road and subsequently skidded on the road. Due to the accident, the Deceased who was reported to be unconscious and sustained facial injuries with suspected cardiac arrest was conveyed to Ng Teng Fong General Hospital by an ambulance. However on 15 July 2019 at 9.26 am, the Deceased succumbed to his injuries and he was pronounced dead by Dr Michael Choo.

**Vehicles to be inspected:** JNF9548 - Rider (Deceased)

IO In-Charge: SIO Kamaliah

**c) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, JSK1728 (TP/IP/45247/2019)**

On 21 July 2019 (Sunday) sometime before 6.00 am, the Deceased and the pillion rider were on the motorcycle and were travelling straight along Tuas South Blvd towards the end, after Tuas South Way. While travelling on lane 1 of the 3-lanes road, the motorcycle veered to the right, mounted the centre divider and landed on the grass verge of the centre divider. As a result of the accident, the Deceased and pillion rider sustained multiple injuries and were conveyed to the Ng Teng Fong General Hospital by ambulance. The Deceased, who was reported to be unconscious, suffered a cardiac arrest. He succumbed to his injuries and was pronounced dead in hospital on the same day at 7.13 a.m., by Dr Wilona Lee. The pillion rider is currently admitted in Ng Teng Fong General Hospital, Tower B, Ward 8, Bed 18A for follow-up treatment.

**Vehicles to be inspected:** JSK1728 - Rider (Deceased)