

(10/1/94)

ASS. REC. BY:

REF: C1/TPD 14013996/NC

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Kanaliah Kaniis

of SPF

Date/Time: 5/8/2019

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBD 3852T

Insured:

at Workshop m/s

Tel:

of

Policy No: MHASPF060000223881

Claim No: TP/IP/43523/2019

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 13/7/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction () Estimate

FBD 3852T-X

IO In-Charge: SIO Kamaliah

- d) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, FBC2407H (TP/IP/47301/2019)
- e) Case IAFP-IB-20190802 - Mechanical Inspection of Motor Lorry, YN668D (TP/IP/47301/2019)

On 30 July 2019 (Sunday) sometime before 9.26 pm, the motor lorry (B1) was travelling along Harbour Drive towards Pasir Panjang Road on the lane 2 of the 3-lanes road. Upon reaching the signalised T-junction of PSA Gate 4 Entrance, the traffic light signal was showing red light. Hence, B1 come to a stop before the junction. After the traffic light signal turned 'green-only', B1 proceed to make a right turn into PSA Gate 4 Entrance. Out of a sudden, B1 saw the motorcycle (A1) travelling at a fast speed from the opposite direction. The front portion of A1's motorcycle then collided into the left front corner of B1's motor lorry. As a result of the accident, A1 sustained lower right limb near amputation and was conveyed conscious to National University Hospital by an ambulance. However on the same day at 2.18 am, A1 succumbed to his injuries and was pronounced dead by Dr Menon.

Vehicles to be inspected: FBC2407H - Rider (Deceased)

Vehicles to be inspected: YN668D - Driver (Potential Defendant)

IO In-Charge: SIO Kamaliah

- f) Case IAFP-IB-20190802 - Mechanical Inspection of Motor Lorry, YN5091J (TP/IP/42055/2019)
- g) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, FBC4128A (TP/IP/42055/2019)

On 6 July 2019 at about 5.37 pm, the deceased was riding motorcycle FBC 4128 A T along Gul lane when the bike collided with motor lorry YN 5091 J that was travelling along Gul Cresent. As a result of the accident the rider dies at the scene while the pillion was sent to NUH in an unconscious state.

Vehicles to be inspected: FBC4128A - Rider (Deceased)

Vehicles to be inspected: YN5091J - Driver (Potential Defendant)

IO In-Charge: SIO Mohd Yazid

- h) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, FBD3852T (TP/IP/43523/2019)

On 13 July 2019 at about 1.09 am, the deceased riding motorcycle FBD3852T along Woodlands Avenue 1 when he lost control of his motorcycle, hit the left kerb mounted the kerb and collided onto a lamp post. Rider was sent to KTPH unconscious and he succumbed to his injuries in hospital.

Vehicles to be inspected: FBD3852T - Rider (Deceased)

IO In-Charge: SIO Mohd Yazid

- i) Case IAFP-IB-20190802 - Mechanical Inspection of Motorcycle, FBG4881H (TP/IP/44541/2019)
- j) Case IAFP-IB-20190802 - Mechanical Inspection of Motor Car, SJY7402C (TP/IP/44541/2019)

On 17 July 2019 (Wednesday) at about 10.03 p.m., the Potential Defendant drove his motorcar on lane 2 of the 4 lanes of Tampines Avenue 2 towards Tampines Avenue 9. At the signalised cross junction of Tampines Street 32, the Potential Defendant made a right turn into Tampines Street 32 towards Tampines Street 33, when the traffic light signal was showing amber. At the same time, the Deceased was riding his motorcycle from the opposite direction along Tampines Avenue 2 towards Tampines Avenue 1, when he collided onto the left front portion of the Potential Defendant's motorcar. Due to the accident, the Deceased was conveyed by ambulance to the Changl General Hospital however, he