

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5318K****AAD1908-039**

*Not Authored*  
*Resony B4poin*  
*86401*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

08 AUG 2019

**SHD 5318K**

JTDKB3FU103078509

TOYOTA

PRIUS

3.8.19

**EQ**

19/12/2018

|              |   | PART                                     | LIST |                 |
|--------------|---|------------------------------------------|------|-----------------|
| 1            | 1 | MOULDING ASSY, BODY ROCKER PANEL, RH     | \$   | 583.30          |
| 2            | 1 | PANEL SUB-ASSY, REAR DOOR, RH            | \$   | 1,258.30        |
| 3            | 1 | LOCK ASSY, REAR DOOR W/MOTOR, RH         | \$   | 554.60          |
| 4            | 1 | REINFORCE SUB-ASSY, ROCKER, OUTER RH     | \$   | 572.10          |
| 5            | 1 | REINFORCEMENT SUB-ASSY, ROCKER PANEL, RH | \$   | 336.60          |
| 6            | 1 | BOARD SUB-ASSY, REAR DOOR TRIM, RH       | \$   | 549.30          |
| 7            | 1 | PANEL, QUARTER WHEEL HOUSE, OUTER RH     | \$   | 290.50          |
| 8            | 1 | REAR FENDER RH                           | \$   | 836.70          |
| 9            | 1 | REAR FENDER LINER                        | \$   | 138.10          |
| 10           | 1 | REAR BUMPER                              | \$   | 458.60          |
| 11           | 1 | REAR BUMPER RE-INFORCEMENT               | \$   | 318.80          |
| 12           | 1 | REAR BUMPER TOWING COVER                 | \$   | 14.70           |
| 13           | 1 | REAR BUMPER UNDER COVER (BLACK)          | \$   | 552.60          |
| 14           | 1 | REAR BUMPER SIDE RETAINER RH             | \$   | 112.70          |
| 15           | 1 | TAILLAMP LOWER RH                        | \$   | 548.40          |
| 16           | 1 | TAILLAMP UPPER RH                        | \$   | 557.90          |
| 17           | 1 | REAR BUMPER SIDE RH                      | \$   | 232.00          |
| 18           | 1 | COVER, REAR COMBINATION LAMP, RH         | \$   | 54.70           |
| 19           | 1 | REAR TAILGATE                            | \$   | 1,547.27        |
| <b>TOTAL</b> |   |                                          | \$   | <b>9,517.17</b> |
| <b>25%</b>   |   |                                          | \$   | <b>2,379.29</b> |
|              |   |                                          | \$   | <b>7,137.88</b> |

**Special Nett**

|   |   |                               |    |          |
|---|---|-------------------------------|----|----------|
| 1 | 1 | REAR DOOR STICKER '6555-3333' | \$ | 80.00    |
| 2 | 1 | REAR RIGHT WHEEL RIM          | \$ | 1,570.55 |
| 3 | 1 | REAR RIGHT WHEEL RIM COVER    | \$ | 175.80   |
| 4 | 1 | SET PARKING AID               | \$ | 700.00   |
| 5 | 1 | SET REAR BUMPER CLIP          | \$ | 66.00    |

**Trans-cab Auto Services Pte Ltd****AAD1908-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5318K**

|              |   |                                   |    |    |                 |     |
|--------------|---|-----------------------------------|----|----|-----------------|-----|
| 6            | 1 | REAR BUMPER PROTECTOR             | \$ | Sm | 100.00          | } X |
| 7            | 2 | REAR WINDSCREEN SEALANT           | \$ | na | 80.00           |     |
| 8            | 1 | WINDSCREEN MOULDING               | \$ | na | 100.00          |     |
| 9            | 1 | REAR WINDSCREEN INNER SPONGE SEAL | \$ | na | 100.00          |     |
| 10           | 1 | REAR TAILGATE TOYOTA LOGO         | \$ | na | 47.00           |     |
| 11           | 1 | REAR TAILGATE WORDING 'PRIUS'     | \$ | na | 52.90           |     |
| 12           | 1 | REAR TAILGATE WORDING 'HYBRID'    | \$ | na | 53.50           |     |
| 13           | 1 | REAR TAILGATE STICKER 'TRANS-CAB' | \$ | na | 80.00           |     |
| 14           | 1 | REAR TAILGATE STICKER '6555-3333' | \$ | na | 80.00           |     |
| <b>TOTAL</b> |   |                                   | \$ |    | <b>3,285.75</b> |     |

|                    |    |                  |
|--------------------|----|------------------|
| <b>TOTAL PARTS</b> | \$ | <b>10,423.63</b> |
|--------------------|----|------------------|

**LABOUR**

|                                                                                                                           |    |          |          |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|----------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$ | 4,500.00 | 4401     |
| To transfer of Tailgate fittings, attachments and perform water seepage test.                                             | \$ | na       | 170.00 X |
| To transfer of Rear Door fittings, attachments and perform water seepage test.                                            | \$ | 5        | 170.00 X |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | 5        | 170.00 X |
| To check steering geometry and computer wheel alignment                                                                   | \$ | 4        | 220.00 X |
| To transfer of Rear Bumper fittings, attachments and perform water seepage test.                                          | \$ | 4        | 170.00 X |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | 5        | 170.00 X |
| To reinstall rear bumper parking sensor.                                                                                  | \$ | 4        | 170.00 X |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$ | 4,500.00 | 2001     |

**Trans-cab Auto Services Pte Ltd****AAD1908-039**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 5318K**

|                                                                                                 |           |                    |
|-------------------------------------------------------------------------------------------------|-----------|--------------------|
| To transfer of Rear Fender fittings, attachments and perform water seepage test.                | \$        | <i>nn</i> 170.00 X |
| To apply paint protection system (PPS) maintain and enhancement                                 | \$        | <i>nn</i> 380.00 X |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                 | \$        | <i>nn</i> 380.00 X |
| To transfer of rear windscreen glass to facilitate bodywork repair.                             | \$        | <i>nn</i> 170.00 X |
| To Rust-Proofing Of The Affected Areas.                                                         | \$        | <i>nn</i> 170.00 X |
| To apply paint protection system (PPS) maintain and enhancement                                 | \$        | <i>nn</i> 380.00 X |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. | \$        | <i>nn</i> 380.00 X |
| <b>TOTAL</b>                                                                                    | <b>\$</b> | <b>12,270.00</b>   |
| <b>Over All Total</b>                                                                           | <b>\$</b> | <b>22,693.63</b>   |

**(PART-BY-PART) Repair Days****15 DAYS***2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: