

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5302E**AAD1908-038***Not Authorized**Resumy B4 point*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

08 AUG 2019

SHD 5302E

JTDKB3FU203076719

TOYOTA

PRIUS

6.8.19

AXA

15/11/2018

PART**LIST**

1	1	REAR BUMPER	\$	SVC	458.60	X
2	1	REAR BUMPER RE-INFORCEMENT	\$	SVC	318.80	X
3	1	REAR BUMPER TOWING COVER	\$	SL	14.70	X
4	1	REAR BUMPER UNDER COVER (BLACK)	\$	Not Cont	552.60	✓
5	1	ANTENNA, ELECTRICAL KEY	\$	SL	61.40	}
6	1	REAR BUMPER SIDE RETAINER LH	\$	SL	112.70	
7	1	REAR BUMPER SIDE RETAINER RH	\$	SL	112.70	
8	1	REAR TAILGATE	\$	N	1,547.27	
9	1	REAR TAILGATE OUTER GARNISH	\$	SL	910.40	
10	1	COVER, REAR COMBINATION LAMP, RH	\$	SL	54.70	
11	1	COVER, REAR COMBINATION LAMP, LH	\$	SL	54.70	
12	1	GARNISH, BACK DOOR SIDE, LH	\$	SL	93.60	
13	1	GARNISH, BACK DOOR SIDE, RH	\$	SL	93.60	
14	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	SL	55.40	
15	1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	SL	55.40	
16	1	BOARD ASSY, BACK DOOR TRIM	\$	SL	254.40	
17	1	PANEL ASSY, BACK DOOR TRIM, UPPER	\$	SL	51.20	
18	1	REAR TAILGATE WEATHERSTRIP	\$	SL	365.20	
19	1	PANEL SUB-ASSY, BODY LOWER BACK (REAR END PANEL)	\$	N	641.50	}
20	1	TAILLAMP LOWER RH	\$	SL	548.40	
21	1	TAILLAMP UPPER RH	\$	SL	557.90	
22	1	REAR BUMPER SIDE RH	\$	SL	232.00	
23	1	REAR BUMPER SIDE LH	\$	SL	232.00	
24	1	TAILLAMP LOWER LH	\$	SL	548.40	
25	1	TAILLAMP UPPER LH	\$	SL	557.90	
26	1	REAR RH FENDER PANEL	\$	N	836.70	
27	1	REAR LH FENDER PANEL	\$	N	836.70	

Trans-cab Auto Services Pte Ltd**AAD1908-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5302E

28	1	LINER, REAR WHEEL HOUSE, LH	\$	138.10	}	X
29	1	LINER, REAR WHEEL HOUSE, RH	\$	138.10		
30	1	BOARD, BACK DOOR TRIM	\$	222.00		
31	1	PANEL ASSY, DECK TRIM SIDE, RH	\$	351.10		
32	1	PANEL ASSY, DECK TRIM SIDE, LH	\$	351.10		
33	1	COVER, FLOOR UNDER, NO.1	\$	172.60		
34	1	COVER, FLOOR UNDER, NO.2	\$	238.70		
35	1	COVER, REAR FLOOR	\$	226.80		
36	1	COVER, DECK TRIM, REAR	\$	125.00		
TOTAL			\$	12,122.37		
25%			\$	3,030.59		
			\$	9,091.78		

Special Nett

Special Net					
1	1SET	PARKING AID	\$	SL	700.00 X
2	1SET	REAR BUMPER CLIP	\$	na	22.00 ✓
3	2	REAR WINDSCREEN SEALANT	\$	na	80.00
4	1	WINDSCREEN MOULDING	\$	na	100.00
5	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00
6	1	REAR TAILGATE TOYOTA LOGO	\$	na	47.00
7	1	REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90
8	1	REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50
9	1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00
10	1	REAR TAILGATE STICKER '6555-3333'	\$	na	80.00
11	1	REAR BUMPER PROTECTOR	\$	na	100.00
12	1	REAR WHEEL RIM	\$	SL	1,570.55
13	1	REAR WHEEL RIM COVER	\$	SL	175.80
14	1	SPARE WHEEL RIM	\$	SL	1,570.55
15	1	SPARE WHEEL RIM COVER	\$	SL	175.80
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00
17	1SET	FENDER WHEELARCH REAR RH CLIP	\$	na	35.00
TOTAL			\$		4,978.10

TOTAL PARTS \$ 14,069.88**LABOUR**

Trans-cab Auto Services Pte Ltd**AAD1908-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5302E

To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$		4,500.00	<i>2201</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		4,500.00	<i>1501</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	<i>X</i>
To Rust-Proofing Of The Affected Areas.	\$	<i>nn</i>	170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	NN	170.00	<i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i>	220.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i>	380.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD1908-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5302E

Labour charge to mount and dismount vehicle on jig
bench, to facilitate repair.

\$ *nn* 380.00 X

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X**TOTAL** \$ **12,100.00****Over All Total** \$ **26,169.88****(PART-BY-PART) Repair Days****15 Days***11 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: