## AAD1908-040 Trans-cab Auto Services Pte Ltd Not Nothorn Resony B4 paint 8984.88 No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G **SHD 9554T SHD 9554T** Vehicle No.: 0 8 AUG 2019 JTDKB3FU703082323 Chassis No.: TOYOTA Vehicle Make: **PRIUS** Vehicle Model: 6.8.19 Date of Accident: Third Party Insurer: AIG 18/7/2019 Date of Registration: LIST PART n 509.10 \$ 1 FRONT BUMPER Ph 112.70 2 \$ FRONT BUMPER SIDE RETAINER LH Sh 3 1 FRONT BUMPER SUPPORT \$ 81.70 SL \$ 907.75 4 1 FRONT LED LAMP (LOWER) LH 2,909.04 \$ 5 1 FRONT HEADLAMP LH Sun 6 1 COMPUTER SUB-ASSY, HEADLAMP, LH NO.1 \$ 492.30 SL \$ 413.10 7 1 MOTOR, HEADLAMP LEVELING, LH n 8 \$ 963.80 1 FRONT FENDER LH SL 9 \$ 48.80 EXTENSION, FRONT FENDER, LH SL 98.30 10 \$ COVER SUB-ASSY, FRONT PILLAR, UPR LH Sh 200.70 11 LINER, FRONT FENDER, LH \$ na 86.50 12 FRONT FENDER EMBLEM LH \$ R \$ 50.90 13 SEAL, FENDER APRON MUDGUARD, LH Sz 14 1 PROTECTOR, FRONT FENDER SIDE PANEL, LH \$ 92.30 n 15 1 FRONT BONNET \$ 969.00 n 16 1 HINGE ASSY, HOOD, LH \$ 58.00 N 1,264.00 \$ 17 1 PANEL SUB-ASSY, FRONT DOOR, LH 18 1 LEFT SIDE VIEW MIRROR \$ 1,275.52 19 1 MOULDING ASSY, BODY ROCKER PANEL, LH \$ 583.30 \$ TOTAL 11,116.81 25% \$ 2,779.20 \$ 8,337.61 **Special Nett**

## 

AAD1908-040 Trans-cab Auto Services Pte Ltd No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330 CO./GST Reg. No. 201019626G **SHD 9554T** Na 66.00 X \$ 4 1 BUMPER CLIP FRT Nn 200.00 X \$ 5 1 FRONT NUMBER PLATE WITH MOULDING 5 350.00 X \$ 1 FRONT TYRE 195/65/15 6 Ma 80.00 6012 7 1 FRONT DOOR STICKER 'TRANS-CAB' **TOTAL** \$ 2,464.35 TOTAL PARTS \$ 10,801.96 **LABOUR** 6,000.00 2001 Putty And Spray Painting Of The Affected Portion. \$ Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust 6,000.00 6601 And Realign The Same \$ NN 170.00 X To Rust-Proofing Of The Affected Areas. \$ To transfer of Fender fittings, attachments and perform water seepage test. \$ 170.00 X To transfer of Front Bumper fittings, attachments and perform water seepage test. \$ 170.00 X To check steering geometry and computer wheel alignment \$ 4 220.00 X To apply paint protection system (PPS) maintain and enhancement 5 380.00 X \$ To transfer of Bonnet fittings, attachments and perform water seepage test. 5 170.00 X \$ To Check Electrical Lighting Concerned. L 170.00 X \$ To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair. 4 380.00 X \$

## **Trans-cab Auto Services Pte Ltd**

AAD1908-040

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666

Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9554T** 

(PART-BY-PART) Repair Days	20 days	
Over All Total	\$ 25,561.96	:
TOTAL	\$ 14,760.00	
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ 4 380.00	X
To transfer of tire, rim and on wheel balancing.	\$ ረ 170.00	X
To transfer of door fittings, attachments and perform water seepage test.	\$ ~~ 380.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: