

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com. Reg. No. 378091/00W

Our Ref: TP 2957/08/19

Your Ref:

Date: 2nd AUG 2019

MS CHEW YEN WEI ZOELY
750, BEDOK RESERVOIR RD, #04-03
SINGAPORE 479256

Repair sum \$ 3150

Estimate cost of repair to HONDA VEZEL 1.5X (A) S/Wagon - SKD 149 D

1 pc front bumper		D7	\$ 817.80	
8 pcs front bumper top clips	© \$ 3.90	nu	31.20	
8 pcs front bumper lower clips	© \$ 3.90	nu	31.20	
1 pc front bumper o/s side retainer		11	25.10	X
1 pc front bumper o/s side bracket clips		11	4.50	X
1 pc front bumper centre top airscoop grille	11	11	370.50	X
1 pc front bumper centre lower grille	11	11	93.60	X
1 pc front bumper reinforcement		DD	341.30	X
1 pc front bumper o/s fog lamp assy	11	11	224.30	X
1 pc front bumper o/s fog lamp garnish	11	11	35.10	X
1 pc front bumper lower sideskirt		11	191.10	X
8 pcs front bumper lower sideskirt clips	© \$ 3.90	11	31.20	X
1 pc front number plate & frame		11	60.00	X
1 pc front grille cover		11	240.80	X
1 pc front grille 'H' emblem		11	25.20	X
2 pcs front grille o/s & n/s moulding	© \$ 58.90	11	117.80	X
8 pcs front grille cover clips	© \$ 3.90	11	31.20	X
1 pc o/s head lamp assy (HID)		cm	1,728.70	X
1 pc o/s head lamp lower bracket		cm	49.00	X
			\$ 4,449.60	2999.2
	Less 20%		\$ 889.92	2399.36
			\$ 3,559.68	
1 set front bumper sensor		Sunk	200.00	20
To wiring check up & adjust headlight alignment.			40.00	20
To respray Tuff-Kote on all affected accident parts.		11	60.00	X
Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front support panel, front bonnet, front o/s fender & necessary parts, to weld, renew & align above parts.			900.00	400
To putty & respray painting on all affected accident parts.			1,100.00	500
			\$ 5,859.68	3519.36
			=====	3117.42

Dollars : Five thousand Eight Hundred Fifty Nine And Cents Sixty Eight Only.

LKK Auto Consultants hence notify the Repairer of the following:

- to display damaged part(s) during recovery
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No alterations/modifications to be made
Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

HUP MOTOR TRADING & SERVICE

.....
Acknowledged by Repairer
Signature: _____
Date: _____

not signed
nu
2/5/19
5/8/19
Repair sum \$ 3150
whp he. Atte...