

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd  
64 Cecil Street  
#04-00 IOB Building  
Singapore 049711

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 13 Aug 2019

**Preliminary Advice**

Vehicle No	: SKD149D	Accident Date	: 01/08/2019
Make	: HONDA VEZEL	Policy No.	: D19MPC0001286
Assignment Date	: 13/08/2019	Excess	: S\$0.00
Date of Inspection	: 5/8/2019	Est. Duration of Repair	: 4
Inspection At	: HUP MOTOR TRADING & SERVICE		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,859.68
Revised Amount	:S\$	3,150.00 (REPAIR SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,150.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	60,000.00
COE / PARF Rebate	:S\$	42,816.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,184.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :