



TeamWork Garage Pte Ltd

53 Ubi Avenue 1 #01-23/24 Spore 408934

Paya Ubi Industrial Park

Tel : 6844 2475

E-mail : claims@teamworkgarage.com

Register number : 201015366H

3RD PARTY CLAIM ESTIMATION

AIIG Singapore

78 Shenton Way

Singapore 079120

Vehicle number	SMK7117P
Make / Model	AUDI/A4
Chassis number	WAUZZZ8K2BA031168
Accident date	07 August 2019
Reference	1908-19

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT BUMPER	1902.10 de ✓
1	FRONT BUMPER INNER FRAME PAD	97.75 ?
2	FRONT BUMPER SIDE RETAINER	119.00 LH-ret ✓ RH-X
1	FRONT BUMPER REINFORCEMENT	741.75 ?
1	FRONT BUMPER TOW COVER	42.55 cost X
1	FRONT BUMPER NOZZLE MOTOR	195.50 ?
1	FRONT BUMPER NOZZLE COVER	47.10 de -
2	FRONT BUMPER REINFORCEMENT BRACKET	345.00 ?
1	FRONT LH BUMPER FOG LAMP COVER	104.65 one -
1	FRONT LH FOG LAMP	178.25 ?
1	FRONT GRILLE ASSY	483.00 ?
1	FRONT SUPPORT PANEL	908.50 ?
1	FRONT SUPPORT PANEL TOP GARNISH	97.75 X
1	FRONT LH HEADLAMP	1706.60 aw ✓
1	FRONT LH HEADLAMP BRACKET	63.25 ?
1	FRONT LH FENDER	644.00 b7 ✓
1	FRONT LH FENDER INNER SHIELD	140.00 ?
1	BONNET	1311.00 b7 ✓
1	BONNET LOCK	126.50 X
1	BONNET LATCH HOOK	115.00 X
1	AIR DCT	23.00 X
1	AIR CLEANER RESONATOR	494.50 X
		9886.75
	Less 5%	494.33
	Subtotal	9392.42
	Balance C/F	9392.42
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
	Balance B/F	9392.42
1 SET	FRONT BUMPER CLIP	40.00 3one ✓
1 SET	FRONT FENDER INNER TRIM CLIP	30.00 X

1 BOT	COOLANT		50.00 ?
		Subtotal	120.00
		Balance C/F	9512.42
S/No	<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
		Balance B/F	9512.42
1	CHECK FRONT WIRING AND LIGHTNING SYSTEM		60.00 30.
2	DIAGNOIS CHECK AND CLEAR FAULT CODE		500.00 200
3	REMOVE, REFIT RADIATOR AND TOP UP COOLANT		150.00 ? 100
4	REMOVE, REFIT CONDENSER AND TOP UP GAS		150.00 100 ?
5	PANEL BEATING ON AFFECTED AREAS	} non include support panel	900.00 600
6	SPRAY PAINTING ON AFFECTED AREAS		1000.00 700
7	APPLY ANTI RUST ON AFFECTED AREAS		150.00 40
8	REMOVE AND RENEW WRAPPING ON AFFECTED AREAS		1200.00 600
		Subtotal	4110.00
		Grand total	13622.42

Taughlin 97495749

wp'

13/8/19 24pm

Resurvey after repair

Taughlin e (Humbrook)

5 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: