



FALCON-AIR

SUNDAR NEWS AGENCY  
BLK 701 WEST COAST RD #05-318  
SINGAPORE 120701

Attention : Motor Claim Department  
Contact : 90294009

Estimate : ES003501

Date : 01/08/2019  
Vehicle Num. : GBE9446M  
Make/Model : TOYOTA HIACE  
Chassis/Eng# : KDH201-0192252  
Accident Date : 23/07/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAILGATE <i>Y- cut</i>		1,765.10
2.	1	TAILGATE LOCK <i>cut</i>		275.03
3.	1	TAILGATE LOGO <i>na</i>		75.80
4.	1	TAILGATE STICKER HI ACE <i>na</i>		48.50
5.	1	TAILGATE STICKER 1250KG <i>na</i>		44.20
6.	1	REAR BUMPER <i>de</i>		415.80
7.	1	REAR END PANEL <i>repair</i>		545.00
List TotalS\$ :				3,169.43
25.00% Discount S\$ :				792.36
				<u>2,377.07</u>
SPECIAL NETT ITEMS :				
1.	1	70 KM/HR STICKER <i>na</i>		10.00
2.	1	SEALANT <i>na</i>		45.00
Special Nett Total S\$ :				<u>55.00</u>
LABOUR :				
TO TRANSFER TAILGATE PARTS/MECHANISM				<del>50.00</del> <i>40</i>
TO REMOVE/REFIX REAR WINDSCREEN GLASS				<del>120.00</del> <i>100</i>

CONTINUE / ...

## FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

SUNDAR NEWS AGENCY  
BLK 701 WEST COAST RD #05-318  
SINGAPORE 120701

Attention : Motor Claim Department  
Contact : 90294009

Estimate : ES003501

Date : 01/08/2019  
Vehicle Num. : GBE9446M  
Make/Model : TOYOTA HIACE  
Chassis/Eng# : KDH201-0192252  
Accident Date : 23/07/2019  
Claim No. :  
Reference : TP NTUC VS AXA  
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER  
TO CUT OUT/REWELD RADIATOR SUPPORT PANEL, REPAIR FLOOR  
PANEL, REAR CHASSIS INCLUDES KNOCKING & REPLACEMENT  
OF PARTS

~~700.00~~ 500

~~550.00~~ 400

Labour Total S\$ :

1,420.00

*Rasul*  
*Hp 900 100 68*  
*4 days*  
*45*  
*21/08/19 @ 1350*  
*Revy after repair*

SingDollars : Three Thousand Eight Hundred Fifty-Two & Cents Seven Only

E. & O.E.

Total S\$ : 3,852.07



for FALCON AIR AUTO SERVICES PTE LTD

- LKK Auto Consultant, hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**FALCON-AIR AUTO SERVICES PTE LTD**

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg