

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52255**
Date Estimated : **07/08/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Maqroma Pte. Ltd.
71 Toh Guan Road East
#06-07 TCH Techcentre

Singapore 608598

- ACCOUNT -

303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH9709X	WBA1V72040V7252	24/11/2016	116d	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To make good rear bumper including to remove and install body parts in order to carry out painting job	850.00	0	850.00
To respray rear bumper	934.00	0	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00
Sundries.	40.00	0	40.00
# To supply rear number plate	83.00	0	83.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

[PASTE HERE]

OD	ADD PARTY	DATE	TIME
	Rasu/ LKK	8/10/19	3
FAX TO FAX NO			
FAX TO FAX NO			
FAX TO FAX NO			
CONFIRMED DATE			
PLEASE FINALISE BY			

Total Labour :	2,057.00
Total Parts :	
Total Repair Costs less Excess:	2,057.00
GST @7%:	143.99
Grand Total :	2,200.99

LOSS OF USE = \$80 X 3 DAYS

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52255**
Date Estimated : **07/08/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Maqroma Pte. Ltd.
71 Toh Guan Road East
#06-07 TCH Techcentre

Singapore 608598

- ACCOUNT - 303
MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH9709X	WBA1V72040V7252	24/11/2016	116d	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

# To supply rear number plate	83.00	0	83.00
-------------------------------	-------	---	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
[PASTE HERE]				

Total Labour :	83.00
Total Parts :	
Total Repair Costs less Excess:	83.00