

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52255**
Date Estimated : **07/08/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Maqroma Pte. Ltd.
71 Toh Guan Road East
#06-07 TCH Techcentre

Singapore 608598

- ACCOUNT - 303

MS First Capital Insurance Limited
6 Raffles Quay
#21-00
Singapore 048580

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLH9709X	WBA1V72040V7252	24/11/2016	116d	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
-------------	----------------------------	---------	------

# To supply rear number plate <i>sub</i>	83.00	0	83.00
--	-------	---	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

[PASTE HERE]

Total Labour :	83.00
Total Parts :	
Total Repair Costs less Excess:	83.00