

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: EQ	DATE	: 07/
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/F
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLV101J		
MODEL	: MERCEDES BENZ S350L		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 6-Aug-19
		TIME	: 15:25HRS
THIRD PARTY REQUESTOR / CONTACT :			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE
1	BOOTLID <i>Dented</i>	1	\$ 3,250.40
2	BOOTLID CENTRE EMBLEM <i>2 per</i>	1	\$ 90.00
3	BOOTLID "S350D" EMBLEM	1	\$ 120.00
4	BOOTLID CENTRE CHROME <i>New</i>	1	\$ 380.00
5	BOOTLID WEATHERSTRIP <i>New</i>	1	\$ 410.00
6	REAR BUMPER <i>Distorted</i>	1	\$ 2,450.80
7	REAR BUMPER LOWER SPOILER <i>Rehnd</i>	1	\$ 680.00
8	REAR BUMPER SIDE RTETAINER <i>2H New</i>	2	\$ 165.00
9	REAR BUMPER SIDE CHROME MOULDING RH <i>Dngd</i>	1	\$ 155.00
10	REAR BUMPER SIDE BEAM RH <i>could</i>	1	\$ 130.00
11	REAR BUMPER CENTRE BEAM <i>could</i>	1	\$ 230.00
12	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 831.00
13	REAR BUMPER TOW COVER <i>could</i>	1	\$ 80.00
14	REAR BUMPER REVERSE SENSOR <i>1 piece dngd</i>	2	\$ 360.00
15	REAR BUMPER REVERSE SENSOR RUBBER <i>New</i>	2	\$ 35.80
16	TAILLAMP RH <i>could</i>	1	\$ 988.00
17	TAILLAMP PANEL RH <i>Repair</i>	1	\$ 351.00

Rear Fender Air vent *could*

Rear Bumper under cover *could*

1 # ~~130~~ 85
1 # ~~380~~ 445

18	TAILALMP SIDE GARNISH RH <i>None</i>	1	\$ 90.00	+
19	END PANEL <i>Rygi</i>	1	\$ 1,406.00	x
20	END PANEL TOP GARNISH <i>None</i>	1	\$ 310.00	x

4326
8393.40

TOTAL PRICE

LESS 10%

SUB TOTAL PRICE

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT
1	REAR BUMPER CLIPS(SET) <i>None</i>	1	\$ 20.00
2	REAR BUMPER SIDE BEAM RIVETS RH (1 SET) <i>None</i>	1	\$ 30.00
3	TAILALMP CLIPS(SET) <i>None</i>	1	\$ 20.00

70

TOTAL

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	TO PANEL BEAT, WELD, CUT, KNOCK STRAIGHTEN, ADJUST GRAZE, JOIN	\$ 2,000.00	600
2	TO PUTTY, SPRAY PAINT, POLISH, WAX AFFECTED PARTS AND PANELS	\$ 2,000.00	800
3	TUFF COAT	\$ 120.00	x
4	WIRING AND BULB CHECKING	\$ 100.00	30
5	TO REMOVE AND REFIX REVERSE SENSOR	\$ 100.00	60
6	TO REMOVE AND REFIX BOOTLID MECHANISH	\$ 180.00	60
7	DIAGNOSE OF VEHICLE & RESET FAULT CODES	\$ 450.00	180

1700

TOTAL

\$4,950.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 11,836.42
TOTAL LABOUR COST : \$ 4,950.00
TOTAL REPAIR COST : \$ 16,786.42

Adrian Ling total: 10163.4
H/S 08/08/19. Y/S: 8.1K
65 Days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM
NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: