

AXA 19/08



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 3422 K

Parts	(a) Cost / List Price Items	\$	2,537.30
	Plus/Less 25%	\$	634.33
	Total of Cost / List	\$	1,902.98
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	1,902.98
Labour		\$	1,700.00
Total		\$	3,602.98

The above total will be subjected to 7% G.S.T.

Not Authorized
Repairing Bk repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Name of Surveyor : Kennerly
Company : LKK
Survey conducted on : 19/8/11 at _____

Remarks By Surveyor

- (a) The repair of this vehicle is authorized / is not authorized until further notice.
- (b) Recommended Days of Repair : 01 day(s)
- (c) Resurvey : Required / Not Required
- (d) Excess : \$ _____
- (e) Signature of surveyor : L Date: 19/8/11



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMA 3422 K**
Make & Model : **TOYOTA CH-R**
Chassis No : **ZYX102120407**

Submit By : **SERENCE**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>R</i>	1	\$946.75		<i>X</i>
2	Front bumper clip <i>nn</i>	10	\$40.00		<i>X</i>
3	Front bumper reinforcement <i>R</i>	1	\$487.30		<i>X</i>
4	Front bumper side retainer LH <i>Sn</i>	1	\$113.90		<i>X</i>
5	Front bumper side retainer RH <i>Sn</i>	1	\$113.90		<i>X</i>
6	Front bumper bracket LH <i>R</i>	1	\$185.30		<i>X</i>
7	Front bumper bracket RH <i>R</i>	1	\$185.30		<i>X</i>
8	Front bumper sponge <i>Sn</i>	1	\$89.80		<i>X</i>
9	Front bumper tow cover <i>Sn</i>	1	\$35.90		<i>X</i>
10	Fog lamp cover LH <i>Sn</i>	1	\$121.75		<i>X</i>
11	LH front fender protector <i>Redden</i>	1	\$172.40		<i>✓</i>
12	LH front fender protector clip <i>nn</i>	10	\$45.00		<i>✓</i>
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

