



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Gan Choon Shan Blk 467B Admiralty Drive #14-137 Singapore 752467 Contact No Mobile: 96611579	Cust No/Name	/Gan Choon Shan
	Reg No/Reg Date	SLT1611H / 20/10/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MJ5740729
	Engine No	G4FGHH679076
	Make/Model	KIA/CERATO K3 1.6 A SX SR
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	08/08/2019/ 15:49		442 / CocoLu	55711

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR AIRDAM, REPAIR REAR BUMPER				✓ 550.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR AIRDAM				630 1000.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				✓ 60.00
M SUNDRY Sundry				20 2.00
E PNT88000 REMOVE & INSTALL REAR AIRDAM				✓ 100.00
A 90000001 CONDUCT DIAGNOSTIC CHECK FOR THE CAR SYSTEM				✓ 200.00
M NEW K3 METAL STREAM MST	1.00	1177.00	00.00	Rx 1177.00

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SURVEYOR NAME: Tan Kah 9445741

SURVEYOR SIGNATURE: [Signature]

DATE: 2/9/19 3:30pm

REMARKS: Resurvey after repair
3 days
sure/khauto.com

Confirm & accepted by

	Nett	3,089.00
7% GST on	3089.00	216.23
Total Payable		3,305.23

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.