

not AAR
dbr account

Vehicle: SBQ8942R, MIT PAJERO
Year of Manufacturing: 1991

In Charge: Lucas

Tel:

Fax:

H/P:

1/53
3 dy.
11/8/19
Wright. AAR

NO. DESCRIPTION

QTY U/P

List Items

1 Front bumper	1
2 Front bumper retainer (LH) 11X	1
3 Front bumper retainer (RH) 11X	1
4 Front bumper lower garnish 11X	1
5 Fog lamp (LH) 11X	1
6 Head lamp (LH) 11X	1
7 Front fender (LH) 11X	1
8 Front fender arch garnish (LH) 11X	1
9 Front fender inner shield (LH) 11X	1
10 Rocker panel garnish (LH) 11X	1
11 Front wheel rim (LH) 11X	1
12 Front upper arm (LH) 11X	1
13 Front knuckle arm (LH) 11X	1
14 Front knuckle bearing (LH) 11X	1
15 Front lower arm (LH) 11X	1
16 Front absorber (LH) 11X	1
17 Front absorber top mounting (LH) 11X	1

Special Nett Items

18 Front bumper clip set 11X	1	50.00
19 Front fender inner shield clip set (LH) 11X	1	50.00
20 Front fender arch garnish clip set (LH) 11X	1	50.00
21 Front wheel tyre (LH) 11X	1	250.00
		400.00

Labour Items

22 To check wiring and lighting system	1	80.00	20
23 To supply under-coating & putty on parts replaced	1	80.00	11X
24 To perform anti rust treatment on affected areas	1	60.00	11X
25 To conduct all wheel alignment before & after	1	180.00	80
26 To R&R front LH undercarriage damaged parts	1	350.00	X
27 To press front LH knuckle bearing assy	1	100.00	X
28 To repair, replace & realign damaged areas	1	1000.00	400
29 To spray painting on affected areas	1	900.00	620
30 To conduct head lamp focus	1	100.00	20
31 Sundries	1	50.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2900.00