

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900245
Date: 08 Aug 2019
Veh Reg No: SMD1530E
Make/Model: TOYOTA VELLFIRE
2.5X CVT
Chasis No: AGH300190625
Reg. Date: 03/08/2018
Your Ref No: SMG5774B

Claim Type: Third Party
Accident Date: 07/08/2019
TP Veh Reg No: SMG5774B

Estimate Repair Cost to Vehicle No :SMD1530E

Quantity	Description	List Price	Amount
		SS	SS
	List Price		
1	1 PC BOOT LID <i>dent</i>	1,955.80 ✓	1,955.80
2	1 PC BOOT LID LOGO <i>new</i>	99.70 +	99.70
3	1 PC BOOT LID VELLFIRE EMBLEM <i>new</i>	88.40 ✓	88.40
4	1 PC BOOT LID LAMP LH <i>cracked</i>	629.70 ✓	629.70
5	1 PC BOOT LID LAMP RH <i>new</i>	629.70 +	629.70
6	1 PC BOOT LID LOCK <i>dent</i>	763.00 ✓	763.00
7	1 PC BOOT LID LOCK CHECKER <i>new</i>	69.90 +	69.90
8	1 PC BOOT LID OUTER OPENING SENSOR <i>new</i>	119.20 +	119.20
9	1 PC BOOT LID INNER CLOSING SENSOR <i>new</i>	489.70 ✓	489.70
10	1 PC BOOT LID RUBBER <i>new</i>	368.00 ✓	368.00
11	1 PC BOOT LID TRIM <i>cracked</i>	673.00 ✓	673.00
12	1 PC REAR WINDSCREEN RUBBER <i>new</i>	178.00 ✓	178.00
13	2 PCS BOOT LID SHOCK ABSORBERS <i>new</i>	661.20 +	661.20
14	1 PC REAR ANTENNA SENSOR <i>cracked</i>	169.90 ✓	169.90
15	1 PC REAR PANEL <i>dent</i>	690.90 ✓	690.90
16	1 PC REAR PANEL TRIM <i>dent</i>	172.30 ✓	172.30
17	1 PC REAR PANEL INNER SPONGE <i>new</i>	497.20 ✓	497.20
18	1 PC SPARE TYRE SPONGE LH <i>new</i>	289.70 +	289.70
19	1 PC REAR FENDER INNER TRIM LH <i>dent</i>	886.40 ✓	886.40
20	1 PC TAIL LAMP LOWER FENDER LH <i>dent</i>	388.90 ✓	388.90
21	1 PC TAIL LAMP LOWER FENDER RH <i>new</i>	388.90 ✓	388.90
22	1 PC REAR BUMPER <i>dent</i>	1,920.30 ✓	1,920.30
23	2 PCS REAR BUMPER BRACKETS <i>new</i>	296.40 ✓	296.40
24	2 PCS REAR BUMPER SIDE RETAINERS <i>new</i>	259.00 ✓	259.00
25	1 PC REAR BUMPER REFLECTOR - LH <i>cracked</i>	86.90 ✓	86.90
26	1 PC REAR BUMPER TOWING COVER <i>new</i>	28.80 +	28.80
27	4 PCS REVERSE SENSORS <i>3 pieces damaged</i>	1,513.60 ✓	1,513.60
		14,314.50	
Less 25%		3,578.63	10,735.94

10,087.80

7,565.85

1,875.80

1,144.80

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay @ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: **EST1900245**
Date: 08 Aug 2019
Veh Reg No: **SMD1530E**
Make/Model: TOYOTA VELLFIRE
2.5X CVT
Chasis No: AGH300190625
Reg. Date: 03/08/2018
Your Ref No: SMG5774B

Claim Type: Third Party
Accident Date: 07/08/2019
TP Veh Reg No: SMG5774B

Estimate Repair Cost to Vehicle No :SMD1530E

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
Special Net			
28	1 SET BOOTLID TRIM CLIPS <i>me</i>	50.00 30	
29	1 TUBE REAR WINDSCREEN SEALANT <i>3me</i>	60.00 40	
30	1 PC REAR WINDSCREEN SEAL <i>190</i>	60.00 40	
31	1 SET REAR PANEL TRIM CLIPS <i>me</i>	40.00 20	
32	1 SET REAR FENDER INNER TRIM CLIPS LH <i>me</i>	40.00 30	
33	1 SET REAR BUMPER CLIPS <i>me</i>	48.00 30	
		298.00	298.00
Labour			
34	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,500.00 1100	
35	1 TO SPRAY PAINTING	1,500.00 1200	
36	1 TO SPRAY UNDERSEAL	180.00 80	
37	1 TO REMOVE AND REFIT REAR WINDSCREEN GLASS	120.00 120	
38	1 TO REMOVE AND REFIT BOOT LID TRIM AND SEAT CUSHION	400.00 120	
39	1 TO CHECK WIRING	50.00 30	
40	1 TO REMOVE AND REPLACE REVERSE SENSOR <i>2170</i>	100.00 60	
41	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00 80	
		3,950.00	3,950.00

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 07/08/2019
TP Veh Reg No: SMG5774B

Estimate No: EST1900245
Date: 08 Aug 2019
Veh Reg No: SMD1530E
Make/Model: TOYOTA VELLFIRE
2.5X CVT
Chasis No: AGH300190625
Reg. Date: 03/08/2018
Your Ref No: SMG5774B

Estimate Repair Cost to Vehicle No :SMD1530E

Quantity	Description	List Price	Amount
		SS	SS
		Total	S\$ 14,983.94
		Add GST @ 7%	1,048.88
		Total Amount Payable	S\$ 16,032.82

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND THIRTY TWO AND CENTS EIGHTY TWO ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

AT

For Kang Car Repairers Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Supplementary: 394.19
Alvin
AUTHORISED SIGNATURE

total 10909.30
h/s 8.7k h/s 08/08/19

08 days

8.7k

08 days

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department

Estimate No: EST1900245
Date: 13 Aug 2019
Veh Reg No: SMD1530E
Make/Model: TOYOTA VELLFIRE
2.5X CVT
Chasis No: AGH300190625
Reg. Date: 03/08/2018
Your Ref No: SMG5774B

Claim Type: Third Party
Accident Date: 07/08/2019
TP Veh Reg No: SMG5774B

Estimate Repair Cost to Vehicle No :SMD1530E

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
	Supplementary Parts to Repair		
	List Price		
1	1 PC REAR LH LOWER GARNISH <i>rehd</i>	204.60	
		204.60	
	Less 25%	51.15	153.45
	Total		S\$ 153.45
	GST Amount		S\$ 10.74
	Total Amount Payable		<u>S\$ 164.19</u>

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 FAX: 68357416
ATTN: Motor Claim Department


Estimate No: **EST1900245**
Date: 20 Aug 2019
Veh Reg No: **SMD1530E**
Make/Model: TOYOTA VELLFIRE
2.5X CVT
Chasis No: AGH300190625
Reg. Date: 03/08/2018
Your Ref No: SMG5774B

Claim Type: Third Party
Accident Date: 07/08/2019
TP Veh Reg No: SMG5774B

Estimate Repair Cost to Vehicle No :SMD1530E

Quantity	Description	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
	Supplementary Parts to Repair		
	Labour		
1	1 TO RESET AND PROGRAM REAR AUTO BOOT LID	280.00 ¹⁵⁰	
2	1 TO TRANSFER REAR AND REFIX BOOT LID MECHANISM	380.00 ⁸⁰	
		660.00	660.00
		Total	S\$ 660.00
	230	GST Amount	S\$ 46.20
		Total Amount Payable	<u><u>S\$ 706.20</u></u>

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE