

Vic (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Wednesday, 15 April, 2020 4:09 PM
To: Adrian Ling (LKKAuto); Vic (LKKAuto); CS A Team; Admin A; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SMD6042P - TP AIG - SURVEYED 15 AUG 19
Attachments: PA09622019 - SMD 6042 P - AUDI Q2 1.0 TFSI S TRONIC - REAR - TP (AIG).xlsx; WhatsApp Image 2019-09-05 at 3.45.00 PM (resize).jpeg; WhatsApp Image 2019-09-05 at 3.44.59 PM (1) (resize).jpeg; WhatsApp Image 2019-09-05 at 3.44.59 PM (2) (resize).jpeg; WhatsApp Image 2019-09-05 at 3.44.56 PM (resize).jpeg; WhatsApp Image 2019-09-05 at 3.44.59 PM (resize).jpeg; WhatsApp Image 2019-09-06 at 4.08.38 PM (2) (resize).jpeg; WhatsApp Image 2019-09-06 at 2.16.18 PM (resize).jpeg; WhatsApp Image 2019-09-06 at 4.08.38 PM (resize).jpeg; WhatsApp Image 2019-09-06 at 10.09.05 AM (resize).jpeg; WhatsApp Image 2019-09-06 at 4.08.37 PM (1) (resize).jpeg; WhatsApp Image 2019-09-06 at 4.08.38 PM (1) (resize).jpeg; WhatsApp Image 2019-09-06 at 4.08.37 PM (resize).jpeg

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$9346.40 @5 days of repairs.

Your early closure is well appreciated.

Best regards - jb