

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0962/2019/NS
Date : 10-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLT 3056 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. CHOO JIN HUI CRAIG
Address : 495 Yio Chu Kang Road
233 SIMEI STREET 4
#02-17
Singapore 520233
Telephone : (HP)+65 97370008
Type of Claim : Third Party Claim
Policy No. : 1800102882-01
Vehicle No : **SMD 6042 P**
Model Code : Q2 1.0 TFSI S TRONIC
Model / Year : 28/8/2018
Engine No : CHZ 461168
Chassis No : WAUZZZGA4JA089581
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Aug-19
Place of Accident : TPE TOWARD PUNGGOL BEFORE EXIT 3A

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 6042 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper assy.	S/N \$ 480.00	✓
3	To renew rear windscreen.	S/N \$ 480.00	✓
4	To dismantle and renew bumper and rear lid. To inspect end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00	1000 ✓
5	To respray rear bumper and rear lid.	\$ 2,500.00	1100 ✓
6	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,140.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMD 6042 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>dehnd.</i>	\$ 1,074.00	✓
2	REAR BUMPER FIXING PARTS ?	\$ 70.00	?
3	REAR BUMPER SPOILER - LH <i>dehnd</i>	\$ 259.00	✓
4	REAR BUMPER TOWING COVER <i>NEP</i>	\$ 39.00	+
5	REAR LIGHT REFLECTOR - LH / RH <i>NEP</i>	2 \$ 54.00	+
6	REAR BUMPER CARRIER ?	\$ 501.00	?
7	REAR BUMPER HOLDING STRAP - LH / RH <i>NEP</i>	2 \$ 24.00	+
8	REAR BUMPER GUIDE SECTION - LH / RH <i>NEP</i>	2 \$ 98.00	+
9	REAR PARKING AID SENSOR - INNER	\$ 462.00	+
10	SEAL RING <i>NEP</i>	4 \$ 12.00	+
11	REAR LID <i>Dented.</i>	\$ 2,195.00	✓
12	REAR LID ATTACHMENT PARTS ?	\$ 109.00	?
13	LOCK STRIKER <i>NEP</i>	\$ 265.00	+
14	FLAP GASKET <i>NEP</i>	\$ 106.00	+
15	LID LOCK	\$ 227.00	+
16	BONNET LOCK COVER <i>NEP</i>	\$ 11.00	+
17	AUDI EMBLEM <i>NEP</i>	NEC \$ 113.00	✓
18	Q2 INSCRIPTION <i>NEP</i>	NEC \$ 87.00	✓
19	TFSI INSCRIPTION <i>NEP</i>	NEC \$ 87.00	✓
20	REAR WINDOW <i>NEP</i>	\$ 711.00	✓
21	PRIMER <i>NEP</i>	\$ 19.00	✓
22	REAR CROSS PANEL TRIM <i>NEP</i>	\$ 141.00	+
23	REAR NO. PLATE <i>NEP</i>	S/N \$ 40.00	+
24	REAR WINDSCREEN SEALANT <i>NEP</i>	S/N \$ 200.00	✓
25	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 7,204.00	
TOTAL LABOUR CHARGES		: \$ 6,140.00	
GRAND TOTAL		: \$ 13,344.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 15/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days.

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant