

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0962/2019/NS
Date : 10-Aug-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SLT 3056 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : MR. CHOO JIN HUI CRAIG
Address : 495 Yio Chu Kang Road
233 SIMEI STREET 4
#02-17
Singapore 520233
Telephone : (HP)+65 97370008
Type of Claim : Third Party Claim
Policy No. : 1800102882-01
Vehicle No : **SMD 6042 P**
Model Code : Q2 1.0 TFSI S TRONIC
Model / Year : 28/8/2018
Engine No : CHZ 461168
Chassis No : WAUZZZGA4JA089581
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 7-Aug-19
Place of Accident : TPE TOWARD PUNGGOL BEFORE EXIT 3A

P/P = \$9,346.40

5 REPAIR DAYS

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMD 6042 P

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00 ✓	
2	To remove and transfer rear lid's convenience lock system, wire harness for tail lights and rear wiper Assy.	S/N \$ 480.00 ✓	
3	To renew rear windscreen.	S/N \$ 480.00 ✓	
4	To dismantle and renew bumper and rear lid. To inspect end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 2,400.00 1000	
5	To respray rear bumper and rear lid.	\$ 2,500.00 1100	
6	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 6,140.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMD 6042 P**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Defend.</i>	\$ 1,074.00 ✓	859.20
2	REAR BUMPER FIXING PARTS <i>Not New</i>	\$ 70.00 ✗	
3	REAR BUMPER SPOILER - LH <i>Defend</i>	\$ 259.00 ✓	207.20
4	REAR BUMPER TOWING COVER <i>Not New</i>	\$ 39.00 ✗	
5	REAR LIGHT REFLECTOR - LH / RH <i>Not New</i>	2 \$ 54.00 ✗	
6	REAR BUMPER CARRIER <i>Not New</i>	\$ 501.00 ✗	
7	REAR BUMPER HOLDING STRAP - LH / RH <i>Not New</i>	2 \$ 24.00 ✗	
8	REAR BUMPER GUIDE SECTION - LH / RH <i>Not New</i>	2 \$ 98.00 ✗	
9	REAR PARKING AID SENSOR - INNER	\$ 462.00 ✗	
10	SEAL RING <i>Not New</i>	4 \$ 12.00 ✗	
11	REAR LID <i>Dented.</i>	\$ 2,195.00 ✓	1,756.00
12	REAR LID ATTACHMENT PARTS <i>Not New</i>	\$ 109.00 ✗	
13	LOCK STRIKER <i>Not New</i>	\$ 265.00 ✗	
14	FLAP GASKET <i>Not New</i>	\$ 106.00 ✗	
15	LID LOCK	\$ 227.00 ✗	
16	BONNET LOCK COVER <i>Not New</i>	\$ 11.00 ✗	
17	AUDI EMBLEM <i>Not New</i>	NEC \$ 113.00 ✓	90.40
18	Q2 INSCRIPTION <i>Not New</i>	NEC \$ 87.00 ✓	69.60
19	TFSI INSCRIPTION <i>Not New</i>	NEC \$ 87.00 ✓	69.60
20	REAR WINDOW <i>Not New</i>	\$ 711.00 ✓	568.80
21	PRIMER <i>Not New</i>	\$ 19.00 ✓	14.80
22	REAR CROSS PANEL TRIM <i>Not New</i>	\$ 141.00 ✗	
23	REAR NO. PLATE <i>Not New</i>	S/N \$ 40.00 ✗	
24	REAR WINDSCREEN SEALANT <i>Not New</i>	S/N \$ 200.00 ✓	
25	SUNDRIES <i>Not New</i>	\$ 300.00 ✗	
TOTAL SPARE PARTS		: \$ 7,204.00	
TOTAL LABOUR CHARGES		: \$ 6,140.00	
GRAND TOTAL		: \$ 13,344.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 15/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 days.
H.S.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0962/2019/NS 5-Sep-19 Glory Tan 1 of 1 SMD 6042 P Q2 1.0 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
Parts			
1	Rear wheel arch trim cover RHS <i>} New</i>	\$ 156.00	✓ 124.40
2	Rear wheel arch trim cover LHS	\$ 156.00	✓ 124.40
		\$ 312.00	
Labours			
1	To repair end panelling.	\$ 1,200.00 <i>500</i>	
2	To respray end panelling.	\$ 1,200.00 <i>550</i>	
3	To install rear windscreen solar film. S/N	\$ 400.00	✓
4.	Owner's paint coating see invoice attached	280.00	✓
Labour total		\$ 2,800.00	
Parts total		\$ 312.00	
GRAND TOTAL		\$ 3,112.00	

For Premium Automobiles Pte Ltd

Adrian Ling
HL

Authorised Signature