## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06, Singapore Land Tower

Singapore 048623

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: CHAN SHU HUI AGNES Date: 19 Aug 2019

# **Preliminary Advice**

Insured Vehicle No : SKM3336M

TP Vehicle No : SLH3343G **Accident Date** : 05/08/2019 Make : SUBARU FORESTER Assignment Date : 14/08/2019 : 16/08/2019 Est. Duration of Repair Date of Inspection : 2 days

Inspection At : My Car Consultant - Ubi (HQ)

53 Paya Ubi Industrial Park, #01-33

Singapore 408934

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,172.80
Revised Amount	:S\$	1,009.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,009.60

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$ Margin for Repair :S\$

### Remarks

(	)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments: TP: WP