

22/03/2001

ACS REC BY:

REF: CS/MSG 19014090/TISf3n2 Special Instruction:

Surveyor: Taufik

ASSIGNMENT (Office)

From (Person): Irm Tan Gnt Jg of MS19 Date/Time: 13.8.19 17.19pm

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKS 383P Insured: SLC 2540L

at Workshop m/s Performa motor Tel: 6319 0174

of 303 Alexandra Road

Policy No: 2911 4954 APO Claim No: 599324

Sum insured: Excess:

Make of Veh: D.O.A 6.7.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 14.8.19 @ 11.11am Person Contacted: Caroline Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKS 383P - X
	SLC 2540L - X
15/08/19 @ 16:53pm	revised ZA to Irm Tan via mmm,

Ass. Fee, Bt. **Taujikh**

MSIG

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT
In thiron

Veh No: **SKS 383P** Yr Regn: **2015, Feb.**
 Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**
 Truck / Trailer or _____
 Make: **BMW 730Li** c.c **2996**
 Colour: **Gold** A/C: **Insured / Std / NI / NA**
 Sp. Reading: **51638** T/Radio: **Insured / Std / NI / NA**
 Eng/No: _____
 C/No: **WISAYE 22060D 22/206**
 Gen. Cond: **Good / Fair / Poor / Burnt**
 Steering: **Inorder / Jammed / Leaked / Burnt** or
 Brake: **Inorder / Jammed / Leaked / Burnt** or
 Modi: **Nil / S/Rim / STD A/Rim** or
 Tyre Size: F: **245/50R18**
 R: **1 -**
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front **6** mm Rear **6** mm
 R/Bal. **6** mm L/Bal. **6** mm
 D.O.A. _____ D.O.I. **14/8/19 12pm**
 Survey held at **PML**
 Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop** or
Rear o/s
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/09/19	Confirmed I/P \$ 3,885.45 @ 3 days with Tautik (\$ 376.70 Red - 13%) RECEIVED 16 SEP 2019 <i>16/9/2019</i>

Date/Time, File Pass by: **16/09/19**
 1) **Taujikh**
 Date/Time, File Return to: _____
 2) _____
 Report Format: _____
 Prop. Amount: **3,885.45 p/p**

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **3**
 Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Insp (\$)
☐ Other (\$)

Survey Fee: **150**
 Transportation: **11**
 Other: _____
 Total: **161**

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 15 Aug 2019

Preliminary Advice

Insured Vehicle No	: SLC2540L	Accident Date	: 06/07/2019
TP Vehicle No	: SKS383P	Assignment Date	: 13/08/2019
Make	: BMW 730LI	Est. Duration of Repair	: 3 days
Date of Inspection	: 14/08/2019		
Inspection At	: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,655.70
Revised Amount	:S\$	3,699.00
Check Items (Estimated)	:S\$	373.70
Total	:S\$	4,072.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jul 2019		13 Aug 2019 17:19 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS		[Created by insurer]																						
Insured:	ARUN BHARADWAJ, ID: S2718419G																							
Main Claimant:	DR NG SHWU YONG, ID: S2507486F																							
Vehicle Reg. No.:	SKS383P	Date of Loss:	06/07/2019 00:00 - :59 [52 Months and 26 Days From LTA Reg Date (Mon Yr)]																					
Claim Type:	TP / 599324	Policy/Cover Note No.:	29114954APO Coverage: 22/01/2019 - 21/01/2020																					
Vehicle Reg. No. (Insured):	SLC2540L	Policy No. (Claimant):																						
		Excess:																						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174																							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 14/08/2019]																							
Adj Asg. Remarks:	On WP. Car in on 14/08/2019 10AM to 12PM Please contact us ASAP if you cannot attend this assignment. Liab: dispute (NR) Contact: Caroline @ 6319 0174																							
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail																						
There are no mail for this case.																								
<div> <div> <div>ALL ASSOCIATED TASKS</div> <div> View All Search Tasks Create New Task Complete </div> </div> <table border="1"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Re: FINAL REPORT / SKS383P / DS CLAIM / MSIG Claim no.: 599324/IT

Shirley Hiew (LKK Auto)

Mon 16/9/2019 4:09 PM

To: Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Dear Jing Xuan,

Finalize amount confirmed.

Final invoice and all supporting documents sent over to MSIG Insurance (Singapore) Pte. Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Toh Jing Xuan <toh.jing.xuan@simedarby.com.sg>

Sent: Friday, 13 September 2019 4:10 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: FINAL REPORT / SKS383P / DS CLAIM / MSIG Claim no.: 599324/IT

Dear Taufikh,

We refer to above matter and attachment Final Report.

Kindly confirm quantum for COR:

Total Labour : \$2,164.00

Total Parts : \$1,721.45

Total Labour and Parts : \$3,885.45

Repair work days : 3 days.

Thank you.

Best regard,

Toh Jing Xuan (Ms)

PML - Body and Paint

DID: 63190122

Fax: 64743229

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views

and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/07/2019 13:27
Date Of Accident	06/07/2019 12:45
Exact Location Of Accident	TANJONG KATONG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKS383P
Insured/Policyholder	
Name Of Registered Owner	DR NG SHWU YONG
NRIC No	S2507486F
Email Address	ENSY777@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92970733
Alternative Phone No	OTHERS-92970733

Vehicle Particulars

Manufacturer	BMW
Model	730LIA
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100402633-04
Cover Note Number	

Driver

Name of Driver	DR NG SHWU YONG
NRIC No	S2507486F
Date Of Birth	19/10/1955
Occupation	INDOOR
Date Of Driving Pass	06/04/1979
Driving Experience	40 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-92970733
Fax Number	
Contact Number	OTHERS-92970733
EEmail Address	ENSY777@GMAIL.COM

Address	358 TANJONG KATONG ROAD
Postcode	437120
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC2540L
Vehicle Make/Model/Colour	BMW 116D PLATINUM SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MR ARUN
NRIC/Passport Number	
Contact Number	94503584
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	FRONT
No. Of Passenger (Including Driver)	


SKETCH PLAN


IMPORTANT NOTICE



1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:


- rental car

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

14.07.19 @ 10am
Survey & repair
XX Survey before 12pm or
arrange for video survey



GST REG. NO : M2 - 0020081 - X

ESTIMATE

09 JUL 2019

Estimate No. : b1 51883
Date Estimated : 09/07/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -

Ng Shwu Yong
358 TANJONG KATONG ROAD

Singapore 437120

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO. CHASSIS NO. REGN. DATE
SKS383P DZ21206 10/02/2015

- Link Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - MODEL damaged part(s) during resurvey
 - 730LiA
 - Resurvey are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis

MILEAGE
0

DESCRIPTION

Replace rear bumper and attachments.

Painting rear bumper.

To check electrical wiring systems and lightings at the rear section for proper function.

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

Sundries.

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VALUE
850 1,275.00

934 1,038.00

150 177.00

150 177.00

new 80.00

Total Labour 1: 2,747.00

DESCRIPTION

SET OF MOUNTS FOR PDC SENSOR RR
RR BUMPER RH MOUNT
RR BUMPER PANEL PRIMED
RR BUMPER RH REFLECTOR

QTY PRIC
1 58.60
1 198.30
1 1,615.00
1 36.80

VALUE
nrv 58.60
unx 198.30
de 1,615.00
nn? 36.80

Total Parts : 1,908.70

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Claim No.

Date & Time 14/8/19 12:10 Excess \$5

Surveyor's Name Taufik Sign

Surveyor's Tel 97465344 Authorised Yes / No

Authorised Date WP Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail Taufik@thurasamy.com

Labour 1 : 2,747.00
Parts : 1,908.70
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 325.90

Grand Total : 4,981.60

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4762.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 51883**
Date Estimated : **09/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ng Shwu Yong
358 TANJONG KATONG ROAD

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 437120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS383P	DZ21206	10/02/2015	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER PROTECTIVE RUBBER STRIP C	106.45	1.00	<i>nil</i>	106.45 (A)

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	106.45
Total Labour & Parts :	106.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 51883**
Date Estimated : **09/07/2019**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Ng Shwu Yong
358 TANJONG KATONG ROAD

Singapore 437120

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKS383P	DZ21206	10/02/2015	730LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments including remove attachments to facilitate repairs.	850.00		850.00
To respray rear bumper.	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To remove old PDC assembly and reconnect to new bumper including conduct checks for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER PROTECTIVE RUBBER STRIP C	106.45	1.00		106.45
RR BUMPER PANEL PRIMED	1,615.00	1.00		1,615.00

SUPPLEMENTARY ITEMS

Total Labour :	2,164.00
Total Parts :	1,721.45
Total Labour & Parts :	3,885.45
Deduction for Excess :	
Total Repair Costs less Excess:	3,885.45
GST @7%:	271.98
Grand Total :	4,157.43

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19014090/T1SF3N2

Date: 17/09/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29114954APO
Claimant Vehicle No :	SKS383P	Insured Vehicle No :	SLC2540L
Date of Loss:	06/07/2019	Nature of Claim:	TP
		Claim No:	599324

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS383P		
Make & Model:	BMW 730LI, 3.0 D/AB 4DR SR LED DSC NAV HUD (A)	Engine No:	10568886N52B30AF
Reg. Date:	10/02/2015 (Man. Year: 2014)	Chassis No:	WBAYE22060DZ21206
Colour:	Gold	Odometer:	51638 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50R18	Rear Tyre Size:	245/50R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,095.15	1,801.45	293.70	14.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,084.00	583.00	21.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,762.15	3,885.45	876.70	18.41
+ GST 7.00/7.00% (\$\$)	333.35	271.98	61.37	18.41
Nett Amount (\$\$)	5,095.50	4,157.43	938.07	18.41

INSPECTION

Date of Assignment:	13/08/2019	
Date Inspected:	14/08/2019	Inspected At: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2019)
Parts:	143	BMW 730LI 3.0 D/AB 4DR SR LED DSC NAV HUD (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS383P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET OF MOUNTS FOR PDC SENSOR RR	Not Necessary	58.60 FS	*- FS
2	1		*RR BUMPER RH MOUNT	Not Necessary	198.30 FS	*- FS
3	1		*RR BUMPER PANEL PRIMED	Deformed	1,615.00 FS	*1,615.00 FS
4	1		*RR BUMPER RH REFLECTOR	Not Necessary	36.80 FS	*- FS
5	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
6	1		*RR BUMPER PROTECTIVE RUBBER STRIP C	Necessary	106.45 FS	*106.45 FS

F=Franchise part. S=SpcNetl.

Total Parts (S\$) 2,095.15 1,801.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE REAR BUMPER AND ATTACHMENTS	New	1,275.00	850.00
2	PAINTING REAR BUMPER	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,667.00	2,084.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >