

INS. CASE OWNER:

CC 4, A6190 14099, Kea39

LKK:
IDAC:

Surveyor:

KSC

DOI:

ASSIGNMENT

14/8/19

Date / Time:

13/8/19

Registered in Merimen:

14/8/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKN925J

Name of Insured:

U ANA

Insured Tel No.:

HP:

Excess Sec II : \$5

D.O.A.:

2/8/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SME 7684T



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hae



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	23/8/19
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup):	☐
	After call ltr to OI:	☒
	Authorisation To Act:	☒
	Release Voucher:	☒
	Final Repair Bill:	☒
	Car Rental Invoice:	☐
	Towing Invoice:	☐
	LTA / GIA:	☒
	Medical Bill:	☐
	PIR:	☐
	Mandate/Reject Instruction:	☒
	LOD:	☒
	Payment Breakdown Form:	☐
	Post-Repair Photos:	☐
	Others:	☐

PRELIMINARY ADVICE		Date/Time:	Sent By:
FINALIZATION		Date/Time:	Confirm with:
Repair Cost:	PIP	\$53,460.32	(5 days) Reduction: 25 %
FINAL SETTLEMENT		Date/Time: 26.03.20	Confirm with: JUNE
Final Liability:	% 100	(Agreed / Assessed) BOLA S/N No.:	21
Repair Cost:	0.67	\$53,762.54	OLD REQ ENDED TP
Loss of Rental (LOR):	\$5 -	(days)	
Loss of Use (LOU):	\$5 300.00	(560 x 5 days)	
Loss of Income (LOI):	\$5 -	(5 x days)	
LOR only ☐	LOU only ☒	LOR + LOU ☐	LOR + LOI ☐ [Tick only one]
GIA/LTA Search	\$5 8.00		
Medical:	\$5 -		
Disbursement:	\$5 -	(e.g. Tow/ Independent)	
Legal Cost	\$5 -		
Total:	\$5 4,010.54	Global Sum \$5:	
FINAL PAYMENT		Date/Time: 26.03.20	Confirm with: JUNE
Payee 1:	\$5 4,010.54	Name 1:	CHENG HAE MOTOR PTE LTD
Payee 2: (Strike if N.A.)	\$5	Name 2:	
Payee 3: (Strike if N.A.)	\$5	Name 3:	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chm@chingnet.com.sg
GST: 201001158E RCB NO: 201001158E

SMK7684T

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1991867/YISHUN

Date: 14 Aug 2019

Policy No: 5108946484

Veh Reg No: SMK7684T

Make/Model: HONDA VEZEL 1.5X CVT

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 03/08/2019

TP Veh Reg No: SKN9215J

Chassis No: RU11314171

Engine No: L15B5564182

Reg. Date: 24/04/2019

Not Authorised

Memory B4 paint

- 5 days

83460.32

Estimate Repair Cost to Vehicle No :SMK7684T

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
List Price			\$	\$
1 REAR BUMPER	850.10	1 PC	850.10	✓
2 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
4 TAILGATE EMBLEM (VEZEL)	43.90	1 PC	43.90	✓
5 TAILGATE INNER LOCK	131.80	1 PC	131.80	✓
6 TAILGATE INNER RUBBER	98.50	1 PC	98.50	✓
7 TAILGATE INNER BOARD	153.40	1 PC	153.40	✓
8 REAR PANEL	411.90	1 PC	411.90	✓
9 REAR PANEL INNER TOP GARNISH	92.30	1 PC	92.30	✓
10 REAR TOOL BOX	126.90	1 PC	126.90	✓
11 REAR WINDSCREEN GLASS SEAL	151.80	1 PC	151.80	✓
			3,184.90	
		Less 20%	636.98	2,547.92
Special Net				
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
15 PANEL BEATING	800.00	1 LA	800.00	✓
16 PUTTY & RESPRAY ON TAILGATE, REAR PANEL, REAR BUMPER, REAR SPARE TYRE COMPARTMENT	800.00	1 LA	800.00	✓
17 RUSTPROOFING	60.00	1 LA	60.00	✓
18 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			1,830.00	1,830.00
			Total	\$ 4,617.92
			Add GST @ 7%	323.25
			Total Amount Payable	\$ 4,941.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

P: 2,400.40

- 20%

= 1,920.32

SM: 240.40

L: 1,300.00

T: 3,460.32

K

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	372B
Vehicle Details	
Vehicle No.:	SMK7684T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	08 Aug 2019
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	L15B5564182
Chassis No.:	RU11314171
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$23,538.00
Original Registration Date:	24 Apr 2019
First Registration Date:	24 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$14,954.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Apr 2029
PARF Rebate Amount:	\$11,215.00
Intended COE Rebate Details	
COE Expiry Date:	23 Apr 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,199.00
COE Rebate Amount:	\$26,559.00
Total Rebate Amount:	\$37,774.00

The information contained herein is correct as at 08 Aug 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chinotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SMK7684T
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

Estimate No: ES1991867/YISHUN
Date: 14 Aug 2019
Policy No: 5108946484
Veh Reg No: SMK7684T
Make/Model: HONDA VEZEL 1.5X CVT

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 03/08/2019
TP Veh Reg No: SKN9215J

Chassis No: RU11314171
Engine No: L15B5564182
Reg. Date: 24/04/2019

Estimate Repair Cost to Vehicle No :SMK7684T

PAGE:1/1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	850.10	1 PC	850.10	✓
2 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
3 REAR TAILGATE	1,100.90	1 PC	1,100.90	✓
4 TAILGATE EMBLEM (VEZEL)	43.90	1 PC	43.90	✓
5 TAILGATE INNER LOCK	131.80	1 PC	131.80	?
6 TAILGATE INNER RUBBER	98.50	1 PC	98.50	?
7 TAILGATE INNER BOARD	153.40	1 PC	153.40	?
8 REAR PANEL	411.90	1 PC	411.90	?
9 REAR PANEL INNER TOP GARNISH	92.30	1 PC	92.30	?
10 REAR TOOL BOX	126.90	1 PC	126.90	?
11 REAR WINDSCREEN GLASS SEAL	151.80	1 PC	151.80	✓
			3,184.90	
		Less 20%	636.98	2,547.92
Special Net				
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	?
			240.00	240.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
15 PANEL BEATING	800.00	1 LA	800.00	?
16 PUTTY & RESPRAY ON TAILGATE,REAR PANEL,REAR BUMPER,REAR SPARE TYRE COMPARTMENT	800.00	1 LA	800.00	400-600
17 RUSTPROOFING	60.00	1 LA	60.00	300
18 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	50.00	1 LA	50.00	✓
			1,830.00	1,830.00
		Total	SS 4,617.92	
		Add GST @ 7%	323.25	
		Total Amount Payable	SS 4,941.17	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

PRE-REPAIR INSPECTION REQUEST – SMK7684T vs SKN9215J (OI) on D.O.A.: 03/08/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni
Sent: 8/13/2019 1:37:21 PM
Attachments:  2684.pdf

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd**.

Claim no : 7856717695SG003
Case Owner : Lee Ming Yao

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Hor Yin Rul (Viviane)
AIG
FNOL Adjuster I
Singapore FNOL | Claims Operations – Auto

Yinnul.Hor@aig.com | www.aig.sg

P: Juna
7:23pm
V. out
E. ✓

From: chmotor@singnet.com.sg [mailto:chmotor@singnet.com.sg]
Sent: Tuesday, August 13, 2019 1:18 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin; chmotor@singnet.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN9215J AND SMK7684T ON 03/08/2019

Dear Sir,

Our selection as below :-

Kenneth Kong LKK Auto Consultants Pte Ltd
Pls assist to arrange for survey asap.

Thanks

Rgds

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

From: Hor, Yinnul
Sent: Tue, 13 Aug 2019 02:09:58 +0000
To: chmotor@singnet.com.sg
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Parthiban, Theerthan; Subramaniam, Divyashni; Tong, Wahxin
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKN9215J AND SMK7684T ON 03/08/2019

Without Prejudice

Your Reference : SMK7684T
Our Reference : 7856717695SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd

Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Goo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Singapore FNOL | Claims Operations – Auto

Yinul.Hor@aig.com | www.aig.sg

From: Cheng Hoe Motor Pte Ltd (Yishun-June) (<mailto:chmotor@singnet.com.sg>)

Sent: Thursday, August 08, 2019 5:24 AM

To: imran.ishak@aig.com; Chin, Lee-Ying; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina

Subject: [EXTERNAL] Repair Survey (Single Joint Expert) - SMK7684T

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

OUR CLIENT – SMK7684T

DOA - 3/8/19@11.10am

YOU

R INSURED : SKN9215J

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel :67556142

Fax : 67557719

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Asher Sng (LKKAuto)

From: Asher Sng (LKKAuto)
Sent: Friday, 23 August 2019 12:15 PM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Subject: Accident Involving SMK 7684T & SKN 9215J on 03/08/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Your Ref: SMK 7684T
Our Ref: CC4/AIG19014099/Kea3

Dear Sir/Madam,

Accident Involving SMK 7684T & SKN 9215J on 03/08/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To : AIG Asia Pacific Insurance Pte. Ltd.
Attn : Lee, Ming-Yao

Your Ref : 7856717695SG
Our Ref : CC4/AIG19014099/EA3
Date : 21 Feb 2020

"WITHOUT PREJUDICE"**ACCIDENT INVOLVING SKN9215J & SMK7684T ON 03/08/2019**

Refer to the above accident.

The accident occurred when insured rear ended third party vehicle. We have clarified with the OI on the nature of the accident and he/she is aware that his/her NCD would be affected.

On behalf of AIG Asia Pacific Insurance Pte. Ltd., we have **successfully / not successfully** carried out **TP Express Settlement** between your insured (vehicle no. SKN9215J) and third party claimant (vehicle no. SMK7684T).

Summary of offer made to workshop Cheng Hoe Motor Pte Ltd is as follows :

	Claimed	Revised
Cost of Repairs (w/GST)	\$ 4,941.17	\$ 3,702.54
Loss of Use (5days)		\$ 300.00 (5days x \$60)
LTA Seach Fee (Via Law Firm)		\$ 8.00
Amount of claim at Liability 100%		<u>\$ 4,010.54</u>

Our surveyor recommended 5days repair.

Enclose herewith the relevant supporting documents for your perusal.

For your approval please.

Regards,
Asher Sng Rong Yi
LKK Auto Consultants Pte Ltd

Print Received Message

This mail is associated with :

***SMK7684T (7856717695SG)**
[SKN9215J]
TP
HO WAI LIT
Aug 3 2019 11:00AM
[LI ANQI]
Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 26/03/2020 10:13 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4010.54) - SMK7684T - Claim Handler: Lee, Ming-Yao

Approved:4010.54:Hi, Please ensure all documents are ready. Also LTA search to be \$8 or \$7+gst?

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Aug 2019 Edit Reg		13 Aug 2019 00:00 Edit Adj Rpt	S\$3,460.32 Edit Estimates	S\$3,460.32 View Rpt		Pending for Survey Report Cancel Case

MainReferenceClaim DetailsDocumentsShow All

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LI ANQI, ID: S9108231D, Tel: +6599999999		
Main Claimant:	HO WAI LIT, ID: S7614372B		
Vehicle Reg. No.:	SMK7684T	Date of Loss:	03/08/2019 11:00 - :59 [3 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 785671769SSG	Policy/Cover Note No.:	2100418359 (Comprehensive)
Vehicle Reg. No. (Insured):	SKN9215J	Policy No. (Claimant):	5108946484
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 23/08/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

- AIG_SG_EXPRESS (26/03/2020): Alert - Adj Mandate Approved (S\$4010.54) - SMK7684T - Claim Handler: Lee, Ming-Y...

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMK7684T (7856717695SG)
[SKN9215J]
TP
HO WAI LIT
Aug 3 2019 11:00AM
[LI ANQI]
Cheng Hoe Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View View in Browser		
Letters/Correspondences														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	(Draft)	Third Party Express Settlement – Payment Breakdown											1	Edit			
Assessment Reports														1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	21/02/20 15:19	Adjuster Immediate Advice											1	Load HTML			
Photos/Images														3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	21/02/20 15:16	General View											1	Load JPG	☒		
2	21/02/20 15:16	General View											1	Load JPG	☒		
3	21/02/20 15:16	General View											1	Load JPG	☒		
4	21/02/20 15:16	General View											1	Load JPG	☒		
5	21/02/20 15:16	General View											1	Load JPG	☒		
6	21/02/20 15:16	General View											1	Load JPG	☒		
7	21/02/20 15:16	General View											1	Load JPG	☒		
8	21/02/20 15:16	General View											1	Load JPG	☒		
9	21/02/20 15:16	General View											1	Load JPG	☒		
10	21/02/20 15:16	General View											1	Load JPG	☒		
11	21/02/20 15:16	General View											1	Load JPG	☒		
12	21/02/20 15:16	General View											1	Load JPG	☒		
13	21/02/20 15:16	General View											1	Load JPG	☒		
14	21/02/20 15:16	General View											1	Load JPG	☒		
15	21/02/20 15:16	Odometer Reading											1	Load JPG	☒		
16	21/02/20 15:16	Odometer Reading											1	Load JPG	☒		
17	21/02/20 15:16	Chassis Number											1	Load JPG	☒		
18	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
19	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
20	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
21	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
22	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
23	21/02/20 15:16	Reinspection Photo											1	Load JPG	☒		
Documentation														1 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)											Thumbnail		Print		
1	14/08/19 14:26	ACKNOWLEDGEMENT EMAIL TO AIG DD 13.08.2019											1	Load PDF			
2	14/08/19 14:26	EMAIL FROM AIG DD 13.08.2019											1	Load PDF			
3	14/08/19 14:26	TP GIA REPORT											1	Load PDF			
4	16/08/19 21:08	TP ESTIMATE - MARKED											1	Load PDF			
5	23/08/19 12:12	LETTER TO OI											1	Load PDF			
6	21/02/20 15:15	TP ESTIMATED - MARKED (FINAL)											1	Load PDF			
7	01/04/20 08:40	WORKSHOP INVOICE											1	Load PDF			
8	01/04/20 08:40	AUTHORISATION TO ACT FORM											1	Load PDF			
9	01/04/20 08:40	Release Voucher											1	Load PDF			
10	01/04/20 08:40	LTA SEARCH											1	Load PDF			
11	01/04/20 08:40	LOD											1	Load PDF			
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)											Thumbnail		Print		
1	15/08/19 10:58	OI GIA REPORT											1	Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer	
Note: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKN9215J (Insd veh)	Model:	HONDA VEZEL 1.5 X CVT
	SMK7684T (TP veh)		(A)
Date of Accident:	03/08/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	4,941.17
Final Repair Cost	:	\$	3,702.54
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	8.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,010.54

Is Third Party Workshop GIA Registered?	☒ YES	☐ NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability _____(%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
	BOLA Liability: _____100____(%) Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 4,010.54
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

01 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19014099/KEA3Q2

Date: 01/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100418359
Claimant
Vehicle No : SMK7684T **Insured Vehicle No :** SKN9215J
Date of Loss: 03/08/2019 **Nature of Claim:** TP **Claim No:** 7856717695SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMK7684T
 Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B5564182
 Reg. Date: 24/04/2019 (Man. Year: 2018) Chassis No: RU11314171
 Colour: Metallic Red Odometer: 5383 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 9 mm Rear Left Side: Dunlop 9 mm
 Front Right Side: Dunlop 9 mm Rear Right Side: Dunlop 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,787.92	2,160.32	627.60	22.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,830.00	1,300.00	530.00	28.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,617.92	3,460.32	1,157.60	25.07
+ GST 7.00/7.00% (S\$)	323.25	242.22	81.03	25.07
Nett Amount (S\$)	4,941.17	3,702.54	1,238.63	25.07
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,010.54		

INSPECTION

Date of Assignment: 13/08/2019
 Date Inspected: 14/08/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	850.10 FL	*850.10 FL
2	6		*REAR BUMPER CLIPS	Necessary	23.40 FL	*23.40 FL
3	1		*REAR TAILGATE	Bent	1,100.90 FL	*1,100.90 FL
4	1		*TAILGATE EMBLEM (VEZEL)	Necessary	43.90 FL	*43.90 FL
5	1		*TAILGATE INNER LOCK	Dented	131.80 FL	*131.80 FL
6	1		*TAILGATE INNER RUBBER	Cut	98.50 FL	*98.50 FL
7	1		*TAILGATE INNER BOARD	Serviceable	153.40 FL	*- FL
8	1		*REAR PANEL	Repair	411.90 FL	*- FL
9	1		*REAR PANEL INNER TOP GARNISH	Serviceable	92.30 FL	*- FL
10	1		*REAR TOOL BOX	Serviceable	126.90 FL	*- FL
11	1		*REAR WINDSCREEN GLASS SEAL	Necessary	151.80 FL	*151.80 FL
12	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
13	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,424.90	2,640.40
- List Item Discount on L Items 20.00/20.00% (S\$)					636.98	480.08
Total Parts (S\$)					2,787.92	2,160.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	PANEL BEATING	New	800.00	500.00
3	PUTTY & RESPRAY ON TAILGATE REAR PANEL,REAR BUMPER,REAR SPARE TYRE COMPARTMENT	New	800.00	600.00
4	RUSTPROOFING	New	60.00	30.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	New	50.00	50.00
Gross Labour Cost (S\$)			1,830.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >