

BMW Dealer

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



16.09 @ 10 am  
Survey & repair  
xx Survey before 12pm

Like.  
Acher

GST REG. NO : M2 - 0020081 - X

14 AUG 2019

**E S T I M A T E**

Estimate No.	: b1 52306	Page No. : 1 of 5
Date Estimated	: 14/08/2019	
Prepared By	: Inthiran A/L Thurasamy	

<b>- ESTIMATE REPAIR FOR -</b> <b>Shane Alexander Abucewicz Tan Yuan-</b> <b>10E Bradell Hill</b> <b>#04-17</b> <b>singapore 579724</b>	<b>- ACCOUNT - 121</b> <b>AIG Asia Pacific Insurance Pte. Ltd.</b> <b>78 Shenton Way</b> <b>#08-16 Chartis Building</b> <b>Singapore 079120</b>
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLD6023G	VD45252	18/12/2018	M2 COUPE	0

DESCRIPTION	VALUE
To replace front bumper and repair fender left.	1275 2,550.00
Painting front bumper and fender left.	1730 1,923.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To replace tyre and wheel rim including balancing. (1x).	80 94.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x)	451 531.00
Sundries.	? 80.00
Total Labour 1:	5,532.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 9JX19 M DOUBLE SPK 437M	1	2,599.55	2,599.55
FRT BUMPER PANEL PRIMED	1	1,272.30	1,272.30
Total Parts :			3,871.85

**Performance Motors Limited**

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



**GST REG. NO : M2 - 0020081 - X**

**E S T I M A T E**

Estimate No. : **b1 52306**  
Date Estimated : **14/08/2019**  
Prepared By : **Inthiran A/L Thurasamy**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SLD6023G</b>	<b>VD45252</b>	<b>18/12/2018</b>	<b>M2 COUPE</b>	<b>0</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>16/9/19 @ 530</u>	Excess S\$ _____
Surveyor's Name <u>Tan Jia Hui</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97495789</u>	Authorised Yes / No _____
Authorised Date <u>WP</u>	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR <input checked="" type="checkbox"/> Yes / No <input type="checkbox"/> No PML Yes / No _____	
Surveyor's E-mail <u>tan.jia.hui@lkk.com.sg</u>	
No. of Working Days Recommend <u>4 days</u>	

Labour 1	:	<b>5,532.00</b>
Parts	:	<b>3,871.85</b>
Labour 2	:	<b>0.00</b>
Excess	:	<b>0.00</b>
Total GST @ 7%	:	<b>658.27</b>
<b>Grand Total</b>	:	<b>10,062.12</b>

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*