ESTIMATED ACCIDENT REPAIR COST



| ACCIDENT TIME REPORTED | 11:20hrs |
|---------------------------|-----------------------------|
| ACCIDENT DATE | 6-Aug-19 |
| BUS CAPTAIN NAME | AMIRUL HAKIM BIN ABD RAHMAN |
| EMPLOYEE NUMBER | |

| BUS REGISTRATION NUMBER | SG1009H |
|----------------------------|---------|
| BUS TYPE (SD/DD) | SD |
| BUS ROUTE NUMBER | |
| BUS ADVERTS (Y/N) | N |

SECTION 1: PARTS & CONSUMABLE ITEMS (MATERIAL COST)

| Total Cost | Quantity | Part or Item Description | Part No. |
|------------|-------------------------|--------------------------|----------|
| \$5,103.58 | the 1 | RADIATOR FLAP | 77200621 |
| \$746.18 | Cus 1 | REAR CORNER BUMPER O/S/R | 77200124 |
| \$80.00 | Ove 1 | SIDE MARKER LIGHT | 77200612 |
| \$3.60 | btv 2 | DOWEL (ANCHOR) | 77014459 |
| | | | |
| A445.24 | 70/ 057 | | |
| \$415.34 | 7% GST PARTS TOTAL COST | | |

SECTION 2: ASSESSMENT / REPAIR / SPRAY PAINT (LABOUR COST)

| LABOUR ITEM (PLEASE SPECIFY IF ITS ASSESSMENT, REPAIR OR SPRAY PAINT) | | TOTAL COST |
|---|------------------|------------|
| TO REMOVE & REPLACE DAMAGED PARTS | 3 DAYS 1300 | \$1,950.00 |
| PUTTY AND SPRAY PAINTING | 4 DAYS 1625 | \$2,600.00 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | 7% GST | \$318.50 |
| | LABOUR TOTAL COS | \$4,868.50 |

PAGE 1

ESTIMATED ACCIDENT REPAIR COST



| SECTION 3: REPAIRS TO BUS | ADVERTISMENT VINYLS | S/PANELS (ADVERTISEMENT | COST) |
|----------------------------------|---------------------|-------------------------|-------|
|----------------------------------|---------------------|-------------------------|-------|

TOTAL ADVERTISEMENT REPAIR COST

SECTION 4: RECOVERY OF ACCIDENT BUS (TOWING COST)

TOTAL TOWING COST

SECTION 5: NUMBER OF DAYS UNDER ACCIDENT REPAIR (LOSS OF USE COST)

Date In For Repairs

Date Out From Repairs

Number of Days Under Repair 8

BUS TYPE (SD / DD)

LOSS OF USE COST

\$2,400.00

| SUMMARY | | |
|-----------------------------------|-------------|--|
| SECTION NO. | COST | |
| 1 | \$6,348.70 | |
| 2 | \$4,868.50 | |
| 3 | - | |
| 4 | | |
| 5 | \$2,400.00 | |
| ESTIMATED ACCIDENT REPAIR COST | \$13,617.20 | |

Tauphir 97495749

14/8/19 e 340.

Resurvey before paint.

5-6 days.

Sur C/likanto.com

taufikh C/likanto.com

PAGE 2

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: