

Vivien

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

FALCON-AIR

WU MAE LAN
BLK 342 CLEMENTI AVE 5 #11-184
SINGAPORE 120342Attention : Motor Claim Department
Contact : 93555705

Estimate : ES003513

Date : 13/08/2019
Vehicle Num. : SFC455J
Make/Model : MIT I-CAR
Chassis/Eng# : JMYLRHA1W7U000780
Accident Date : 11/08/2019
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
NETT ITEMS :				
1.	1	TAILGATE		860.00 <i>bt</i>
2.	1	TAILGATE LOGO		35.00 <i>rel</i>
3.	1	TAILGATE EMBLEM I		40.00 <i>rel</i>
4.	1	REAR BUMPER		788.00 <i>de</i>
5.	1	REAR BUMPER SIDE RETAINER LH/RH		16.00 <i>rel</i>
6.	1	REAR BUMPER LOWER		900.00 <i>Rx</i>
7.	1	REAR BUMPER LOWER GARNISH		900.00 <i>Rx</i>
8.	1	EXHAUST HEAT SHIELD		98.00 <i>?</i>
Nett Total S\$:				3,637.00
10.00% Discount S\$:				363.70
				<u>3,273.30</u>
SPECIAL NETT ITEMS :				
1.	1	REAR NUMBER PLATE		45.00 <i>bt</i>
2.	1	SEALANT		40.00 <i>rel</i>
Special Nett Total S\$:				<u>85.00</u>
LABOUR :				
TO REMOVE/REFIX TAILGATE GLASS				100.00 <i>✓</i>

CONTINUE / ...


FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**WU MAE LAN
BLK 342 CLEMENTI AVE 5 #11-184
SINGAPORE 120342Attention : Motor Claim Department
Contact : 93555705

Estimate : ES003513

Date : 13/08/2019
Vehicle Num. : SFC455J
Make/Model : MIT I-CAR
Chassis/Eng# : JMYLRHA1W7U000780
Accident Date : 11/08/2019
Claim No. :
Reference : TP NTUC VS III
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO TRANSFER TAILGATE PARTS/MECHANISM	50.00	40
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS	800.00	650
		TO REPAIR REAR END PANEL , INCLUDES KNOCKING AND REPLACEMENT OF PARTS	450.00	350
		Labour Total S\$:		1,400.00

Tan Jiah 97495749
-wp
19/8/19 0245pm
Resurvey after repair
4 days
tanjiah@falconair.com

SingDollars : Four Thousand Seven Hundred Fifty-Eight & Cents Thirty Only

E. & O.E.

Total S\$: 4,758.30

for FALCON AIR AUTO SERVICES PTE LTD

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg