



FALCON-AIR

WU MAE LAN
BLK 342 CLEMENTI AVE 5 #11-184
SINGAPORE 120342

Attention: Motor Claim Department
Contact: 93555705

Vivien

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Page 1 / 2

Estimate ES003513

Date: 13/08/2019
Vehicle Num.: SFC455J
Make/Model: MITI-CAR
Chassis/Eng#: JMYLRHA1W7U000780
Accident Date: 11/08/2019
Claim No.:
Reference: TP NTUC VS III
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
		NETT ITEMS		
1	1	TAILGATE		860.00 <i>bt</i>
2	1	TAILGATE LOGO		35.00 <i>re</i>
3	1	TAILGATE EMBLEM		40.00 <i>re</i>
4	1	REAR BUMPER		788.00 <i>de</i>
5	1	REAR BUMPER SIDE RETAINER LH/RH		16.00 <i>re</i>
6	1	REAR BUMPER LOWER		900.00 <i>Rx</i>
7	1	REAR BUMPER LOWER GARNISH		900.00 <i>Rx</i>
8	1	EXHAUST HEAT SHIELD		98.00 <i>bt</i>
		Nett Total S\$	1837.	3637.00
		10.00% Discount S\$		363.70
			1653.30	3273.30
		SPECIAL NETT ITEMS		
1	1	REAR NUMBER PLATE		45.00 <i>bt</i>
2	1	SEALANT		40.00 <i>re</i>
		Special Nett Total S\$		85.00
		LABOUR		
		TO REMOVE/REFIX TAILGATE GLASS		100.00

CONTINUE /

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S\$528840 Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K1 S\$128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**WU MAE LAN
BLK 342 CLEMENTI AVE 5 #11-184
SINGAPORE 120342

Attention: Motor Claim Department

Contact: 93555705

Estimate: ES003513

Date: 13/08/2019
Vehicle Num.: SFC455J
Make/Model: MIT I-CAR
Chassis/Eng#: JMYLRHA1W7U000780
Accident Date: 11/08/2019
Claim No.:
Reference: TP NTUC VS III
Policy No.:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

		TO TRANSFER TAILGATE PARTS/MECHANISM		50.00 ⁴⁰
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS		800.00 ⁶⁵⁰
		TO REPAIR REAR END PANEL INCLUDES KNOCKING AND		
		REPLACEMENT OF PARTS		450.00 ³⁵⁰

Labour Total S\$:

1400.00 ¹¹⁴⁰

1653.30
85
1140
2878.30
4/5/2300

Tanjum 97495749
-wp
19/8/19 @ 245 pm
Recovery after repair
4 days
tanjume@kharp.com

SingDollars: Four Thousand Seven Hundred Fifty-Eight & Cents Thirty Only

E & O E

Total S\$ 4,758.30

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 900G #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1111

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg