

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pang Xiu Shi

Date: 15 Aug 2019

Preliminary Advice

Vehicle No	: SKD5043S	Accident Date	: 10/08/2019
Make	: VOLKSWAGEN TIGUAN	Policy No.	: A29127154AVW
Assignment Date	: 14/08/2019	Excess	: S\$1,500.00
Date of Inspection	: 14/08/2019	Est. Duration of Repair	: 6 days
Inspection At	: Volkswagen Group Singapore Pte Ltd (MacPherson) 1 Kampong Ampat, Singapore 368314 Singapore 368314		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,372.12
Revised Amount	:S\$	8,317.40
Check Items (Estimated)	:S\$	26.11
Total	:S\$	8,343.51

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	68,462.00
Salvage Value	:S\$	
Margin for Repair	:S\$	76,538.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.