

22/03/2002

ASS. REC. BY:

Assigner: Adrian

REF:

CS/AGI19014125/Avd3¹²

Special Instruction:

ASSIGNMENT (Office)

From (Person):

My Raktia

of

AGI

Date/Time:

13/8/19 @ 5.22pm

Estimated Cost:

Bill to:

OD / REP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLR 8804H

Insured:

SMK 7557C

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

2 Kelki Zuleif Ave 2 #01-17/18

Policy No:

Claim No:

C10003709/JM

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

8/8/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:31 AM @ 14/8/19

Person Contacted:

Zi KingVehicle IN / OUT

Date/Time

Action/Instruction

Estimate /SLR 8804H - NA / Lp19004916/24DOT: 16/3/19SMK 7557C-X11/11/19Adrian confirmed LS \$15000 (Red 14,856.75, 50%)

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 16 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLR8804 H Yr Regn: 2017 / AugustType: ML Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius Alpha Hybrid 1797Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 213155 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZVW 400025766Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / SR / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Habikad

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 14/08/19Survey held at NSIDes. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget DirectMV: 95KPV: 47.6KNett: 47.4K

RECEIVED 11 NOV 2019

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

Survey Fee:

Date:

1) 11/11 - typist

2)

IN

OUT

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

450

Prel. Report:

Final Report:

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Tuesday, 13 August 2019 5:22 PM
To: Chio Ziting; Admin-D (LKKAuto)
Cc: Julie Mangubat; sur@lkkauto.com
Subject: TPPD Survey: Claim ref:C10003709/JM || OI- SMK7557C (Blue) TP- SLR8804H || Est:0.00 || N-51
Attachments: 13082019110927-0001.pdf; 8804.pdf

Hi Team,

We would like to arrange TP PRS for SLR8804H. Please see attached files for reference.

Workshop has chosen Mr Adrian Ling to survey the vehicle.

Kindly confirm.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: Chio Ziting <ziting@n51.com.sg>

Sent: Tuesday, 13 August 2019 5:15 PM

To: Ivy Ratilla <ivy.r@budgetdirect.com.sg>

Subject: Re: SLR8804H & SMK7557C - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS || C10003709

Dear Sir / Madam,

We appoint your surveyor from Mr Adrian Ling - LKK.

Please see attached.

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



From: Chio Ziting <ziting@n51.com.sg>

Sent: Tuesday, 13 August 2019 11:14 AM

To: Claims <claims@budgetdirect.com.sg>

Subject: SLR8804H & SMK7557C - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Pixel 3a

Google Pixel 3a. Get the latest phone today.

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

Land Rover Defender 90 Hard Top 2.2.

Comes With Many Accessories,
Call To Enquire.
Direct Owner StarAd

AutoInn
An Inspiration For Car Buyers

click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category Save Search Print Sort by Date Posted 20 results/page

4 vehicles | **Search** Prius Alpha Hybrid 1.8A S

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

Search Selection Prius Alpha Hybrid 1.8A S Any Any Any Any Any Any Available

☐ **Toyota Prius Alpha Hybrid 1.8A S** \$99,800 \$12,060 /yr 06-Sep-2017 1,797 cc - MPV Available

Fuel Type: Petrol-Electric
Well Maintained Unit, No Repairs Needed!

Posted: 13-Aug-2019 Tags: 2017 Toyota Prius, 2017 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota

☐ **Toyota Prius Alpha Hybrid 1.8A S** \$102,800 \$10,800 /yr 09-Feb-2018 1,797 cc - MPV Available

Fuel Type: Petrol-Electric
Elegant Black, 7 Seater MPV, Almost New Condition, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Flexible In House Loan Available.

Prime Motor & Leasing
 Posted: 31-Jul-2019 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota

☐ **Toyota Prius Alpha Hybrid 1.8A S** \$102,000 \$10,710 /yr 09-Feb-2018 1,797 cc 25 km MPV Available

Fuel Type: Petrol-Electric
Almost Brand New Condition, 7 Seaters MPV, With Warranty, Easy Financing, High Trade In.

Prime Motor & Leasing
 Posted: 16-Jul-2019 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota

☐ **Toyota Prius Alpha Hybrid 1.8A S** \$102,000 \$10,700 /yr 12-Feb-2018 1,797 cc 7,700 km MPV Available

Fuel Type: Petrol-Electric
Elegant Blue, 7 Seaters MPV, Almost Brand New, Low Fuel Consumption With Hybrid, Low Maintenance Cost, Very Well Maintained, With Warranty, Easy Financing, Flexible In-house Loan Packages Available.

Prime Motor & Leasing
 Posted: 03-Aug-2019 Tags: 2018 Toyota Prius, 2018 toyota prius, Toyota Prius, toyota prius, Toyota, Prius, prius, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Save Search

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Prius Alpha Hybrid 1.8A S, Prius Alpha Hybrid 1.8A S Singapore, used Prius Alpha Hybrid 1.8A S Singapore, used Prius Alpha Hybrid 1.8A S, used vehicles Singapore or even buy used Prius Alpha Hybrid 1.8A S Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

SHORTLISTED HISTORY

Compare

Follow sgCarMart.com



Download on the
App Store

GET IT ON
Google play

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	909C
Vehicle Details	
Vehicle No.:	SLR8804H
Vehicle to be Exported:	Yes
Intended Deregistration Date:	14 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS ALPHA HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR1976138
Chassis No.:	ZVW400025766
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,981.00
Original Registration Date:	30 Aug 2017
First Registration Date:	30 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,374.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$4,030.00
Intended COE Rebate Details	
COE Expiry Date:	29 Aug 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,405.00
COE Rebate Amount:	\$43,524.00
Total Rebate Amount:	\$47,554.00

The information contained herein is correct as at 14 Aug 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/08/2019 16:32
Date Of Accident	08/08/2019 13:15
Exact Location Of Accident	TPE TWDS AIRPORT BEFORE UPPER CHANGI ROAD NORTH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR8804H
Insured/Policyholder	
Name Of Registered Owner	DARWIN-51 CAR RENTAL PTE LTD
Co Reg No	201407909C
Email Address	SALES@N51.COM.SG
Mobile Phone No	(LOCAL) +65-88215151
Alternative Phone No	OFFICE-88215151

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS ALPHA HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	CHAUFFEUR
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	SD19V08678/VPZ/R02
Cover Note Number	

Driver

Name of Driver	LIM SOON BENG (LIN SHUNMING)
NRIC No	S7702605C
Date Of Birth	14/02/1977
Occupation	OUTDOOR
Date Of Driving Pass	23/10/1997
Driving Experience	21 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90085875
Fax Number	
Contact Number	OTHERS-90085875
EEmail Address	STEVENLIM.SB@GMAIL.COM

Address	APT BLK 246 YISHUN AVENUE 9 #08-249 SINGAPORE
Postcode	760246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMK7557C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KOH TUCK LOONG
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

LIM SOON BENG (LIN SHUNMING)

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLR8804H

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

APT BLK 246 YISHUN AVENUE 9 #08-249
SINGAPORE

Postcode

760246

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 08/08/19 at @ 1315 hrs, I was travelling in my vehicle (SLR 88044) along TPE towards airport before Upper Changi Road North on the 2nd lane from the right. There was a road work on the extreme right lane, and the traffic was very heavy. The vehicle in front of me stopped due to traffic jammed and I slow down and stopped too. Suddenly, a car (SMK 7557C) from behind collided onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

2006 - Adrian

TP Budget Direct.
Veron.

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

Contact : 88215151 90085875

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Distorted</i>	1	523.90	523.90 ✓
REAR BUMPER RH END SEAL COVER <i>Distorted</i>	1	92.30	92.30 ✓
REAR BUMPER RH REFLECTOR <i>cracked.</i>	1	58.00	58.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	98.00	196.00 ✓
REAR END PANEL <i>Distorted.</i>	1	781.45	781.45 ✓
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	285.00	285.00 +
REAR END PANEL INNER TOP GARNISH <i>Del'd</i>	1	287.90	287.90 ✓
REAR EXHAUST SILENCER ALUMINIUM HEAT SHIELD <i>cracked</i>	1	151.90	151.90 ✓
REAR EXHAUST SILENCER BOX <i>Bar</i>	1	1017.70	1017.70 823.10 ✓
REAR EXHAUST SILENCER BOX GASKET <i>new</i>	1	35.00	35.00 ✓
REAR EXHAUST SILENCER BOX RUBBER MOUNTING <i>new</i>	2	55.00	110.00 +
REAR RH BODY END MEMBER <i>repair</i>	1	781.10	781.10 X
REAR RH DECK BOX COVER <i>Del'd</i>	1	381.60	381.60 ✓
REAR RH DECK BOX TOP COVER <i>Del'd</i>	1	381.10	381.10 195 ✓
REAR RH DOOR <i>Buckled.</i>	1	1279.10	1,279.10 ✓
REAR RH DOOR FRAME BLACK STICKER <i>new</i>	1	171.45	171.45 ✓
REAR RH DOOR INNER TRIM BOARD <i>new</i>	1	737.90	737.90 X
REAR RH DOOR MECHANISM LOCK <i>new</i>	1	708.10	708.10 459 ✓

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 88215151 90085875

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

REAR RH DOOR OUTER MOUDLING	<i>Ne new</i>	1	211.60	211.60 ✓
REAR RH DOOR VERTICAL GARNISH	<i>} Ne new</i>	1	172.25	172.25 ✓
REAR RH DOOR WEATHER STRIP		1	274.40	274.40 ✓
REAR RH FENDER	<i>Distorted.</i>	1	972.45	972.45 ✓
REAR RH FENDER AIR VENT	<i>Deformed.</i>	1	174.25	174.25 ✓
REAR RH FENDER GLASS INNER TRIM GARNISH	<i>Deformed.</i>	1	411.60	411.60 ✓
REAR RH FENDER GLASS MOULDING	<i>New</i>	1	274.70	274.70 ✓
REAR RH FENDER INNER PANEL	<i>Repair</i>	1	731.35	731.35 ✓
REAR RH FENDER INNER UPHOLSTERY TRIM GARNISH L/R	<i>Distorted</i>	2	656.00	1,312.00 ✓
REAR RH FLOOR EXTENSION PANEL	<i>Distorted</i>	1	440.25	440.25 ✓
REAR RH SAFETY BELT	<i>Damaged.</i>	1	731.35	731.35 ✓
REAR RH SHOCK ABSORBER	<i>New New</i>	1	209.10	209.10 ✓
REAR RH TAILLAMP INNER PANEL	<i>Distorted</i>	1	580.00	580.00 316 ✓
REAR RH WHEEL BEARING HUP	<i>New New</i>	1	781.90	781.90 ✓
REAR SPARE TYRE PANEL	<i>Buckled.</i>	1	972.45	972.45 ✓
REAR SPARE TYRE RETAINER LOCK	<i>Damaged</i>	1	77.00	77.00 ✓
REAR SPARE TYRE SPONGE TRAY	<i>Deformed</i>	1	396.70	396.70 ✓
REAR SPONGE COMPARTMENT TRAY	<i>Deformed.</i>	1	459.70	459.70 396.70

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 88215151 90085875

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

REAR SPONGE COMPARTMENT TRAY TOP COVER <i>del d</i>	1	655.00	655.00 ✓
REAR TAILGATE <i>Distorted</i>	1	929.60	929.60 ✓
REAR TAILGATE 'HYBRID' EMBLEM <i>} New</i>	1	50.00	50.00 ✓
REAR TAILGATE 'PRIUS' EMBLEM <i>} New</i>	1	52.30	52.30 ✓
REAR TAILGATE DAMPER L/R <i>Not New</i>	2	356.70	713.40 ✗
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH <i>Del d</i>	1	578.00	578.00 ✓
REAR TAILGATE MECHANISM LOCK <i>Damaged</i>	1	425.00	425.00 ✓
REAR TAILGATE OUTER GARNISH <i>del d</i>	1	427.90	427.90 ✓
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM <i>New</i>	1	87.10	87.10 ✓
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>Not New</i>	2	29.00	58.00 ✗
REAR TAILGATE TOP SPOILER <i>Not New</i>	1	1220.00	1,220.00 ✗
REAR TAILGATE WEATHER STRIP <i>del</i>	1	360.70	360.70 ✓
REAR TAILGATE WINDSCREEN LOWER SEAL <i>} New</i>	2	42.00	84.00 ✓
REAR TAILGATE WINDSCREEN MOULDING L/R <i>} New</i>	2	65.00	130.00 ✓
REAR TAILGATE WINDSCREEN UPPER SEAL <i>New</i>	1	38.00	38.00 ✓
REAR TAILLAMP BACK RUBBER SEAL L/R <i>RA New</i>	2	69.50	139.00 60.
REAR TAILLAMP L/R <i>del d</i>	2	660.60	1,321.20 1030
REAR TAILLAMP LOWER BRACKET L/R <i>RA del d</i>	2	68.00	136.00 68.

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 88215151 90085875

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

RH SIDE ROCKER PANEL GARNISH	<i>can be</i>	17487.75	1	972.45	972.45 ^{598.}
ROOF TOP LINING	<i>the re</i>	13115.81	1	2528.80	2528.80 ^X
Subtotal before discount					28,069.00
Percentage discount 25%					7,017.25
Sub-total 1					21,051.75
REAR BUMPER CLIPS - SET	<i>Nec</i>		1	50.00	50.00 30
REAR BUMPER REVERSE SENSOR - SET	<i>Damaged</i>		1	250.00	250.00 200
REAR END PANEL INNER TOP GARNISH CLIPS - SET	<i>Nec</i>		1	20.00	20.00 10
REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R - SET	<i>Nec</i>		2	30.00	60.00 30
REAR RH BATTERY	<i>Not Nec</i>		1	250.00	250.00 X
REAR RH FENDER GLASS SEALANT	<i>Nec</i>		1	60.00	60.00 40
REAR RH INNER TRIM BOARD CLIPS - SET	<i>Nec</i>		1	50.00	50.00 30
REAR RH TYRE	<i>Not Nec</i>		1	350.00	350.00 X
REAR SPARE TYRE PANEL INSULATOR MAT	<i>Nec</i>		1	250.00	250.00 200
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	<i>Nec</i>		1	80.00	80.00 30
REAR TAILGATE NUMBER PLATE	<i>2 Not Nec</i>		1	25.00	25.00 X
REAR TAILGATE NUMBER PLATE HOLDER			1	50.00	50.00 X
REAR TAILGATE OUTER GARNISH CLIPS - SET	<i>Nec</i>		1	20.00	20.00 10

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
 2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
 AUTOHUB
 SINGAPORE 417921

Contact : 88215151 90085875

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

REAR TAILGATE TOP SPOILER CLIPS - SET <i>new</i>	1	50.00	50.00 <i>30</i>
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	80.00 <i>60</i>
REAR TAILLAMP CLIPS L/R - SET <i>new</i>	2	30.00	60.00 <i>20</i>
ROOF TOP LINING CLIPS - SET <i>Not New</i>	1	80.00	80.00 <i>X</i>
Subtotal before discount			1,785.00
Percentage discount 0%			0.00
Sub-total 2			1,785.00
Parts-total			22,836.75

LABOUR

- To reset system after repair works
- To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.
- To remove, reinstall tailgate windscreen
- To remove, reinstall fender glass
- To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.
- To road test driving, check and resetting wheel alignments system.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~300.00~~ *100*
~~50.00~~ ✓
~~150.00~~ *120*
~~120.00~~ *60*
~~180.00~~ *100*
~~100.00~~ *80*
~~200.00~~ *100*
~~100.00~~ *80*
~~2,200.00~~ *1800*
~~3,200.00~~ *2400*

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

DARWIN-51 CAR RENTAL PTE LTD
2 KAKI BUKIT AVE 2 #02-12 KAKI BUKIT
AUTOHUB
SINGAPORE 417921

Contact : 88215151 90085875

ESTIMATE

Repair Code : CLM15453

Date in : 08/08/2019

Vehicle Num. : SLR8804H

Model : TOYOTA PRIUS ALPHA HYBRID 1.8S CVT

Chassis/Eng# : ZVW400025766/2ZR1976138

To mount vehicle on to Car 'O' Liner.

To apply anti-rust chemical on repaired and replaced panel.

	4990.	300.00
		120.00 100
Labour Total		7,020.00
Parts & Labour Total		29,856.75

*** This is a computer-generated document which requires no signature.***

page 6

L&K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 18795.81

4/s. 15k

16 Days.

15k

16795.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI19014125/Avd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 12-11-2019	
				
			Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 7557C	Veh. Inspected	SLR 8804H	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10003709/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	13/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS ALPHA HYBRID	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZVW400025766	Colour	GREY	
Odometer	213155	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	HABILEAD	6 mm	
L/H Front Tyre	205/60 R16	HABILEAD	6 mm	
R/H Rear Tyre	205/60 R16	HABILEAD	6 mm	
L/H Rear Tyre	205/60 R16	HABILEAD	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/08/2019	Inspection Date	14/08/2019	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 8804H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	523.90	523.90
1	REAR BUMPER RH END SEAL COVER	DISTORTED	92.30	92.30
1	REAR BUMPER RH REFLECTOR	CRACKED	58.00	58.00
2	REAR BUMPER SIDE RETAINER L/R @\$98.00	NECESSARY	196.00	196.00
1	REAR END PANEL	DISTORTED	781.45	781.45
1	REAR END PANEL ANTENNA SENSOR	NOT NECESSARY	285.00	-
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	287.90	287.90
1	REAR EXHAUST SILENCER ALUMINIUM HEAT SHIELD	CRUMPLED	151.90	151.90
1	REAR EXHAUST SILENCER BOX	BENT	1,017.70	823.10
1	REAR EXHAUST SILENCER BOX GASKET	NECESSARY	35.00	35.00
2	REAR EXHAUST SILENCER BOX RUBBER MOUNTING @\$55.00	NOT NECESSARY	110.00	-
1	REAR RH BODY END MEMBER	TO REPAIR SEE LABOUR	781.10	-
1	REAR RH DECK BOX COVER	DEFORMED	381.60	381.60
1	REAR RH DECK BOX TOP COVER	DEFORMED	381.10	195.00
1	REAR RH DOOR	BUCKLED	1,279.10	1,279.10
1	REAR RH DOOR FRAME BLACK STICKER	NECESSARY	171.45	171.45
1	REAR RH DOOR INNER TRIM BOARD	NOT NECESSARY	737.90	-
1	REAR RH DOOR MECHANISM LOCK	DAMAGED	708.10	459.00
1	REAR RH DOOR OUTER MOULDING	NOT NECESSARY	211.60	-
1	REAR RH DOOR VERTICAL GARNISH	NOT NECESSARY	172.25	-
1	REAR RH DOOR WEATHER STRIP	NOT NECESSARY	274.40	-
1	REAR RH FENDER	DISTORTED	972.45	972.45
1	REAR RH FENDER AIR VENT	DEFORMED	174.25	174.25
1	REAR RH FENDER GLASS INNER TRIM GARNISH	DEFORMED	411.60	411.60
1	REAR RH FENDER GLASS MOULDING	NECESSARY	274.70	274.70
1	REAR RH FENDER INNER PANEL	TO REPAIR SEE LABOUR	731.35	-
2	REAR RH FENDER INNER UPHOLSTERY TRIM GARNISH L/R @\$656.00	DISTORTED	1,312.00	1,312.00
1	REAR RH FLOOR EXTENSION PANEL	DISTORTED	440.25	440.25
1	REAR RH SAFETY BELT	DAMAGED	731.35	731.35
1	REAR RH SHOCK ABSORBER	NOT NECESSARY	209.10	-
1	REAR RH TAILLAMP INNER PANEL	DISTORTED	580.00	316.00

Report Ref No. CS/AGI19014125/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH WHEEL BEARING HUP	NOT NECESSARY	781.90	-
1	REAR SPARE TYRE PANEL	BUCKLED	972.45	972.45
1	REAR SPARE TYRE RETAINER LOCK	DAMAGED	77.00	77.00
1	REAR SPARE TYRE SPONGE TRAY	DEFORMED	396.70	396.70
1	REAR SPONGE COMPARTMENT TRAY	DEFORMED	459.70	396.70
1	REAR SPONGE COMPARTMENT TRAY TOP COVER	DEFORMED	655.00	655.00
1	REAR TAILGATE	DISTORTED	929.60	929.60
1	REAR TAILGATE "HYBRID" EMBLEM	NECESSARY	50.00	50.00
1	REAR TAILGATE "PRIUS" EMBLEM	NECESSARY	52.30	52.30
2	REAR TAILGATE DAMPER L/R @\$356.70	NOT NECESSARY	713.40	-
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	DEFORMED	578.00	578.00
1	REAR TAILGATE MECHANISM LOCK	DAMAGED	425.00	425.00
1	REAR TAILGATE OUTER GARNISH	CRACKED	427.90	427.90
1	REAR TAILGATE OUTER GARNISH "LOGO" EMBLEM	NECESSARY	87.10	87.10
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R @\$29.00	NOT NECESSARY	58.00	-
1	REAR TAILGATE TOP SPOILER	NOT NECESSARY	1,220.00	-
1	REAR TAILGATE WEATHER STRIP	CUT	360.70	360.70
2	REAR TAILGATE WINDSCREEN LOWER SEAL @\$42.00	NECESSARY	84.00	84.00
2	REAR TAILGATE WINDSCREEN MOULDING L/R @\$65.00	NECESSARY	130.00	130.00
1	REAR TAILGATE WINDSCREEN UPPER SEAL	NECESSARY	38.00	38.00
2	REAR TAILLAMP BACK RUBBER SEAL L/R @\$69.50	O/S NECESSARY	139.00	60.00
2	REAR TAILLAMP L/R @\$660.60	CRACKED	1,321.20	1,030.00
2	REAR TAILLAMP LOWER BRACKET L/R @\$68.00	O/S DAMAGED	136.00	68.00
1	RH SIDE ROCKER PANEL GARNISH	CRACKED	972.45	598.00
1	ROOF TOP LINING	NOT NECESSARY	2,528.80	-
	LESS 25% DISCOUNT		-7,017.25	-4,371.19
			21,051.75	13,113.56
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR BUMPER REVERSE SENSOR (SN)	DAMAGED	250.00	200.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
2	SET REAR FENDER INNER UPHOLSTERY TRIM GARNISH CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	30.00
1	REAR RH BATTERY (SN)	NOT NECESSARY	250.00	-
1	REAR RH FENDER GLASS SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR RH INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00

Report Ref No. CS/AGI19014125/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR RH TYRE (SN)	NOT NECESSARY	350.00	-
1	REAR SPARE TYRE PANEL INSULATOR MAT (SN)	NECESSARY	250.00	200.00
1	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE NUMBER PLATE (SN)	NOT NECESSARY	25.00	-
1	REAR TAILGATE NUMBER PLATE HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
	SET REAR TAILGATE TOP SPOILER CLIPS (SN)	NECESSARY	50.00	30.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	60.00
2	REAR TAILLAMP CLIPS L/R @\$30.00 (SN)	NECESSARY	60.00	20.00
1	SET ROOF TOP LINING CLIPS (SN)	NOT NECESSARY	80.00	-
			1,785.00	690.00
	LABOUR			
	TO RESET SYSTEM AFTER REPAIR WORKS.		300.00	100.00
	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS,CHECK LIGHTING,AND REWIRE FOR PARKING SENSOR.		50.00	50.00
	TO REMOVE,REINSTALL TAILGATE WINDSCREEN.		150.00	120.00
	TO REMOVE,REINSTALL FENDER GLASS.		120.00	60.00
	TO REMOVE,CHANGE REAR SUSPENSION PARTS,AXLE CARRIAGE,ABSORBER,LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB AND ETC.		180.00	100.00
	TO ROAD TEST DRIVING,CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		100.00	80.00
	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY,CUSHION SEAT,TRIM GARNISH,TRIM LINER CARPET (TO FR).		200.00	100.00
	TO TRANSFER DOOR GLASS,REGULATOR GEAR,MOTOR,RAILING,CHANNEL,TRIM BOARD,MECHANISM LOCK AND HANDLE.		100.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT.		2,200.00	1,800.00
	TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR RH BODY END MEMBER AND REAR RH FENDER INNER PANEL.		3,200.00	2,400.00
	TO MOUNT VEHICLE ON TO CAR "O" LINER.	NOT NECESSARY	300.00	-

Report Ref No. CS/AGI19014125/Avd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		120.00	100.00
			7,020.00	4,990.00
GRAND TOTAL			29,856.75	18,793.56
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				15,000.00

Report Ref No. CS/AGI19014125/Avd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.