

# BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636  
Tel: 6559 8944 / Fax: 6269 2404

## AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore (068811)

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 6338 7288 Fax : 6880 4838

DEAR SIR / MADAM :

*Not withair*

### ACCIDENT REPAIR ON: SLF493L

MODEL : VOLKSWAGEN GOLF 1.4 TSI

POLICY NO : MA005101

CHASSIS NO : VVWZZZAUZGW089662

MANUFACTURE OF YEAR : 2015

DATE/TIME OF ACCIDENT: 12/08/2019 Time: 0800Hrs at MALAYSIA CUSTOMS TOWARDS SINGAPORE.

THIRD PARTY VEHICLE NO: SFX66M

Date: 15/08/2019

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

### Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Rear bumper	1	739.50	Dented	739.50 X
2 Rear bumper side retainer LH	1	27.30	Necessary	27.30 X
3 Rear bumper side retainer RH	1	27.30	Necessary	27.30 X
4 Rear bumper clip	12	1.60	Necessary	19.20 X
5 Rear bumper centre bracket	1	47.60	Broken	47.60 X
6 Rear bumper sensor	6   1	118.00	Malfunction	708.00 ~ 118.00 X
7 Rear bumper sensor ring	6   1	1.50	Necessary	9.00 X 1.50 X
8 Rear bumper sponge	3	80.00	Torn	240.00 X
9 Rear bumper reinforcement	1	322.00	Dented	322.00 X
10 Rear bumper lower garnish	1	221.00	Cut	221.00 X
11 Rear number plate lamp LH	1	16.80	Cracked	16.80 X
12 Rear number plate lamp RH	1	16.80	Cracked	16.80 X
13 Rear end panel	1	366.00	Dented	366.00 X
14 Rear end panel top garnish	1	89.80	Kinked	89.80 X

\$923.40 - 10%

= \$831.06

Sub-Total: 2,850.30

Less: 10% discount - 285.03

Total Parts after 10% discount: 2,565.27

### Special Nett Items

1 Anti-rust coating	1	80.00	80.00 X
2 Rear number plate with casing	1	100.00	100.00 X
3 Rear end panel seal	1	120.00	120.00 X
			300.00

Total Parts: 2,865.27

### Labour Charges For Rear Portion

1 Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	1,000.00 1501
2 Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	750.00 2201

- 3 Provide skill labour to disconnect and check electrical wiring 60.00 101
- 4 Remove and reinstall cushions, seats, backrest, inner trim, garnish, roof lining and or upholstery to facilitate repairs 150.00 X
- 5 Provide skill labour to remove and replace bumper sensors 80.00 760

Total Labour: \$440

Total Parts & Labour:  
GST 7%  
Grand Total:

2,040.00  
4,905.27  
343.37  
5,248.64

Estimate Repair Duration

08 days

ACCIDENT VEHICLE OF : SLF493L

Page : 2 of 2

1-2 days

**Remark:** Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: WEN ZHENG

Survey attended by:

Name : Kennerly  
Company : UKC  
Date : 18/8/18  
Time : 12pm  
Contact No : 969,0683  
Email : \_\_\_\_\_

Part : \$ 831.06

Labour : \$ 440.00

\$ 1271.06 - 20%

= \$ 1016.84