

REF: CS/FCI19014133/Ktd3ⁿ²

Special instruction.

Conveyor: Kenneth

ASSIGNMENT (Office)

From (Person): May chua of FCC Date/Time: 12.50pm @ 14/8/19

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKW 7460H Insured: SHD 33104

at Workshop m/s Siong Lee Tel: 6453 1255

of 160 8th Ming Drive # 02-07

Policy No: _____ Claim No: D19005204MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 8/8/2019
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{1up} H.O.D. Endorsement: _____

Date/Time: 3:05pm @ 14/8/19 Person Contacted: Kwee pin Vehicle IN OUT

Date/Time	Action/Instruction	Estimate
14/8/19	Ms. Kwee pin said estimate not yet ready so she ask to arrange for sunny tomorrow (15/8/19).	<input checked="" type="checkbox"/>
	SKW 7460H - CC4/MU16001830 / Uhh3y2	201: 23/01/2016
	SHD 33104 - CC3/CTI18013382 / GJ93y2	DOA: 20/7/2018

16/8 @ 3:27am - sent preli advise via email

ABS. REC. BY:

REF: FCI

ASSIGNMENT

From: _____ Date: 15/8/2019

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 74604

at Workshop n/s Siong Lee

of 160 Sin Ming Drive # 02-07

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: After 11 am

Veh No: SKW 74604 Yr Regn: 11 / 15

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 1598

Make: NIS ^{SA} S/10/ky C.C. 1498

Colour: M. Grey A/C: Insured / Std / NI / NA

Sp. Reading: 145 718 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MNTBBAB172 0024906

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$58k

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front	Rear
R/Bal. 7 mm	R/Bal. 4 mm
L/Bal. 7 mm	L/Bal. 4 mm
D.O.A. 8/8/19	D.O.I. 15/8/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
15/8	OK Tan said 1.B.1
Lump Sum \$1750+ (Red: 2783.69, 61%) confirm	

Date/Time, File Pass to? : Preli. Report

1) 28/8 Typst : Final Report

Date/Time, File Return to? _____

Days Of Repair: 4

Resurvey No. of Trip: _____

2) _____

Report Format: TP

Lump Sum / I.B.I. / \$ 1750+

Add Fee: Site Insp (\$))

Interview (\$))

Tech. Invs (\$))

Weekend (\$))

Survey Fee:	135
Transportation:	50
S + RS, SI	11
Plinks	
Others	
TOTAL	196



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005204MFSH

Date: 16/8/2019

Our Ref: CS/FCI19013857/Etd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SKW 7460H

Please be informed that we had conducted the inspection of the abovementioned vehicle
16/8/2019 at the premises of M/s Siong Lee have the following to report: -

Workshop Estimate Amount	: S\$ <u>4,533.69</u>
Revised Estimate Amount	: S\$ <u>2,199.18</u>
"Check" Items Amount	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the o/s front portion



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Kenneth Kong

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-08-2019	Our Ref No. D19005204MFSH
Accident Date	08-08-2019	Claim Type. Third Party
Insured Vehicle	SHD3310U	Third Party Vehicle. SKW7460H
Survey Location	160 SING MING DRIVE #02-07 AUTOCITY	
Contact Person.	MR TAN / MS KWEE PIN	
Contact No.	6453 1255/ 0	Fax No. 63373700
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIONG LEE MOTOR	Attention. NIL
Cc : TP Solicitor	CHEONGHOH LAW CORPORATION	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 16 August 2019 3:27 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'May Chua'; SUR
Subject: RE: SURVEY ASSESSMENT - D19005204MFSH/1
Attachments: PRELI ADVISED OF SKW 7460H.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SKW 7460H**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 14 August 2019 3:09 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'May Chua' <maychua@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005204MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer arrange survey on 15/08/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 14 August 2019 12:50 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; May Chua <maychua@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19005204MFSH/1

Denise Tay (LKKAuto)

From: twinauto@singnet.com.sg
Sent: Wednesday, 28 August 2019 2:10 PM
To: Denise Tay (LKKAuto)
Subject: Re: SKW 7460H / FIRST CAPITAL / DOA: 8/8/2019

Dear Denise

Accepted that amount @ \$1750.00 / 4days.

Thank you.
Regards

Siong Lee Motor
Tel: 6457 0410
Fax: 6552 0692

On Wed Aug 28 2019 10:41:54 GMT+0800 (Singapore Standard Time) Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

----- Original Message -----

Dear Madam,

Offer at \$1750/- lump sum 4 working days

Best Regards,
Denise Tay
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email:
sur@lkkauto.com
| fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



松 利 摩 哆
SIONG LEE MOTOR

Company Reg. No.: 100638/00J

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

14 August 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: LAU SING LI
H/P: 9638 9570

Dear Sirs / Madam,

Not Notified

11 Sep @ ?

*Resurvey After Paint
4 days*

**Accident Claim for Vehicle No. SKW 7460 H , Involving Vehicle No. SHD 3310 U,
Accident on 08 AUGUST 2019, AT 46 CORNWALL GARDEN.**

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	NETT PRICE
1	FRONT BONNET	1PC	\$ 1,030.00 <i>1,030</i>
2	FRONT BUMPER	1PC	\$ 655.20 <i>655</i>
3	FRONT BUMPER RETIANER - RH	1PC	\$ 38.70 <i>38</i>
4	HEADLAMP - RH	1PC	\$ 591.40 <i>591</i>
5	FRONT FENDER - RH	1PC	\$ 718.80 <i>718</i>
TOTAL LIST PRICE			\$ 3,034.10
LESS 10%			\$ (30.41)
TOTAL AMOUNT			\$ 3,003.69

LABOUR :			<i>720</i>
1	LABOUR TO SPRAY PAINT	\$	850.00
2	LABOUR TO PANEL BEATING	\$	<i>300</i> 680.00
TOTAL LABOUR		\$	1,530.00
TOTAL AMOUNT		\$	4,533.69

4260.69

THANK YOU

FROM:
SIONG LEE MOTOR
Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display (damage records) during resurvey
- Parts prices to be subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No litigation or court case allowed
- Supplemental charges to be reviewed and is subject to approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014133/Ktd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-09-2019	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3310U	Veh. Inspected	SKW 7460H
Policy No.		Coverage (\$)	0.00
Claim No.	D19005204MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	14/08/2019
2. Vehicle Particulars & Condition			
Make & Model	NISSAN SYLPHY (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0024906	Colour	METALLIC GREY
Odometer	145718	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	7 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	4 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	08/08/2019	Inspection Date	15/08/2019
Survey held at	160 SIN MING DRIVE # 02-07		
Repairer	SIONG LEE MOTOR		
5a. Remarks			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 7460H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BONNET	TO REPAIR SEE LABOUR	1,030.00	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	655.20	-
1	FRONT BUMPER RETAINER-RH	SERVICEABLE	38.70	-
1	HEADLAMP-RH	CRACKED	591.40	591.40
1	FRONT FENDER-RH	BENT	718.80	718.80
	LESS 10% DISCOUNT		-303.41	-131.02
			2,730.69	1,179.18
	LABOUR			
	LABOUR TO SPRAY PAINT.		850.00	720.00
	LABOUR TO PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT BONNET AND FRONT BUMPER.		680.00	300.00
			1,530.00	1,020.00
	GRAND TOTAL		4,260.69	2,199.18
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,750.00

Report Ref No. CS/FCI19014133/Ktd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.