

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

#

#

SUPPLEMENTARY ITEMS

Total Labour :	7,073.00
Total Parts :	7,133.16
Total Repair Costs less Excess:	14,206.16
GST @7%:	994.43
Grand Total :	15,200.59

	OD	ADD PARTS	DATE	WORKING DAYS
FAX TO FAX NO		Rasul Ltk	25/9/19	7
FAX TO FAX NO				
FAX TO FAX NO				
CONFIRMED DATE				
PLEASE FILL IN USE BY				

LOSS OF USE = \$100 X 9 DAYS
GIA SEARCH FEE - \$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 52320**
Date Estimated : **14/08/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Preeti Jain
19 Keppel View
#06-66
Singapore
SINGAPORE 098412

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA2729X	OJ00241	26/02/2016	X3 sDrive20	0
DESCRIPTION	ACCOUNT:	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, front bonnet, front right fender and front right wheel arch cover etc including to remove and install body parts in order to carry out painting job.		2,550.00	0	2,550.00
To respray front bumper, front bonnet and front right fender		3,164.00	0	3,164.00
To check steering geometry and conduct wheel alignment according to BMW specification		451.00	0	451.00
To replace right B1-Xenon headlight.		408.00	0	408.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.		150.00	0	150.00
To carry out body cavity preservation.		200.00	0	200.00
Sundries		150.00	0	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT RH FENDER	808.05	1	0	808.05
# FRT RH SIDE PANEL BOTTOM HOLDER	57.05	1	0	57.05
# RH MOUNT FOR SIDEWALL/HEADLIGHT	57.05	1	0	57.05
BONNET	1,731.16	1	0	1,731.16
CLADDING BUMPER FRT (PDC/SCHWARZ)	267.15	1	0	267.15
FRT BUMPER PANEL PRIMED	1,317.74	1	0	1,317.74
EMBLEM GROMMET	0.78	2	0	1.55
BMW EMBLEM	69.11	1	0	69.11
# EXPANDING RIVET*	0.65	3	0	1.95
# CLIP	2.00	2	0	4.00
# EXPANDING RIVET BLACK	1.35	20	0	27.00
FRT RH WHEEL ARCH COVER	179.75	1	0	179.75
# STRAINER FOR WASH PUMP	8.00	2	0	16.00
# WINDSHIELD CLEANING CONTAINER	146.75	1	0	146.75
# STRAINER F/WASH PUMP	11.20	1	0	11.20
RH BI XENON HEADLIGHT	2,437.65	1	0	2,437.65

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 52320**
Date Estimated : **14/08/2019**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -

Preeti Jain
19 Keppel View
#06-66
Singapore
SINGAPORE 098412

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLA2729X	OJ00241	26/02/2016	X3 sDrive20	0

DESCRIPTION	ACCOUNT:		
	ORIGINAL PRICE	DISC. %	NETT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# FRT RH SIDE PANEL BOTTOM HOLDER	57.05	1	0	57.05
# RH MOUNT FOR SIDEWALL/HEADLIGHT	57.05	1	0	57.05
# EXPANDING RIVET*	0.65	3	0	1.95
# CLIP	2.00	2	0	4.00
# EXPANDING RIVET BLACK	1.35	20	0	27.00
# STRAINER FOR WASH PUMP	8.00	2	0	16.00
# WINDSHIELD CLEANING CONTAINER	146.75	1	0	146.75
# STRAINER F/WASH PUMP	11.20	1	0	11.20
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	321.00
Total Labour & Parts :	321.00