

1552/00

INS. CASE OWNER:

Stammy

CC 4 ASM
AXA1901 4139 G p6322

LKK:

IDAC:

Surveyor:

XHQ

DOI:

ASSIGNMENT

7/15/19

Date / Time:

14/8/19

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SMA 3507B

Name of Insured:

VENKETAYAM S/O DEENATHAYAM

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

7/8/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L- YES / NO)

Claim No.:

SAM02WHB/17/113

Policy No.:

VPA/PN3128

Make / Model:

PONTIAC

Place of Accident:

STE (SE) TMS YIO LHM KAND

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJM 4037G

INSRS:
WSP:
Tel:
Liability:
RMKS:

Yong Sing

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SJM 4037G - X

SJM 4037G - A

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler/ Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

SS

2407.50 (as per AXA)

Loss of Rental (LOR):

SS

600.00 (5 days) X \$120

Loss of Use (LOU):

SS

(S x days)

Loss of Income (LOI):

SS

(S x days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

3014.95

Global Sum S\$:

3000.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3000.00

Name 1:

Yong Sing Motor Works

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

Signature

602

REF: ASM (AXH)

Hsiang Tong

ASSIGNMENT

From: Date: 15-8-2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJM 40376

at Workshop m/s Yong Sing
of 53 Refu Law 12

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10:30 am - 11:00 am over working

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$50k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SJM40376 Yr Regt: 31 Dec 2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Camry C.C. 2362

Colour: Silver A/C: Insured / Std / Nil / NA

Sp. Reading: 156421 T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No: MR053BK 4007030845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inoper / Jammed / Leaked / Burnt or

Brake: Inoper / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/50 R17

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 15-08-19

Survey held at w/s 10230

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

07/10 Finalized \$2350 with Zhu Yang
(Ref # 1219/844).

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair @ Replace (/) (Yang Sing Request)	Repair @ Replace (/) (Surveyor Recommend)
1	COVER, REAR BUMPER	5215906938	1	\$ 1,050.00	25%	\$ 787.50	Replace	495.5
2	RETAINER, REAR BUMPER SIDE, RH	5257506080	1	\$ 133.00	25%	\$ 99.75	Replace	
3	RETAINER, REAR BUMPER SIDE, LH	5257606080	1	\$ 133.00	25%	\$ 99.75	Replace	
4	SUPPORT, REAR BUMPER SIDE, NO 2 RH	5215706050	1	\$ 68.00	25%	\$ 66.00	Replace	
5	SUPPORT, REAR BUMPER SIDE, NO 2 LH	5215806050	1	\$ 68.00	25%	\$ 66.00	Replace	
6	REINFORCEMENT, WHEEL HOUSE, RH	5214796050	1	\$ 107.00	25%	\$ 80.25	Replace	
7	REINFORCEMENT, WHEEL HOUSE, LH	5214806050	1	\$ 107.00	25%	\$ 80.25	Replace	
8	REINFORCEMENT SUB-ASSY, REAR BUMPER	5202306081	1	\$ 560.00	25%	\$ 420.00	Replace	396.4
9	BUMPER CLIPS		10	\$ 30.00	25%	\$ 22.50	Replace	30
10	PANEL SUB-ASSY, BODY LOWER BACK	5830706120	1	\$ 760.00	25%	\$ 570.00	Replace	30
11	SEALANT SIKAFLEX		1	\$ 30.00	0%	\$ 30.00	Replace	SN
12	SENSOR, ULTRASONIC, NO 1	8934133180B0	1	\$ 450.00	25%	\$ 337.50	Replace	
13	SENSOR, ULTRASONIC, NO 2	8934133130B0	1	\$ 450.00	25%	\$ 337.50	Replace	
14	RETAINER, ULTRASONIC SENSOR, NO 1	8934833030C0	1	\$ 122.00	25%	\$ 91.50	Replace	
15	RETAINER, ULTRASONIC SENSOR, NO 2	8934833080C0	1	\$ 122.00	25%	\$ 91.50	Replace	
16	REFLECTOR ASSY, REFLEX, RH	8191048012	1	\$ 100.00	25%	\$ 75.00	Replace	
17	REFLECTOR ASSY, REFLEX, LH	8192048012	1	\$ 100.00	25%	\$ 75.00	Replace	
18	PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR	6440106330	1	\$ 1,360.00	25%	\$ 1,020.00	Replace	
19	WEATHERSTRIP, LUGGAGE COMPARTMENT DOOR	6446106080	1	\$ 240.00	25%	\$ 180.00	Replace	191.12
20	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, RH	6451006050	1	\$ 200.00	25%	\$ 150.00	Replace	
21	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, LH	6451006050	1	\$ 200.00	25%	\$ 150.00	Replace	
22	LOCK ASSY, LUGGAGE COMPARTMENT DOOR	6460006020	1	\$ 390.00	25%	\$ 292.50	Replace	
23	STRIKER, LUGGAGE COMPARTMENT DOOR LOCK	6462106050	1	\$ 110.00	25%	\$ 82.50	Replace	
24	PROTECTOR, BACK DOOR OUTSIDE GARNISH	7682506140	1	\$ 408.00	25%	\$ 306.00	Replace	128.85
25	EMBLEM, LUGGAGE COMPARTMENT DOOR	9097502084	1	\$ 155.00	25%	\$ 116.25	Replace	57.59
26	PLATE, BACK DOOR NAME, NO 2 (CAMRY)	9097502084	1	\$ 72.00	25%	\$ 54.00	Replace	43.61
27	PLATE, LUGGAGE COMPARTMENT DOOR NO 1 (2.4)	7544306220	1	\$ 72.00	25%	\$ 54.00	Replace	39.95
28	PLATE, REAR FLOOR FINISH (END PANEL GARNISH)	5838706080	1	\$ 338.00	25%	\$ 253.50	Replace	
29	COVER, LUGGAGE COMPARTMENT DOOR (REAR BOOT TRIM)	6471906090C0	1	\$ 440.00	25%	\$ 330.00	Replace	
30	LAMP ASSY, LICENSE PLATE	8127006052	1	\$ 208.00	25%	\$ 156.00	Replace	
31	NUMBER PLATE AND FRAME		1	\$ 40.00	0%	\$ 40.00	Replace	40 (SN)
32	LAMP ASSY, REAR COMBINATION, RH	8155006270	1	\$ 650.00	25%	\$ 487.50	Replace	496.6
33	LAMP ASSY, REAR COMBINATION, LH	8156006270	1	\$ 650.00	25%	\$ 487.50	Replace	496.6
34	LAMP ASSY, REAR, LH	8159006150	1	\$ 338.00	25%	\$ 253.50	Replace	
35	LAMP ASSY, REAR, RH	8158006150	1	\$ 338.00	25%	\$ 253.50	Replace	
36			1				Replace	
37			1				Replace	
38			1				Replace	
39			1				Replace	
40			1				Replace	
41			1				Replace	
42			1				Replace	
43			1				Replace	

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR REAR PORTION	\$1,300.00	400
Total Labour Cost	\$1,300.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY REAR BUMPER	\$500.00	200
TO RESPRAY REAR END PANEL	\$350.00	200
TO RESPRAY REAR BOOT LID	\$500.00	200
TO RESPRAY REAR BUMPER REINFORCEMENT	\$350.00	X N/N
Total Spray Painting Cost	\$1,700.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$150.00	40
TO TRANSFER REAR BOOT LID MECHANISM	\$150.00	X N/N
TO PROVIDE ANTI RUST COATING	\$200.00	X
TO CONDUCT WIRE CHECKING	\$100.00	30
TO VACUUM AND CLEAN ON INTERIOR	\$80.00	60
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$150.00	X N/N
Total Other Costs	\$830.00	\$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1130

11826.25%

2370.22

25%: 1777.66

SN: 40

2947.66


20%: 2350

Yong Sing Estimate Repair

Vehicle Registration Number : SJM 4037G
 Make / Model : CAMRY 2.4 AUTO ABS AIRBAG
 Chassis No : MR053BK4007030845
 Year of Manufacture : 2008
 Registration Date : 31-Dec-08
 Type of Repair (TP/OD/WS) : TP
 Date/Time of Accident : 7 AUGUST 2019 / 09:25 hrs
 Rental Vehicle : Yes ☒ No
 Remark : TP

Case Ref. No. : YS/19/0069

The damages on the vehicle are as indicated in the following diagram :



	Yong Sing estimate breakdown cost	Adjusted by Surveyor, if applicable
Total Labour Cost	\$ 1,300.00	\$ -
Total Spray Painting Cost	\$ 1,700.00	\$ -
Total Spare Parts Cost	\$ 10,639.00	\$ -
Other Charges	\$ 830.00	\$ -
TOTAL	\$ 14,469.00	\$ -
Lump Sum Repair, if any :		
No. of Repair Days	[7] days	[] days

SURVEYOR'S Remark

4 Days.
 Lumpsum repair.
 After repair photos.
 En. Qiao - 82880282
 15/8/19.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Part 1 - Labour & Panel Beating Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO REMOVE & INSTALL ALL REPLACE ITEM, TO REPAIR REAR PORTION	\$1,300.00	400
Total Labour Cost	\$1,300.00	\$0.00

Part 2 - Spray Painting Related Works

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO RESPRAY REAR BUMPER	\$500.00	200
TO RESPRAY REAR END PANEL	\$350.00	200
TO RESPRAY REAR BOOT LID	\$500.00	200
TO RESPRAY REAR BUMPER REINFORCEMENT	\$350.00	X NN
Total Spray Painting Cost	\$1,700.00	\$0.00

Part 3 - Other Costs - Accident Repair Related Expenses

Job Scope	Yong Sing Estimate	Surveyor Adjustment
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$150.00	40.
TO TRANSFER REAR BOOT LID MECHANISM	\$150.00	X NN
TO PROVIDE ANTI RUST COATING	\$200.00	?
TO CONDUCT WIRE CHECKING	\$100.00	30.
TO VACCUMM AND CLEAN ON INTERIOR	\$80.00	60.
TO CHECK WATER LEAKAGE ON INSTALLED PARTS	\$150.00	X. NN
Total Other Costs	\$830.00	\$0.00

Part 4 - Spare Parts / Material Usage

Item	Part Name	Part No	Qty	List Price (\$)	Discount (25%)	Final Price (\$)	Repair ® Replace (/) (Yong Sing Request)	Repair ® Replace (/) (Surveyor Recommend)
1	COVER, REAR BUMPER <i>de</i>	5215906938	1	\$ 1,050.00	25%	\$ 787.50	Replace	
2	RETAINER, REAR BUMPER SIDE, RH <i>X</i>	5257506080	1	\$ 133.00	25%	\$ 99.75	Replace	
3	RETAINER, REAR BUMPER SIDE, LH <i>X</i>	5257606080	1	\$ 133.00	25%	\$ 99.75	Replace	
4	SUPPORT, REAR BUMPER SIDE, NO.2 RH <i>X</i> <i>NN</i>	5215706050	1	\$ 88.00	25%	\$ 66.00	Replace	
5	SUPPORT, REAR BUMPER SIDE, NO.2 LH <i>X</i>	5215806050	1	\$ 88.00	25%	\$ 66.00	Replace	
6	REINFORCEMENT, WHEEL HOUSE, RH <i>?</i>	6164706050	1	\$ 107.00	25%	\$ 80.25	Replace	
7	REINFORCEMENT, WHEEL HOUSE, LH <i>?</i>	6164806050	1	\$ 107.00	25%	\$ 80.25	Replace	
8	REINFORCEMENT SUB-ASSY, REAR BUMPER <i>?</i>	5202306081	1	\$ 560.00	25%	\$ 420.00	Replace	
9	BUMPER CLIPS <i>all</i>		10	\$ 30.00	25%	\$ 22.50	Replace	
10	PANEL SUB-ASSY, BODY LOWER BACK <i>X</i> <i>NN</i>	5830706120	1	\$ 760.00	25%	\$ 570.00	Replace	
11	SEALANT SIKAFLEX <i>?</i>		1	\$ 30.00	0%	\$ 30.00	Replace	
12	SENSOR, ULTRASONIC, NO.1 <i>X</i> <i>NN</i>	8934133180B0	1	\$ 450.00	25%	\$ 337.50	Replace	
13	SENSOR, ULTRASONIC, NO.2 <i>X</i> <i>NN</i>	8934133130B0	1	\$ 450.00	25%	\$ 337.50	Replace	
14	RETAINER, ULTRASONIC SENSOR, NO.1 <i>all</i>	8934833030C0	1	\$ 122.00	25%	\$ 91.50	Replace	
15	RETAINER, ULTRASONIC SENSOR, NO.2 <i>all</i>	8934833080C0	1	\$ 122.00	25%	\$ 91.50	Replace	
16	REFLECTOR ASSY, REFLEX, RH <i>X</i> <i>NN</i>	8191048012	1	\$ 100.00	25%	\$ 75.00	Replace	
17	REFLECTOR ASSY, REFLEX, LH <i>X</i> <i>NN</i>	8192048012	1	\$ 100.00	25%	\$ 75.00	Replace	
18	PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR <i>X</i> <i>NN</i>	6440106330	1	\$ 1,360.00	25%	\$ 1,020.00	Replace	
19	WEATHERSTRIP, LUGGAGE COMPARTMENT DOOR <i>?</i>	6446106080	1	\$ 240.00	25%	\$ 180.00	Replace	
20	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, RH <i>X</i>	6451006050	1	\$ 200.00	25%	\$ 150.00	Replace	
21	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, LH <i>X</i>	6451006050	1	\$ 200.00	25%	\$ 150.00	Replace	
22	LOCK ASSY, LUGGAGE COMPARTMENT DOOR <i>X</i> <i>NN</i>	6460006020	1	\$ 390.00	25%	\$ 292.50	Replace	
23	STRIKER, LUGGAGE COMPARTMENT DOOR LOCK <i>X</i>	6462106050	1	\$ 110.00	25%	\$ 82.50	Replace	
24	PROTECTOR, BACK DOOR OUTSIDE GARNISH <i>scr</i>	7682506140	1	\$ 408.00	25%	\$ 306.00	Replace	
25	EMBLEM, LUGGAGE COMPARTMENT DOOR <i>all</i>	9097502064	1	\$ 155.00	25%	\$ 116.25	Replace	
26	PLATE, BACK DOOR NAME, NO.2 (CAMRY) <i>all</i>	9097502064	1	\$ 72.00	25%	\$ 54.00	Replace	
27	PLATE, LUGGAGE COMPARTMENT DOOR, NO.3 (2.4) <i>all</i>	7544306220	1	\$ 72.00	25%	\$ 54.00	Replace	
28	PLATE, REAR FLOOR FINISH (END PANEL GARNISH) <i>X</i>	5838706080	1	\$ 338.00	25%	\$ 253.50	Replace	
29	COVER, LUGGAGE COMPARTMENT DOOR (REAR BOOT TRIM) <i>X</i> <i>NN</i>	6471906090C0	1	\$ 440.00	25%	\$ 330.00	Replace	
30	LAMP ASSY, LICENSE PLATE <i>X</i> <i>NN</i>	8127006052	1	\$ 208.00	25%	\$ 156.00	Replace	
31	NUMBER PLATE AND FRAME <i>/</i>		1	\$ 40.00	0%	\$ 40.00	Replace	
32	LAMP ASSY, REAR COMBINATION, RH <i>?</i>	8155006270	1	\$ 650.00	25%	\$ 487.50	Replace	
33	LAMP ASSY, REAR COMBINATION, LH <i>?</i>	8156006270	1	\$ 650.00	25%	\$ 487.50	Replace	
34	LAMP ASSY, REAR, LH <i>X</i> <i>NN</i>	8159006150	1	\$ 338.00	25%	\$ 253.50	Replace	
35	LAMP ASSY, REAR RH <i>X</i> <i>NN</i>	8158006150	1	\$ 338.00	25%	\$ 253.50	Replace	
36			1				Replace	
37			1				Replace	
38			1				Replace	
39			1				Replace	
40			1				Replace	
41			1				Replace	
42			1				Replace	
43			1				Replace	

44			1				Replace	
45			1				Replace	
47			1				Replace	
TOTAL MATERIALS \$ 10,639.00 \$ 7,996.75								

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	767H
Vehicle Details	
Vehicle No.:	SJM4037G
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	TOYOTA
Vehicle Model:	CAMRY 2.4 AUTO ABS AIRBAG
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	2AZE118692
Chassis No.:	MR053BK4007030845
Maximum Power Output:	123.0 kW (164 bhp)
Open Market Value:	\$27,261.00
Original Registration Date:	31 Dec 2008
First Registration Date:	31 Dec 2008
Transfer Count:	1
Actual ARF Paid:	\$27,261.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Dec 2028
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$31,553.00
COE Rebate Amount:	\$29,576.00
Total Rebate Amount:	\$29,576.00

The information contained herein is correct as at 15 Aug 2019

OK



Service Request Details

Claim

S9M01WHD

Reference

None 

Loss Date

August 7, 2019

Report Date

Aug 13, 2019 9:38:00 AM

Request Date

August 13, 2019

Due Date

August 20, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

P: zhi yang

T: 3.49 p.m

V: Out

E: ✓

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJM4037G

Model

CAMRY

Service Address

...

Primary Contact/Insured

DEENATHAYALU VENKATROYALU S/O
1C CANTONMENT ROAD, #24-31, 085301, Singapore
91444570
VROYALU@YAHOO.COM

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions

6

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

[New Message](#)

Catherine Chong (LKK Auto)

From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Sent: Saturday, 10 August, 2019 12:58 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: yongsingmotors@gmail.com; Jason Sim
Subject: [EXTERNAL] 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SMA 3507B
Attachments: SJM4037G Accident on 07 August 2019.pdf

Categories: Shekhar

Attention Motor Claims Department.

Our Ref: SJM 4037G

DOA: 07-08-2019

Dear Sir/Mdm

RE: 3rd PARTY CLAIMS AGAINST YOUR INSURED VEHICLE SMA 3507B
Kindly refer to attachment for our client's SAS report and our estimated cost of repair (based on our visual inspection only) for our client's vehicle, for your perusal.

We would like to check on liability and appreciate if you could confirm your agreement on direct settlement with us for COR and claim for LOU \$150/day or rental \$200/day. Number of days will be in accordance with your surveyor's recommendation.

Please provide a list of surveyors to choose from and you may then arrange to survey our client's vehicle to be survey at No. 53 Defu Lane 12, Singapore 539144.

We thank you in advance for your assistance in this matter.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315

YS 榮興 **YONG SING**
MOTOR WORKS

Hsiao Tong (LKKAUTO)

From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Sent: Monday, 7 October 2019 7:10 PM
To: Guo Qiang (LKKAUTO); Shu Pei (LKKAUTO); Hsiao Tong (LKKAUTO)
Cc: yongsingmotors@gmail.com; Jason Sim
Subject: RE: Finalise for SJM 4037G
Attachments: LOD SJM4037G.pdf; RENTAL AGREEMENT.pdf; receipt-20190810-125036.pdf; INVOICE SJM4037G.pdf

Hi LKK,

Please refer to the attachment.

Kindly please let us know when is the payment for this case

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Saturday, October 5, 2019 10:24:43 AM
To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasonsimm@yongsingmotor.com>
Subject: RE: Finalise for SJM 4037G

Hi Guo Qiang,

We accept the amount of \$2350 before GST and 4 working days

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>
Sent: Thursday, October 3, 2019 9:37:01 AM
To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Hsiao Tong

(LKKAUTO) <chewht@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasonsims@yongsingmotor.com>

Subject: RE: Finalise for SJM 4037G

Hi Zhi Yang,

Confirmed COR \$2350 before GST @ 4 working days.

Regards,
Guo Qiang

From: Zhi Yang Phua [mailto:ZhiYangPHUA@yongsingmotor.com]
Sent: Tuesday, 1 October, 2019 8:27 PM
To: Guo Qiang (LKKAUTO); Shu Pei (LKKAUTO); Shiao Chan (LKKAUTO)
Cc: yongsingmotors@gmail.com; Jason Sim
Subject: RE: Finalise for SJM 4037G

Hi Guo Qiang,

As spoken, here are the revise finalised amount for SJM 4037G

Finalise for SJM 4037G

Our COR for the above mentioned vehicle is \$2,358.13 excluding GST.

Lumpsum repair job and 04 repair days were given.

Please take note that we are registered with GST.

Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Friday, September 20, 2019 10:01:31 AM
To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Shiao Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasonsims@yongsingmotor.com>
Subject: RE: Finalise for SJM 4037G

Hi LKK,

Please revert to us soonest possible

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua

Sent: Monday, September 9, 2019 9:43:24 AM

To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Shiao Chan (LKKAUTO) <siewsc@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>

Subject: FW: Finalise for SJM 4037G

Hi Guo Qiang,

Kindly please finalize with us soonest possible

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua

Sent: Sunday, September 1, 2019 3:43:14 PM

To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>

Subject: Finalise for SJM 4037G

Hi Guo Qiang,

Re: Finalise for SJM 4037G

Our COR for the above mentioned vehicle is \$3,414.60 excluding GST.

Part by Part repair job and 04 repair days were given.

Please take note that we are registered with GST.

Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>

Sent: Monday, August 26, 2019 1:18:13 PM

To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>

Subject: AFTER PAINT PHOTO FOR SJM4037G

Dear Guo Qiang,

As requested by you, please see attached after paint photo for SJM4037G. We will contact the driver to pick up the vehicle in the next couple of hours.

Please assist to finalised this case as soon as possible. Thank you for your assistance.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Yong Sing

Sent: Monday, 26 August 2019 1:14 PM

To: Guo Qiang (LKKAUTO)

Cc: Zhi Yang Phua

Subject: AFTER PAINT PHOTO FOR SJM4037G

Dear Guo Qiang,

As requested by you, please see attached after paint photo for SJM4037G. We will contact the driver to pick up the vehicle in the next couple of hours.

Please assist to finalised this case as soon as possible. Thank you for your assistance.

With Regards,

Sam Sim (Mr)

Executive

Mobile: 9182 0027 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144

☒



<TP - Mandate IA> - S9M01WHD [ACCIDENT INVOLVING SMA 3507B(OI) & SJM 4037G(TP) ON 07/08/2019]

Type

🔔 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,271.95(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 14-Oct-19

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/10/2019

Survey Details:

Date of loss	7-Aug-19
Date of appointment	14-Aug-19
Date of survey	15-Aug-19
Location of survey	YONG SING MOTOR WORKS

Vehicle Details:

Claim Type:	Third party
Vehicle number	SJM 4037G
Make and Model	TOYOTA CAMRY 2.4 A
Date of registration	31/12/2008
Excess	NIL
Market Value	\$52,000
Parf Rebate	\$29,576
Nett Loss	\$22,424

Repair details:

Initial Estimate	\$ 14,469.00
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 2,000.67
Check items (estimate)	NIL
Labour	\$ 1,130.00
Total	\$ 3,130.67
Lump Sum(if applicable)	\$ 2,350.00
Number of days for repair	4



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

OI REAR-ENDED THIRD PARTY.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$	2,514.50
Loss of use		NIL no. of days
Loss of rental	\$	750.00 (5days x \$150.00)
Loss of income		NIL no. of days
LTA search fees	\$	7.45
Others		NIL
Proposed Total	\$	3,271.95

Hsiao Tong (LKKAUTO)

From: Shu Pei (LKKAUTO)
Sent: Tuesday, 15 October 2019 12:33 PM
To: Hsiao Tong (LKKAUTO)
Subject: RE: New message for service request 131113, vehicle number SJM4037G

] ESTIMATE & SURVEYOR ASSIGNMENT PAPER PASS TO HANDLER	LSP	19/8/2019 11:16:27 AM
] **PENDING COR RECOMMENDATION	CHT	2/9/2019 8:01:49 AM
] Message AXA : Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$3,271.95 (all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong – 14-Oct-19	CHT	14/10/2019 8:49:25 AM
] 10/15/19 11:55 AM NG Stacey-----Hi please start off negotiation from \$2280 for repair cost (Lumpsum) to max \$2400 for repair cost. thanks.	LSP	15/10/2019 12:20:55 PM

Best Regards,
Shu Pei | Admin
LKK Auto Consultants Pte Ltd
Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Tuesday, 15 October 2019 12:08 PM
To: Admin A <admin-a@lkkauto.com>
Subject: FW: New message for service request 131113, vehicle number SJM4037G

Best Regards,
Summer Lee | Admin
LKK Auto Consultants Pte Ltd
Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: stacey.ng@axa.com.sg <stacey.ng@axa.com.sg>
Sent: Tuesday, 15 October, 2019 11:57 AM
To: admin-d@lkkauto.com
Subject: New message for service request 131113, vehicle number SJM4037G

AXA Insurance has sent you a message for claim number S9M01WHD.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

Hsiao Tong (LKKAUTO)

From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Sent: Monday, 4 November 2019 4:56 PM
To: Hsiao Tong (LKKAUTO)
Cc: yongsingmotors@gmail.com; Jason Sim; Guo Qiang (LKKAUTO); Admin A
Subject: RE: Finalise for SJM 4037G //LKK REF: CC4/ASM19014139/Gpb3

Hi Hsiao Tong,

We accepted the offer \$3000.

Please let us know for the payment for this vehicle

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, October 26, 2019 12:02:19 PM
To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasonsims@yongsingmotor.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Finalise for SJM 4037G //LKK REF: CC4/ASM19014139/Gpb3

Without Prejudice

Dear Sirs/Mdm,

We refer to the above matter.

We propose settlement at a global sum of \$3,000.00(all-in).

Please confirm acceptance.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>

Sent: Monday, 7 October 2019 7:10 PM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Cc: yongsingmotors@gmail.com; Jason Sim <jasons@yongsingmotor.com>

Subject: RE: Finalise for SJM 4037G

Hi LKK,

Please refer to the attachment.

Kindly please let us know when is the payment for this case

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua

Sent: Saturday, October 5, 2019 10:24:43 AM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>

Subject: RE: Finalise for SJM 4037G

Hi Guo Qiang,

We accept the amount of \$2350 before GST and 4 working days

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>

Sent: Thursday, October 3, 2019 9:37:01 AM

To: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>

Subject: RE: Finalise for SJM 4037G

Hi Zhi Yang,

Confirmed COR \$2350 before GST @ 4 working days.

Regards,
Guo Qiang

From: Zhi Yang Phua [mailto:ZhiYangPHUA@yongsingmotor.com]
Sent: Tuesday, 1 October, 2019 8:27 PM
To: Guo Qiang (LKKAUTO); Shu Pei (LKKAUTO); Shiau Chan (LKKAUTO)
Cc: yongsingmotors@gmail.com; Jason Sim
Subject: RE: Finalise for SJM 4037G

Hi Guo Qiang,

As spoken, here are the revise finalised amount for SJM 4037G

Finalise for SJM 4037G

Our COR for the above mentioned vehicle is \$2,358.13 excluding GST.

Lumpsum repair job and 04 repair days were given.

Please take note that we are registered with GST.

Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Friday, September 20, 2019 10:01:31 AM
To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupeil@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasonsims@yongsingmotor.com>
Subject: RE: Finalise for SJM 4037G

Hi LKK,

Please revert to us soonest possible

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Monday, September 9, 2019 9:43:24 AM
To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>; Shu Pei (LKKAUTO) <shupe@lkkauto.com>; Shiao Chan (LKKAUTO) <siewsc@lkkauto.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>
Subject: FW: Finalise for SJM 4037G

Hi Guo Qiang,

Kindly please finalize with us soonest possible

With Regards,

Phua Zhi Yang

Operation Supervisor
Mobile: 9101 7563 Fax: 6284 2798
No: 53, Defu Lane 12 Singapore 539144 (Head Office)
No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua
Sent: Sunday, September 1, 2019 3:43:14 PM
To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>
Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>; Jason Sim <jasons@yongsingmotor.com>
Subject: Finalise for SJM 4037G

Hi Guo Qiang,

Re: Finalise for SJM 4037G

Our COR for the above mentioned vehicle is \$3,414.60 excluding GST.

Part by Part repair job and 04 repair days were given.

Please take note that we are registered with GST.

Please refer to the attachment.

We hope to hear from your confirmation soon. Thank you.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Zhi Yang Phua <ZhiYangPHUA@yongsingmotor.com>

Sent: Monday, August 26, 2019 1:18:13 PM

To: Guo Qiang (LKKAUTO) <guoqiang@lkkauto.com>

Cc: yongsingmotors@gmail.com <yongsingmotors@gmail.com>

Subject: AFTER PAINT PHOTO FOR SJM4037G

Dear Guo Qiang,

As requested by you, please see attached after paint photo for SJM4037G. We will contact the driver to pick up the vehicle in the next couple of hours.

Please assist to finalised this case as soon as possible. Thank you for your assistance.

With Regards,

Phua Zhi Yang

Operation Supervisor

Mobile: 9101 7563 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144 (Head Office)

No: 10, Defu Lane 8 Singapore 539315



From: Yong Sing

Sent: Monday, 26 August 2019 1:14 PM

To: Guo Qiang (LKKAUTO)

Cc: Zhi Yang Phua

Subject: AFTER PAINT PHOTO FOR SJM4037G

Dear Guo Qiang,

As requested by you, please see attached after paint photo for SJM4037G. We will contact the driver to pick up the vehicle in the next couple of hours.

Please assist to finalised this case as soon as possible. Thank you for your assistance.


With Regards,

Sam Sim (Mr)

Executive

Mobile: 9182 0027 Fax: 6284 2798

No: 53, Defu Lane 12 Singapore 539144



AXA INSURANCE SINGAPORE PTE LTD
AXA Tower
8 Shenton Way
#27-01/02
Singapore 068811

MOTOR CLAIMS DEPT

Date: 27-09-2019

Our Ref: SJM4037G
Your Ref: SMA3507B

Dear Sir/Madam,

ACCIDENT INVOLVING SJM4037G AND SMA3507B ON 07-08-2019 ALONG SLIP RD FROM CTE TOWARDS YIO CHU KANG ROAD

LETTER OF CLAIM

We claim on behalf of **ONG CHWEE KIAT** owner of the vehicle No. **SJM4037G**. Your driver's negligent driving has caused the above accident. As a result, my client has suffered the following losses: -

1. Cost of Repair (Invoice 20116)	\$ 2,514.50
2. Loss of Use for ___ days @ S\$ 0.00 /day	\$ 0.00
3. Loss of Rental for 5 Days @ S\$ 180 /day	\$ 900.00
4. Loss of Income for _____ days @ S\$ _____/day	\$ 0.00
5. Police Report/ SAS Report/ LTA Search Fee	\$ 7.49
6. Survey Fee	-

Total Claims : \$ 3,421.99

We enclose the following documents:

- | | |
|---|--|
| ☐ Repair Invoice | ☐ Letter of Authorisation |
| ☐ Survey Report | ☐ LTA Search result |
| ☐ Photographs _____ pcs | ☐ Others : |
| ☐ Investigation results | 1. <input type="text"/> |
| ☐ Proof of Loss of Use/Rental/Income | 2. <input type="text"/> |

We look forward to your confirmation to settle our claims within 15 days from the date of this letter. Payment by cheque shall be crossed and made payable to YONG SING MOTOR WORKS for amount of **\$ 3,421.99**

Yours sincerely,
PHUA ZHI YANG

Operation Supervisor,
YONG SING MOTOR WORKS

BILL TO: AXA INSURANCE SINGAPORE PTE LTD

TAX INVOICE

NO: 20116

DATE: 27-Sep-19

SALESPERSON	VEHICLE/EQPT NO.	MAKE/MODEL	PO NO.	OUR REF. NO.
ZHI YANG	SJM 4037G	TOYOTA CAMRY		

DESCRIPTION	\$ AMOUNT
TO PROVIDE LABOUR AND MATERIAL FOR REPAIR TO ACCIDENT VEHICLE AS APPROVED BY SURVEYOR	2,350.00

NOTE:

All cheques should be crossed and made payable to Yong Sing Motor Works
For bank transfer, please indicate our invoice number:
Current a/c no.: 556-743532-001
Bank code: 7339 Branch code: 556

NET: \$	2,350.00
GST 7%: \$	164.50
GRAND TOTAL: \$	2,514.50

Customer's Acceptance & Satisfaction

Signature

Yong Sing Motor Works

Authorised Signature



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM19014139/Gpb3s2		
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811 ATTN: STACEY NG		Date : 13-11-2019		
		Code : ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMA 3507B	Veh. Inspected	SJM 4037G	
Policy No.	VPA/P2131128	Coverage (\$)	0.00	
Claim No.	S9M01WHD	Excess (\$)	0.00	
Assign From	STACEY NG	Assign Date	14/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY	c.c	2362	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	MR053BK4007030845	Colour	SILVER	
Odometer	156421	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R17	GOODYEAR	6 mm	
L/H Front Tyre	225/50 R17	GOODYEAR	6 mm	
R/H Rear Tyre	225/50 R17	GOODYEAR	6 mm	
L/H Rear Tyre	225/50 R17	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/08/2019	Inspection Date	15/08/2019	
Survey held at	YONG SING MOTOR WORKS 53 DEFU LANE 12 #01-01 SINGAPORE 539144			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJM 4037G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	COVER, REAR BUMPER (CONSISTENT)	DEFORMED	1,050.00	499.50
1	RETAINER, REAR BUMPER SIDE, RH (CONSISTENT)	NOT NECESSARY	133.00	-
1	RETAINER, REAR BUMPER SIDE, LH (CONSISTENT)	NOT NECESSARY	133.00	-
1	SUPPORT, REAR BUMPER SIDE, NO.2 RH (CONSISTENT)	NOT NECESSARY	88.00	-
1	SUPPORT, REAR BUMPER SIDE, NO.2 LH (CONSISTENT)	NOT NECESSARY	88.00	-
1	REINFORCEMENT, WHEEL HOUSE, RH (CONSISTENT)	NOT NECESSARY	107.00	-
1	REINFORCEMENT, WHEEL HOUSE, LH (CONSISTENT)	NOT NECESSARY	107.00	-
1	REINFORCEMENT SUB-ASSY, REAR BUMPER (CONSISTENT)	BENT	560.00	396.40
10	BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	PANEL SUB-ASSY, BODY LOWER BACK (CONSISTENT)	TO REPAIR SEE LABOUR	760.00	-
1	SENSOR ULTRASONIC, NO.1 (CONSISTENT)	NOT NECESSARY	450.00	-
1	SENSOR ULTRASONIC, NO.2 (CONSISTENT)	NOT NECESSARY	450.00	-
1	RETAINER ULTRASONIC, SENSOR, NO.1 (CONSISTENT)	NECESSARY	122.00	122.00
1	RETAINER ULTRASONIC, SENSOR, NO.2 (CONSISTENT)	NECESSARY	122.00	122.00
1	REFLECTOR ASSY, REFLEX, RH (CONSISTENT)	NOT NECESSARY	100.00	-
1	REFLECTOR ASSY, REFLEX, LH (CONSISTENT)	NOT NECESSARY	100.00	-
1	PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR (CONSISTENT)	TO REPAIR SEE LABOUR	1,360.00	-
1	WEATHERSTRIP, LUGAGGE COMPARTMENT DOOR (CONSISTENT)	TORN	240.00	191.12
1	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, RH (CONSISTENT)	NOT NECESSARY	200.00	-
1	HINGE ASSY, LUGGAGE COMPARTMENT DOOR, LH (CONSISTENT)	NOT NECESSARY	200.00	-
1	LOCK ASSY, LUGGAGE COMPARTMENT DOOR (CONSISTENT)	NOT NECESSARY	390.00	-
1	STRIKER, LUGGAGE COMPARTMENT DOOR LOCK (CONSISTENT)	NOT NECESSARY	110.00	-
1	PROTECTOR, BACK DOOR OUTSIDE GARNISH (CONSISTENT)	SCRATCHED	408.00	128.85
1	EMBLEM, LUGGAGE COMPARTMENT DOOR (CONSISTENT)	NECESSARY	155.00	47.59

Report Ref No. CC4/ASM19014139/Gpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	PLATE, BACK DOOR NAME. NO. 2 (CAMRY) (CONSISTENT)	NECESSARY	72.00	43.61
1	PLATE, LUGGAGE COMPARTMENT DOOR, NO. 3 (2.4) (CONSISTENT)	NECESSARY	72.00	39.95
1	PLATE, REAR FLOOR FINISH (END PANEL GARNISH) (CONSISTENT)	NOT NECESSARY	338.00	-
1	COVER, LUGGAGE COMPARTMENT DOOR (REAR BOOT TRIM) (CONSISTENT)	NOT NECESSARY	440.00	-
1	LAMP ASSY, LICENCE PLATE (CONSISTENT)	NOT NECESSARY	208.00	-
1	LAMP ASSY, REAR COMBINATION, RH (CONSISTENT)	CRACKED	650.00	496.60
1	LAMP ASSY, REAR COMBINATION, LH (CONSISTENT)	CRACKED	650.00	496.60
1	LAMP ASSY, REAR LH (CONSISTENT)	NOT NECESSARY	338.00	-
1	LAMP ASSY, REAR RH (CONSISTENT)	NOT NECESSARY	338.00	-
	LESS 25% DISCOUNT		-2,642.25	-653.55
			7,926.75	1,960.67
	SPECIAL NETT ITEMS			
1	SEALANT SIKAFLEX (SN) (CONSISTENT)	NOT NECESSARY	30.00	-
1	NUMBER PLATE AND FRAME (SN) (CONSISTENT)	SCRATCHED	40.00	40.00
			70.00	40.00
	LABOUR			
	TO REMOVE & INSTALL ALL REPLACE ITEM. TO REPAIR REAR PORTION. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY LOWER BACK AND PANEL SUB-ASSY, LUGGAGE COMPARTMENT DOOR.		1,300.00	400.00
	TO RESPRAY REAR BUMPER.		500.00	200.00
	TO RESPRAY REAR END PANEL.		350.00	200.00
	TO RESPRAY REAR BOOT LID.		500.00	200.00
	TO RESPRAY REAR BUMPER REINFORCEMENT.	NOT NECESSARY	350.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		150.00	40.00
	TO TRANSFER REAR BOOT LID MECHANISM.	NOT NECESSARY	150.00	-
	TO PROVIDE ANTI RUST COATING.	NOT NECESSARY	200.00	-
	TO CONDUCT WIRE CHECKING.		100.00	30.00
	TO VACUUM AND CLEAN ON INTERIOR.		80.00	60.00

Report Ref No. CC4/ASM19014139/Gpb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WATER LEAKAGE ON INSTALLED PARTS.	NOT NECESSARY	150.00	-
			3,830.00	1,130.00
GRAND TOTAL			11,826.75	3,130.67
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CC4/ASM19014139/Gpb3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.