

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M1002081-X



Supplementary

Estimate No. : b1 52313
Date Estimated : 14/08/2019
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -

Koh Yong Mong
86 Cardiff Grove

Singapore 558952

- ACCOUNT - 66

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SML304G	WBAJG120603G776	30/04/2019	X1 sDrive18i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
# To supply rear right tyre (80%) <i>cut ✓</i>	360.00	0	360.00 ✓
# To knock out tail end panel	425.00	0	425.00 ✓
# To respray tail end panel and luggage compartment floor plate.	1,386.00	0	1,386.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
#				
# BLIND RIVET NUT WITH COLLAR M5 <i>rec ✓</i>	5.30	2	0	10.60
# PLUG IN NUT <i>rec ✓</i>	3.05	4	0	12.20
# BLIND RIVET NUT <i>rec ✓</i>	3.85	1	0	3.85
#				
#				

SUPPLEMENTARY ITEMS

Total Labour :	2,171.00
Total Parts :	26.65
Total Repair Costs less Excess:	2,197.65