Trans; cab Auto Services Pte Ltd

No. 2 Any Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SMM 7455C

ab Auto Services Pte Ltd			
Mo Kio Street 63 Singapore 569111	Nos	1 dhains	
5287 6666 Fax No. : 6257 1330		100 Man re	
Reg. No. 201019626G	Reson	Notherine	
55C		7 0 7 7	
		83842-15	
Vehicle No.:	SMM 7	SMM 7455C	
Chassis No.:	MR053	REH604597966	
Vehicle Make:	TOYOT	TOYOTA	
Vehicle Model:	COROL	COROLLA ALTIS	
Date of Accident :			
Third Party Insurer :	AIG		
Date of Registration:	12/7/20	019	
PART		LIST	
FRONT BUMPER	\$	Bu 531.10 -	
FRONT FENDER SUB-ASSY —>	\$	By 908.70 -	
FRONT FENDER, LINER	\$	5 227.00 x	
FRONT FENDER RETAINER	\$	em 8.60 -	
FRONT LEFT HEADLAMP	\$	cm 2,487.80	
TO	TAL \$	4,163.20	
	5% \$	1,040.80	
	\$	3,122.40	
Special Nett			
FENDER INNER TRIM CLIP RH	\$	~~ 28.00 X	
	AL \$	28.00	
TOTAL PAI	RTS \$	3,150.40	
LAROUR			
LABOUR			
To remove and refit interior fittings, trimings, garnish	١,		
fittings and other, to enable repair.	\$	380.00 X	
Putty and spray painting of the affected portion.	\$	2,800.00 4	
Panel beating, knocking and straightening the			
necessary portion, remove and renewal of parts, adju	ıst		
and realign the same	\$	2,800.00 40	
To check steering geometry and computer wheel			
alignment	\$	220.00 X	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SMM 7455C

PART BY PART (REPAIR DAY)	10 DAYS	
Over All Total	\$ 10,240.40	=
TOTAL	\$ 7,090.00	
To transfer of tire, rim and on wheel balancing.	\$ NW 170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ 380.00	×
To rust-proofing of the affected areas.	\$ 170.00	301
To Check Electrical Lighting Concerned.	\$ 170.00	201

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature: