

ASS. REC. BY:

Surveyor: RusuREF es/FCI/9014152/Rld3ⁿ²

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Joanne Yong

of

FCI

Date/Time:

4:32pm @ 14/8/19

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

UBE 97655

Insured:

SHC2987D

at Workshop m/s

Sin Sheng Engineering

Tel:

68639595

of

No. 8 Tuas Avenue 18 (Level 3)

Policy No:

Claim No:

D19005156MPSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 6/8/2019

CA / REV / REP. / REV 24 HRS

(DS)15/8/19

H.O.D. Endorsement:

Date/Time:

4:42pm @ 14/8/19

Person Contacted:

gugenVehicle IN / OUT

Date/Time

Action/Instruction

Polymold ✓UBE 97655 - XSHC 2987D - CS/FCI/18003793/71vd392DoA: 24/2/201816/8/19@ 17:50 pm revised PA to Joanne Yong via email


Rasul

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: **GBE 97655**
at Workshop m/s: **SIN SENG ENGINEERING**
of **No. 8, THIAS AVE 18**
Insured: **FCU**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: **7** days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **GBE 97655** Yr Regn: **2016 / MAY**
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: **FIAT DOBLO CARHOMAX 1.6 cc 1598**
Colour: **BLUE** A/C: Insured / Std / NI / NA
Sp. Reading: **99557** T/A radio: Insured / Std / NI / NA
Eng/No: _____
C/No: **ZFA 26306006C51224**
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: **NI** / S/Rim / STD A/Rim or
Tyre Size: F: **195/60R16C**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHISU **PIB** / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.	06/08/19	D.O.A.	15/08/19

Survey held at **SIN SENG**

Des. of Damages: Frt / Rear / O/S **NI** / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
06/09/19	Confirmed US \$ 5,750/- @ 7 days with Rasul. (\$ 6,050.63 Red - 51%)

RECEIVED 06 SEP 2019

6/9/2019

Date/Time, File Pass 1st

06/09/19

1) **Typ: ct**

Date/Time, File Return 1st

2)

☐ : Preli. Report

☒ : Final Report

Days Of Repair: **7**

Resurvey No. of Trip: **1**

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) **5,750/- 45**

Survey Fee:

Transportation:

Photos

Others

TOTAL

170 + 15
50
50
58
343

1x15 = 15



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19005156MFSH

Date: 16 August 2019

Our Ref: CS/FCI19014152/R1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. GBE 9765S .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 15/08/2019 at the premises of M/s Sin Sheng Engineering Services and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,800.63</u>
Revised Estimate Amount	: S\$ <u>7,224.43</u>
"Check" Items Amount	: S\$ _____
Total	: S\$ _____
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the n/s body.



Comments/ Present Status:

Damages Consistent.
Repair days: 7 days

Yours faithfully,
Mohammed Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	07-08-2019	Our Ref No. D19005156MFSH
Accident Date	06-08-2019	Claim Type. Third Party
Insured Vehicle	SHC2987D	Third Party Vehicle. GBE9765S
Survey Location	NO 8 TUAS AVE 18 (LEVEL 3)	
Contact Person.	SUSAN	
Contact No.	6863 9595/ 0	Fax No. 6863 6477
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SIN SHENG ENGINEERING SERVICES	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Re: Our Ref: D19005156MFSH Pre-Repairs Assessment Request for GBE9765S -
accident involving with SHC2987D

sinsheng engineeringservices <sinsheng1981@gmail.com>

Thu 5/9/2019 2:38 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>

Hi Mr. Rasul,

We are agreed the offer.

**** KINDLY NOTE THAT WE ARE ALLOCATED AT NO 8 TUAS AVE 18 (LEVEL 5), SINGAPORE
638892 WITH IMMEDIATE EFFECT ****

Thank You

Regards

Pei Jin

Sin Sheng Engineering Services

No 8 Tuas Ave 18

Singapore 638892

(Level 3_Office)

(Level 5_Workshop)

Tel: 6863 9595

Fax: 6863 6477

On Thu, 5 Sep 2019 at 10:59, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Susan,

Refer to attachment

Finalised amount is \$ 5,750 / 7 days lump sum

Kindly confirm

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 August 2019 5:50 PM
To: 'Joanne Yong'; 'CWS Motor Claims'
Cc: assignments; SUR; Admin-D (LKKAuto)
Subject: RE: SURVEY ASSESSMENT - D19005156MFSH/1
Attachments: GBE 9765S - Preli Advise -.pdf

Dear Joanne,

Enclosed preliminary revised of vehicle GBE 9765S.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 14 August 2019 5:03 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Joanne Yong' <Joanneyong@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19005156MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed that repairer agreed survey on 15/08/2019.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Wednesday, 14 August 2019 4:32 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Joanne Yong

<JoanneYong@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19005156MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Company

Owner ID:

196N

Vehicle Details

Vehicle No.:

GBE9765S

Vehicle to be Exported:

Yes

Intended Deregistration Date:

31 Dec 2019

Vehicle Make:

FIAT

Vehicle Model:

DOBLO CARGO MAXI 1.6 MTJ AMT GLAZE

Primary Colour:

Grey

Manufacturing Year:

2016

Engine No.:

263A50007628798

Chassis No.:

ZFA26300006C51224

Maximum Power Output:

-

Open Market Value:

\$19,295.00

Original Registration Date:

17 May 2016

First Registration Date:

17 May 2016

Transfer Count:

0

Actual ARF Paid:

\$965.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

16 May 2026

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$46,502.00

COE Rebate Amount:

\$29,651.00

Total Rebate Amount:**\$29,651.00**

The information contained herein is correct as at 08 Aug 2019

OK

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002926

Date : 10/08/2019
Vehicle Num. : GBE9765S
Make/Model : FIAT DOBLO 1.6MJTD (E5)-2016
Chassis/Eng# : ZFA26300006C51224/263A5000762E
Accident Date : 06/08/2019
Claim No. :
Reference : SHC2987D
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT DOOR, LHS <i>repair bt</i>		2,615.62
2.	1	DOOR HANDLE OUTER LH <i>repair</i>		215.60X
3.	1	DOOR GARNISH X <i>sul</i>	6569.92	462.20X
4.	1	SIDE MIRROR, LHS <i>bt</i>		795.40
5.	1	DOOR GLASS LH <i>repair</i>	15%	398.20X
6.	1	RUNCHANNEL X <i>sul</i>		395.20X
7.	1	SLIDING DOOR, LH <i>bt</i>		2,863.50
8.	1	SLIDING DOOR HANDLE, LH <i>repair</i>	5584.43	245.30X
9.	1	SLIDING DOOR GARNISH X <i>sul</i>		355.20X
10.	1	SLIDING DOOR LOCK X <i>sul</i>		268.20X
11.	1	SIDE PANEL, LHS <i>repair</i>		2,152.10X
12.	1	SIDE PANEL GARNISH, LH <i>repair cut</i>		295.40
List Total S\$:				11,061.92
15.00% Discount S\$:				1,659.29
				9,402.63
NETT ITEMS :				
1.	1	COMPANY REGISTRATION STICKER <i>nc</i>		20.00
Nett Total S\$:				20.00
10.00% Discount S\$:				2.00
				18.00

CONTINUE / ...

SIN SHENG ENGINEERING SERVICES

NO 8, TUAS AVE 18,
(Level 3), SINGAPORE 638892
Tel No. : 6863-9595 Fax No. : 6863-6477
E-Mail : sinsheng1981@gmail.com
Buss. Reg. No. : 312029/00D

GOLDBELL LEASING PTE LTD
59 SENOKO ROAD
SINGAPORE 758123

Attention : Motor Claim Department
Contact : 6861 0007 Fax No. : 6753 7780

Estimate : ES002926

Date : 10/08/2019
Vehicle Num. : GBE9765S
Make/Model : FIAT DOBLO 1.6MJTD (E5)-2016
Chassis/Eng# : ZFA26300006C51224/263A5000762E
Accident Date : 06/08/2019
Claim No. :
Reference : SHC2987D
Policy No. : 29090793

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO PANEL BEAT/REPAIR LH BODY
TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS

SPRAY PAINTING

TO APPLY TUFF KOTE

TO CHECK WIRING

LOSS OF USE : 7 DAYS @ \$ 120/DAY

Labour Total S\$:

16/8/19
Panel
Hp 900/100 68
7 days
4/5

600	950.00
900	1,200.00
80	150.00
40	80.00
2,380.00	

1620

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15/08/19 @ 1530
Resy after repair

5584.43 Total S\$: 11,800.63
18.00
1620.00
7222.43
2020
5777.94
4/5 - 5,750 7 days

SIN SHENG ENGINEERING SERVICES



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19014152/R1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 10-09-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 2987D	Veh. Inspected	GBE 9765S	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19005156MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	14/08/2019	
2. Vehicle Particulars & Condition				
Make & Model	FIAT DOBLO CARGO MAXI 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	ZFA26300006C51224	Colour	BLUE	
Odometer	99557	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R16C	PIRELLI	6 mm	
L/H Front Tyre	195/60 R16C	PIRELLI	6 mm	
R/H Rear Tyre	195/60 R16C	PIRELLI	6 mm	
L/H Rear Tyre	195/60 R16C	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	06/08/2019	Inspection Date	15/08/2019	
Survey held at	NO 8 TUAS AVENUE 18 (LEVEL 3)			
Repairer	SIN SHENG ENGINEERING SERVICES			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 9765S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR,LHS	BENT	2,615.62	2,615.62
1	DOOR HANDLE OUTER LH	TO REPAIR SEE LABOUR	215.60	-
1	DOOR GARNISH	SERVICEABLE	462.20	-
1	SIDE MIRROR,LHS	BROKEN	795.40	795.40
1	DOOR GLASS LH	TO REPAIR SEE LABOUR	398.20	-
1	RUNCHANNEL	SERVICEABLE	395.20	-
1	SLIDING DOOR,LH	BENT	2,863.50	2,863.50
1	SLIDING DOOR HANDLE,LH	TO REPAIR SEE LABOUR	245.30	-
1	SLIDING DOOR GARNISH	SERVICEABLE	355.20	-
1	SLIDING DOOR LOCK	SERVICEABLE	268.20	-
1	SIDE PANEL,LHS	TO REPAIR SEE LABOUR	2,152.10	-
1	SIDE PANEL GARNISH,LH	CUT	295.40	295.40
	LESS 15% DISCOUNT		-1,659.29	-985.49
			9,402.63	5,584.43
NETT ITEMS				
1	COMPANY REGISTRATION STICKER (N)	NECESSARY	20.00	20.00
	LESS 10% DISCOUNT		-2.00	-2.00
			18.00	18.00
LABOUR				
	TO PANEL BEAT/REPAIR LH BODY.TO DISMANTLE/REPLACE ABOVEMENTIONED PARTS.INCLUSIVE OF THE REPAIR OF DOOR HANDLE OUTER LH,DOOR GLASS LH,SLIDING DOOR HANDLE,LH AND SIDE PANEL,LHS.		950.00	600.00
	SPRAY PAINTING.		1,200.00	900.00
	TO APPLY TUFF KOTE.		150.00	80.00
	TO CHECK WIRING.		80.00	40.00
			2,380.00	1,620.00

Report Ref No. CS/FCI19014152/R1sd3n2



GRAND TOTAL		11,800.63	7,222.43
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,750.00

Report Ref No. CS/FCI19014152/R1sd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.