

REF: CC3/MC19014161/Asd3 9

ASSIGNMENT

A. Arzoo
Merimen

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$1,300/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 107K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 1/2 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLN281SL Yr Regn: 2017 April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q3 C.C. 1395

Colour: Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 34339 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAU22846HROT1281

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SR / STD A/Rim or

Tyre Size: F: 235/55R17

R: 235/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm

D.O.A. _____ D.O.L. 12/08/19

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or Front N/S.

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	ODALG.
	SLN281SL - X
15/08/19	@ 09:36 am revised IA to ALG via merimen
15/08/19	@ 09:40 am mandate requested authorise repair to Victor via merimen
	MV:
	PV:
	Nett:
16/08/19	@ 11:12 am mandate approved by Victor 10th via merimen
16/08/19	@ 14:16 pm inform ALA to Ewan Huzar via email.
03/12/19	Adrian Confirmed P/P \$10,893.20 @ 5 days with Boss. C\$18,980.2 P46

RECEIVED 10 JAN 2020

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) Typist	2)	IN	Basic & Add.	3009/11
3)	4)	OUT	S + RS, SI	
5)	6)		Photos	
			Others	
			TOTAL	

Final Report: \$10,893.20 P/P
Resurvey No of Trip - 2

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	437F
Vehicle Details	
Vehicle No.:	SLN2815L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Aug 2019
Vehicle Make:	AUDI
Vehicle Model:	Q3 1.4 TFSI S TRONIC
Primary Colour:	Green
Manufacturing Year:	2017
Engine No.:	CZD283072
Chassis No.:	WAUZZZ8U6HR071281
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$29,729.00
Original Registration Date:	27 Apr 2017
First Registration Date:	27 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$33,621.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2027
PARF Rebate Amount:	\$25,215.00
Intended COE Rebate Details	
COE Expiry Date:	26 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$54,406.00
COE Rebate Amount:	\$41,877.00
Total Rebate Amount:	\$67,092.00

The information contained herein is correct as at 15 Aug 2019

OK

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Tuesday, 3 December 2019 11:36 am
To: Boo seng yak
Cc: Adrian Ling (LKKAuto); SUR; Carrine Leong; Chang Chee Sing; jiajee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION - SLN2815L - OD AIG - SURVEYED 14 AUG 19

Dear Mr. Boo,

Confirmed final fig \$10,893.20 @ 5 days of repairs before excess \$ 1,300/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 18 November 2019 4:07 pm
To: Adrian Ling (LKKAuto) <adrianling@lkkauto.com>; Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Chang Chee Sing <claims@premiumauto.com.sg>; jiajee.yap@premiumauto.com.sg
Subject: FINAL REVISION - SLN2815L - OD AIG - SURVEYED 14 AUG 19

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of \$10,893.20 @ 5 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Friday, 16 August 2019 2:16 PM
To: claims@premiumauto.com.sg
Cc: Admin A; Admin-D (LKKAuto); SUR
Subject: RE: OD CLAIM FOR SLN 2815 L ON 10/8/2019
Attachments: ESTIMATE.pdf

Dear Ezuwan Huzaini,

As instructed by our client, please proceed to repair the insured vehicle SLN 2815L (Excess S 1,300/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Thursday, 15 August 2019 5:01 PM
To: claims@premiumauto.com.sg; 'Admin A' <admin-a@lkkauto.com>; 'Admin-D (LKKAuto)' <admin-d@lkkauto.com>; 'SUR' <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SLN 2815 L ON 10/8/2019

Dear all,

Any updates on the repair approval?

Thank you.

Best Regards,
Ezuwan Huzaini
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg

View Received Message

This mail is associated with :

***SLN2815L**
OD
Aug 10 2019 1:00PM
[KOH POEY ING]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 16/08/2019 11:12 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$12838.00) - SLN2815L - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:12838.00:Re-inspection to be done for damage check and supplementary items / labour,

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 15 Aug 2019

Preliminary Advice

Vehicle No	: SLN2815L	Accident Date	: 10/08/2019
Make	: AUDI Q3	Policy No.	: 2100507983-02
Assignment Date	: 14/08/2019	Excess	: S\$0.00
Date of Inspection	: 14/08/2019	Est. Duration of Repair	: 5 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,874.00
Revised Amount	:S\$	12,838.00
Check Items (Estimated)	:S\$	4,687.00
Total	:S\$	17,525.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	67,092.00
Salvage Value	:S\$	
Margin for Repair	:S\$	39,908.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/08/2019 15:38
Date Of Accident	10/08/2019 13:00
Exact Location Of Accident	MT SINAI DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2815L
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KOH POEY ING
NRIC No	S0859437F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97883124
Alternative Phone No	HOME-64694038

Vehicle Particulars

Manufacturer	AUDI
Model	Q3-1.4 TFSI (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100507983-02
Cover Note Number	

Driver

Name of Driver	KOH POEY ING
NRIC No	S0859437F
Date Of Birth	01/11/1945
Occupation	INDOOR
Date Of Driving Pass	21/12/1966
Driving Experience	52 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97883124
Fax Number	
Contact Number	HOME-64694038
EMail Address	NOEMAIL

SKETCH PLAN

I understand, acknowledge, agree and consent that


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purpose(s).
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: F-2000
NR/CXN No.:

Accident Photo



Accident Photo





CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KOH POEY ING
 Period of Insurance : 27 Apr 2019 To 26 Apr 2020
 Engine No. : CZD283072
 Chassis No. : WAUZZZ8U6HR071281

Vehicle No. : SLN2815L
 Policy No. : 2100507983-02
 Endorsement No. :
 Issued Date : 16 Apr 2019

ABOUT THE COVER

Make/Model : AUDI Q3 1.4 TFSI (150BHP) DESIGN
 Engine Capacity/Tonnage : 1,395.00 CC Sum Insured : Market Value First Year of Registration : 2017
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1300 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KOH POEY ING - \$1300 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63862223

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125223

PREMIUM LEASING - SH
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0965/2019/NS
Date	:	14-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	MR KOH POEY ING
Address	:	61 MT SINAI DRIVE #02-05 Singapore 277113
Telephone	:	HP +65 97883124
Type of Claim	:	Own Damage Claims
Policy No.	:	2100507983-02
Vehicle No	:	SLN 2815 L
Model Code	:	Audi Q3 1.4 TFSI S TRO
Model / Year	:	27/4/2017
Engine No	:	CZD 283072
Chassis No	:	WAUZZZ8U6HR071281
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Aug-19
Place of Accident	:	MT SINAI DRIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLN 2815 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,600.00	1000. ✓
3	To respray front bumper, lhs front fender and bonnet.	\$ 3,400.00	1100. ✓
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 7,672.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLN 2815 L**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehnd</i>	S 1,788.00	✓ 1430.40
2	FRONT BUMPER FIXING PARTS <i>new</i>	S 99.00	+
3	FRONT AIR GUIDE GRILLE - LH <i>let</i>	S 139.00	✓ 111.20
4	FRONT GRILLE - CENTRE <i>new</i>	S 197.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER <i>new</i>	S 160.00	+
6	FRONT BUMPER SPOILER <i>Rehnd</i>	S 349.00	✓ 279.20
7	RADIATOR GRILLE <i>new</i>	S 1,053.00	+
8	RADIATOR GRILLE STRIKER PLATE <i>new</i>	S 111.00	+
9	FRONT BUMPER IMPACT BAR <i>Not Nec</i>	S 770.00	? X
10	FRONT BUMPER FOAM FILLER PIECE <i>Not Nec</i>	S 93.00	? X
11	IMPACT BAR TRIM <i>Not Nec</i>	S 59.00	? X
12	FRONT BUMPER COVER <i>new</i>	S 112.00	+
13	AIR CON STICKER <i>new</i>	NEC S 38.00	+
14	CAUTION SIGN <i>new</i>	NEC S 13.00	+
15	FRONT PARKING AID SENSOR - SIDE <i>Not Nec</i>	S 231.00	✓ X
16	FRONT PARKING AID SENSOR - INNER <i>new</i>	S 231.00	+
17	SIGNAL HORN - LH LOW TONE <i>Not Nec</i>	S 182.00	? X
18	FENDER - LH <i>Ryis</i>	S 824.00	+
19	FENDER ATTACHMENT PARTS <i>new</i>	S 63.00	+
20	FENDER BRACKET <i>new</i>	S 75.00	+
21	POP RIVET <i>new</i>	6 S 18.00	+
22	FRONT FENDER SUPPORT - LH <i>new</i>	S 96.00	+
SUB TOTAL SPARE PARTS		\$ 6,701.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 2815 L

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
22	WHEEL HOUSING LINER - LH <i>Not</i>	\$ 223.00	+
23	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not</i>	\$ 139.00	+
24	FRONT WHEEL SPOILER - LH <i>Not</i>	\$ 66.00	+
25	BONNET	\$ 3,205.00	+
26	BONNET EDGE PROTECTION - FRONT <i>Not</i>	\$ 25.00	+
27	BONNET LID LOCK <i>Not</i>	\$ 184.00	+
28	MAIN BEAM HEADLIGHT MOUNT - LH <i>Combined</i>	\$ 107.00	? ✓ 85.60
29	LOWER SUPPORT - LH <i>Not</i>	\$ 50.00	? X
30	UPPER SUPPORT - LH <i>Damaged</i>	\$ 60.00	? ✓ 47.60
31	RETAINING PLATE - LH <i>Not</i>	\$ 79.00	? X
32	LED HEADLIGHT - LH <i>Combined</i>	\$ 7,087.00	✓ 5669.60
33	CORNERING LIGHT POWER MODULE <i>Not</i>	\$ 508.00	? X
34	MAIN LIGHT ELECTRONICS <i>Not</i>	\$ 625.00	? X
35	LED UNIT - BLUE <i>Not</i>	\$ 712.00	? X
36	HEADLAMP FAN <i>Not</i>	\$ 363.00	? X
37	POWER MODULE CONTROL UNIT <i>Not</i>	\$ 520.00	? X
38	HEADLIGHT HOSE - LH <i>Not</i>	\$ 32.00	+ X
39	LIFT CYLINDER - LH <i>Damaged</i>	\$ 192.00	? ✓ 102.00
40	LIFT CYLINDER HOSE <i>Not</i>	\$ 170.00	+
41	ELBOW SUPPORT <i>Not</i>	\$ 54.00	+
42	WASHER RESERVOIR <i>Not</i>	\$ 200.00	+
43	FRONT WHEEL COVER - LH / RH <i>Not</i>	\$ 472.00	✓ 377.60
SUB TOTAL SPARE PARTS		\$ 15,073.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLN 2815 L**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
44	GROMMET <i>Not Nec</i>	18 \$ 44.00	✓ X
45	RADIATOR AIR GUIDE - LH <i>Not Nec</i>	\$ 23.00	✓ X
46	RADIATOR SEALING STRIP - CENTRE <i>Not Nec</i>	\$ 21.00	✓
47	FRONT NO. PLATE <i>Not Nec</i>	S/N \$ 40.00	✓
48	SUNDRIES <i>Nec</i>	\$ 300.00	✓ 17.00
TOTAL SPARE PARTS		\$ 22,202.00	
TOTAL LABOUR CHARGES		\$ 7,672.00	
GRAND TOTAL		\$ 29,874.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 14/08/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorized, 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0965/2019/NS
Date	:	14-Aug-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days of repairs - jb - 18 Nov 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	MR KOH POEY ING
Address	:	61 MT SINAI DRIVE #02-05 Singapore 277113
Telephone	:	HP +65 97883124
Type of Claim	:	Own Damage Claims
Policy No.	:	2100507983-02
Vehicle No	:	SLN 2815 L
Model Code	:	Audi Q3 1.4 TFSI S TRO
Model / Year	:	27/4/2017
Engine No	:	CZD 283072
Chassis No	:	WAUZZZ8U6HR071281
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	10-Aug-19
Place of Accident	:	MT SINAI DRIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLN 2815 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 3,600.00	\$ 1,000.00
3	To respray front bumper, lhs front fender and bonnet.	\$ 3,400.00	\$ 1,100.00
4	To carry out diagnostic check.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 7,672.00	\$ 2,772.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLN 2815 L**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 1,788.00	\$ 1,430.40
2	FRONT BUMPER FIXING PARTS	\$ 99.00	
3	FRONT AIR GUIDE GRILLE - LH	\$ 139.00	\$ 111.20
4	FRONT GRILLE - CENTRE	\$ 197.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER	\$ 160.00	
6	FRONT BUMPER SPOILER	\$ 349.00	\$ 279.20
7	RADIATOR GRILLE	\$ 1,053.00	
8	RADIATOR GRILLE STRIKER PLATE	\$ 111.00	
9	FRONT BUMPER IMPACT BAR	\$ 770.00	
10	FRONT BUMPER FOAM FILLER PIECE	\$ 93.00	
11	IMPACT BAR TRIM	\$ 59.00	
12	FRONT BUMPER COVER	\$ 112.00	
13	AIR CON STICKER	NEC \$ 38.00	
14	CAUTION SIGN	NEC \$ 13.00	
15	FRONT PARKING AID SENSOR - SIDE	\$ 231.00	
16	FRONT PARKING AID SENSOR - INNER	\$ 231.00	
17	SIGNAL HORN - LH LOW TONE	\$ 182.00	
18	FENDER - LH	\$ 824.00	
19	FENDER ATTACHMENT PARTS	\$ 63.00	
20	FENDER BRACKET	\$ 75.00	
21	POP RIVET	6 \$ 18.00	
22	FRONT FENDER SUPPORT - LH	\$ 96.00	
	SUB TOTAL SPARE PARTS	\$ 6,701.00	\$ 1,820.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 2815 L

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 1,820.80
22	WHEEL HOUSING LINER - LH		\$ 223.00	
23	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 139.00	
24	FRONT WHEEL SPOILER - LH		\$ 66.00	
25	BONNET		\$ 3,205.00	
26	BONNET EDGE PROTECTION - FRONT		\$ 25.00	
27	BONNET LID LOCK		\$ 184.00	
28	MAIN BEAM HEADLIGHT MOUNT - LH		\$ 107.00	\$ 85.60
29	LOWER SUPPORT - LH		\$ 50.00	
30	UPPER SUPPORT - LH		\$ 60.00	\$ 47.60
31	RETAINING PLATE - LH		\$ 79.00	
32	LED HEADLIGHT - LH		\$ 7,087.00	\$ 5,669.60
33	CORNERING LIGHT POWER MODULE		\$ 508.00	
34	MAIN LIGHT ELECTRONICS		\$ 625.00	
35	LED UNIT - BLUE		\$ 712.00	
36	HEADLAMP FAN		\$ 363.00	
37	POWER MODULE CONTROL UNIT		\$ 520.00	
38	HEADLIGHT HOSE - LH		\$ 32.00	
39	LIFT CYLINDER - LH		\$ 192.00	\$ 102.00
40	LIFT CYLINDER HOSE		\$ 170.00	
41	ELBOW SUPPORT	2	\$ 54.00	
42	WASHER RESERVOIR		\$ 200.00	
43	FRONT WHEEL COVER - LH / RH		\$ 472.00	\$ 377.60
	SUB TOTAL SPARE PARTS		\$ 15,073.00	\$ 8,103.20

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLN 2815 L

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 8,103.20
44	GROMMET	18	\$ 44.00	
45	RADIATOR AIR GUIDE - LH		\$ 23.00	
46	RADIATOR SEALING STRIP - CENTRE		\$ 21.00	
47	FRONT NO. PLATE	S/N	\$ 40.00	
48	SUNDRIES		\$ 300.00	\$ 18.00
TOTAL SPARE PARTS			\$ 22,202.00	\$ 8,121.20
TOTAL LABOUR CHARGES			\$ 7,672.00	\$ 2,772.00
GRAND TOTAL			\$ 29,874.00	\$ 10,893.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLN 2815 L

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0965/2019/NH

9TH JAN 2020

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLN 2815 L, Audi Q3 1.4 TFSI S TRONIC.

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLN 2815 L**, claimant, **Ms. Koh Poey Ing**, please find the related document per attached.

1. A copy of the Original invoice no. 85014703 – S\$ 10,264.72.
2. A copy of the Discharge Voucher duly signed by client.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SLN 2815 L

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6536 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:32

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85014703 Date : 07/01/2020 Order : SLN2815L Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SLN2815L (V 33312)	Regn Date: 27/04/2017	Mileage: 37508	WIP No.: 63858
Model: Q3 1.4 TFSI S tronic 8UGARX	Chassis: WAUZZZ8U6HR071281	Engine: C2D 283072	Dept: u
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1300.00	1.00	-1,300.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT.TO REPAIR LHS FRONT FENDER. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	1100.00	1.00	1,100.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	ASU0807065L GRU	COVER Less 020%	1.00	1788.00	1,430.40
X	ASU0807681P 4U8	GRILL Less 020%	1.00	139.00	111.20
X	ASU0807061N 4U8	(SHARE)FR.SPOILER Less 020%	1.00	349.00	279.20
X	ASU0805607A	MOUNTING - A/P Less 020%	1.00	107.00	85.60
X	ASU0805931	SUPPORT - A/P Less 020%	1.00	59.50	47.60
X	ASU0941773A	HEADLIGHT Less 020%	1.00	7087.00	5,669.60
X	ASU0853717 4U8	COVER Less 020%	1.00	236.00	188.80
X	ASU0853718 4U8	COVER Less 020%	1.00	236.00	188.80
X	ASU0805333	SUPPORT - A/P Less 020%	1.00	22.50	18.00
X	ASU0955101D	CYLINDER - A/P Less 020%	1.00	127.50	102.00

Parts 8,121.20
Labour 0.00
Sublet 2,772.00
Menus 0.00
Lubricant 0.00



Sub-Total	9,593.20
7% GST	671.52
Grand Total	10,264.72

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SME 2529 Z

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0965/2019/EH
21 August 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi Q3 1.4 TFSI S TRO
Vehicle Chassis No. : WAUZZZ8U6HR071281
Vehicle Regn No. : SLN 2815 L
Vehicle Mileage : 34339 KM
Vehicle Owner : Ms. Koh Poey Ing
Certificate No. : 2100507983-02
Own Damage Excess : \$1,391.00 (Inclusive GST)
Accident Date : 10/08/2019
Place : MT SINAI DRIVE
Repair Cost : S\$ 10264.72
WIP No. : 63858
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733


Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

Time :

Date :


1630 hrs
22/8

DISCHARGE VOUCHER- AIG - SLN 2815 L

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Aug 2019		14 Aug 2019 18:47 Edit Adj Rpt	S\$10,893.20 Edit Estimates	S\$10,893.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH POEY ING, ID: S0859437F, Tel: +6597883124, Email: NOEMAIL								
Vehicle Reg. No.:	SLN2815L	Date of Loss:	10/08/2019 13:00 - :59 [27 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 7441180715SG	Policy/Cover Note No.:	2100507983 (Comprehensive) Coverage: 27/04/2019 - 26/04/2020						
		Excess:	S\$1,300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 23/08/2019]								
Driver/Custodian:	KOH POEY ING (73 / Male), NRIC: S0859437F, Tel: +6597883124 Email: NOEMAIL								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (16/08/2019): Alert - Adj Mandate Approved (S\$12838.00) - SLN2815L - Claim Handler: Mithoo Sin... - AIG_SG (15/08/2019): SLN2815L / OD / 10/08/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN2815L (7441180715SG)

OD

Aug 10 2019 1:00PM

[KOH POEY ING]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Assessment Reports						1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	15/08/19 09:36	Adjuster Immediate Advice			Load HTM		
Photos/Images						3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	15/08/19 09:39	General View			Load JPG		☒
2	15/08/19 09:39	General View			Load JPG		☒
3	15/08/19 09:39	General View			Load JPG		☒
4	15/08/19 09:39	General View			Load JPG		☒
5	15/08/19 09:39	General View			Load JPG		☒
6	15/08/19 09:39	General View			Load JPG		☒
7	15/08/19 09:39	General View			Load JPG		☒
8	15/08/19 09:39	General View			Load JPG		☒
9	15/08/19 09:39	General View			Load JPG		☒
10	15/08/19 09:39	General View			Load JPG		☒
11	15/08/19 09:39	General View			Load JPG		☒
12	15/08/19 09:39	General View			Load JPG		☒
13	15/08/19 09:39	General View			Load JPG		☒
14	15/08/19 09:39	General View			Load JPG		☒
15	15/08/19 09:39	General View			Load JPG		☒
16	15/08/19 09:39	General View			Load JPG		☒
17	15/08/19 09:39	General View			Load JPG		☒
18	15/08/19 09:39	General View			Load JPG		☒
19	15/08/19 09:39	General View			Load JPG		☒
20	15/08/19 09:39	General View			Load JPG		☒
21	15/08/19 09:39	General View			Load JPG		☒
22	15/08/19 09:39	General View			Load JPG		☒
23	15/08/19 09:39	General View			Load JPG		☒
24	28/11/19 17:30	Reinspection Photo			Load JPG		☒
25	28/11/19 17:30	Reinspection Photo			Load JPG		☒
26	28/11/19 17:30	Reinspection Photo			Load JPG		☒
27	28/11/19 17:30	Reinspection Photo			Load JPG		☒
28	28/11/19 17:30	Reinspection Photo			Load JPG		☒
29	28/11/19 17:30	Reinspection Photo			Load JPG		☒
30	28/11/19 17:30	Reinspection Photo			Load JPG		☒
31	28/11/19 17:30	Reinspection Photo			Load JPG		☒
32	28/11/19 17:30	Reinspection Photo			Load JPG		☒
33	28/11/19 17:30	Reinspection Photo			Load JPG		☒
34	28/11/19 17:30	Reinspection Photo			Load JPG		☒
35	28/11/19 17:30	Reinspection Photo			Load JPG		☒
36	28/11/19 17:30	Reinspection Photo			Load JPG		☒
37	28/11/19 17:30	Reinspection Photo			Load JPG		☒
38	28/11/19 17:30	Reinspection Photo			Load JPG		☒
39	28/11/19 17:30	Reinspection Photo			Load JPG		☒
40	28/11/19 17:30	Reinspection Photo			Load JPG		☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/08/19 09:38	SLN 2815L GIA.pdf		Load PDF
2	15/08/19 09:38	DRIVING & CI.pdf		Load PDF
3	15/08/19 09:38	ESTIMATE.pdf		Load PDF
4	03/12/19 11:33	ESTIMATE MARKED.pdf		Load PDF
5	14/01/20 09:47	DISCHARGE VOUCHER		Load PDF
6	14/01/20 09:47	WORKSHOP INVOICE		Load PDF

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	04/09/19 02:30	Accident Statement		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/08/19 15:46	Accident Photo		Load JPG ☒
2	13/08/19 15:46	Accident Photo		Load JPG ☒
3	13/08/19 15:46	Accident Photo		Load JPG ☒
4	13/08/19 15:46	Accident Photo		Load JPG ☒
5	13/08/19 15:46	Accident Photo		Load JPG ☒
6	13/08/19 15:46	Accident Photo		Load JPG ☒
7	13/08/19 15:46	Accident Photo		Load JPG ☒
8	13/08/19 15:46	Accident Photo		Load JPG ☒
9	13/08/19 15:46	Accident Photo		Load JPG ☒
10	13/08/19 15:46	Accident Photo		Load JPG ☒
11	13/08/19 15:46	Accident Photo		Load JPG ☒
12	13/08/19 15:46	Accident Photo		Load JPG ☒
13	13/08/19 15:46	Accident Photo		Load JPG ☒
14	13/08/19 15:46	Accident Photo		Load JPG ☒
15	13/08/19 15:46	Accident Photo		Load JPG ☒
16	13/08/19 15:46	Accident Photo		Load JPG ☒
17	13/08/19 15:46	Accident Photo		Load JPG ☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	13/08/19 15:47	Sketch Plan		Load JPG ☒
2	13/08/19 15:47	Sketch Plan #2		Load JPG ☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19014161/ASD3Q2

Date: 14/01/2020

REFERENCE

Insured/Claimant: KOH POEY ING Policy No: 2100507983
Date of Loss: 10/08/2019 Nature of Claim: OD Claim No: 7441180715SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN2815L**
Make & Model: AUDI Q3, 1.4 TFSI (A) Engine No: CZD283072
Reg. Date: 27/04/2017 (Man. Year: 2017) Chassis No: WAUZZZ8U6HR071281
Colour: Grey Odometer: 34339 km
Engine Capacity: 1395 cc
Market Value/New Car Price: S\$107,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R17 Rear Tyre Size: 235/55 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,202.00	8,121.20	14,080.80	63.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,672.00	2,772.00	4,900.00	63.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,874.00	10,893.20	18,980.80	63.54
- Excess (S\$)	1,300.00	1,300.00	0.00	0.00
(S\$)	28,574.00	9,593.20	18,980.80	66.43
+ GST 7.00/7.00% (S\$)	2,000.18	671.52	1,328.66	66.43
Nett Amount (S\$)	30,574.18	10,264.72	20,309.46	66.43

INSPECTION

Date of Assignment: 14/08/2019

Date Inspected: 14/08/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,788.00 FS	*1,430.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	99.00 FS	*- FS
3	1		*FRONT AIR GUIDE GRILLE -LH	Cut	139.00 FS	*111.20 FS
4	1		*FRONT GRILLE -CENTRE	Not Necessary	197.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER	Not Necessary	160.00 FS	*- FS
6	1		*FRONT BUMPER SPOILER	Deformed	349.00 FS	*279.20 FS
7	1		*RADIATOR GRILLE	Not Necessary	1,053.00 FS	*- FS
8	1		*RADIATOR GRILLE STRIKER PLATE	Not Necessary	111.00 FS	*- FS
9	1		*FRONT BUMPER IMPACT BAR	Not Necessary	770.00 FS	*- FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	93.00 FS	*- FS
11	1		*IMPACT BAR TRIM	Not Necessary	59.00 FS	*- FS
12	1		*FRONT BUMPER COVER	Not Necessary	112.00 FS	*- FS
13	1		*AIR CON STICKER	Not Necessary	38.00 FS	*- FS
14	1		*CAUTION SIGN	Not Necessary	13.00 FS	*- FS
15	1		*FRONT PARKING AID SENSOR -SIDE	Not Necessary	231.00 FS	*- FS
16	1		*FRONT PARKING AID SENSOR -INNER	Not Necessary	231.00 FS	*- FS
17	1		*SIGNAL HORN -LH LOW TONE	Not Necessary	182.00 FS	*- FS
18	1		*FENDER -LH	Repair	824.00 FS	*- FS
19	1		*FENDER ATTACHMENT PARTS	Not Necessary	63.00 FS	*- FS
20	1		*FENDER BRACKET	Not Necessary	75.00 FS	*- FS
21	6		*POP RIVET	Not Necessary	18.00 FS	*- FS
22	1		*FRONT FENDER SUPPORT -LH	Not Necessary	96.00 FS	*- FS
23	1		*WHEEL HOUSING LINER -LH	Not Necessary	223.00 FS	*- FS
24	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	139.00 FS	*- FS
25	1		*FRONT WHEEL SPOILER -LH	Not Necessary	66.00 FS	*- FS
26	1		*BONNET	Not Necessary	3,205.00 FS	*- FS
27	1		*BONNET EDGE PROTECTION -FRONT	Not Necessary	25.00 FS	*- FS
28	1		*BONNET LID LOCK	Not Necessary	184.00 FS	*- FS
29	1		*MAIN BEAM HEADLIGHT MOUNT -LH	Cracked	107.00 FS	*85.60 FS
30	1		*LOWER SUPPORT LH	Not Necessary	50.00 FS	*- FS
31	1		*UPPER SUPPORT LH	Damaged	60.00 FS	*47.60 FS
32	1		*RETAINING PLATE-LH	Not Necessary	79.00 FS	*- FS
33	1		*LED HEADLIGHT -LH	Cracked	7,087.00 FS	*5,669.60 FS
34	1		*CORNERING LIGHT POWER MODULE	Not Necessary	508.00 FS	*- FS
35	1		*MAIN LIGHT ELECTRONICS	Not Necessary	625.00 FS	*- FS
36	1		*LED UNIT-BLUE	Not Necessary	712.00 FS	*- FS
37	1		*HEADLAMP FAN	Not Necessary	363.00 FS	*- FS
38	1		*POWER MODULE CONTROL UNIT	Not Necessary	520.00 FS	*- FS
39	1		*HEADLIGHT HOSE-LH	Not Necessary	32.00 FS	*- FS
40	1		*LIFT CYLINDER -LH	Damaged	192.00 FS	*102.00 FS
41	1		*LIFT CYLINDER HOSE	Not Necessary	170.00 FS	*- FS
42	1		*ELBOW SUPPORT	Not Necessary	54.00 FS	*- FS
43	1		*WASHER RESERVOIR	Not Necessary	200.00 FS	*- FS
44	2		*FRONT WHEEL COVER-LH/RH	Necessary	472.00 FS	*377.60 FS
45	18		*GROMMET	Not Necessary	44.00 FS	*- FS
46	1		*RADIATOR AIR GUIDE -LH	Not Necessary	23.00 FS	*- FS
47	1		*RADIATOR SEALING STRIP-CENTRE	Not Necessary	21.00 FS	*- FS
48	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*- FS
49	1		*SUNDRIES	Necessary	300.00 FS	*18.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 22,202.00 8,121.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ,LHS FRONT FENDER ,BONNET AND LHS HEADLIGHT .RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	3,600.00	1,000.00
3	TO RESPRAY FRONT BUMPER ,LHS FRONT FENDER AND BONNET	New	3,400.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			7,672.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >