

# Performance Motors Limited

A member of the Sims Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## Final Report

Estimate No. : b1 52318  
Date Estimated : 14/08/2019  
Prepared By : Chua Kee Sin

- ESTIMATE REPAIR FOR -  
Tan Chee Keong (Chen ZhiQiang)  
70B Telok Blangah Heights  
#22-527

- ACCOUNT - 219  
Cash Sales - Service  
Singapore

Singapore 102070

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGC10Y	WBAJA12080WW39211	28/06/2019	520i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front M bumper and remove attachment etc including to remove and install body parts in order to carry out painting job.	850.00	0.00	850.00
To respray front M bumper.	934.00	0.00	934.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00	0.00	150.00
To replace right LED AHL headlight.	408.00	0.00	408.00
Sundries.	80.00	0.00	80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RH FINISHER DECO HIGH-GLOSS BLACK	80.30	1.00	0.00	80.30 #
# FRT BUMPER PANEL PRIMED (M)	1,653.55	1.00	0.00	1,653.55 #
# RH HEADLIGHT LED AHL HIGH (ICON LIG	4,855.25	1.00	0.00	4,855.25 #

### # SUPPLEMENTARY ITEMS

QD	QD PRICE	DATE	QTY
FAX TO FAX NO	Tau fith	29/9/19	3
FAX TO FAX NG	LEK		
FAX TO FAX NO			
CONFIRMED DATE			

Total Labour : 2,422.00  
Total Parts : 6,589.10  
Total Labour & Parts : 9,011.10  
Deduction for Excess :  
Total Repair Costs less Excess: 9,011.10 ✓  
GST @7%: 630.78  
Grand Total : 9,641.88

LOSS OF USE=\$120 X 3DAYS  
GIA SEARCH FEE=\$2.00