

Section A - Accident Details

Registration Number	SHB706S
Case Reference Number	TAX/08/19/2022
Registration Date	12/12/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	PHNG CHIAN SENG
Type of Accident	Others
Accident Date and Time	9/8/2019 3:55 PM
Accident Reported Date and Time	10/8/2019 9:46 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24102783
Special Instruction to ARC, if any	DROVE IN
Prepared Date and Time	10/8/2019 11:43 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify the Repairer of the following:


- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$300.00
Total Spray Cost	\$936.00	\$400.00
Total Spare Part Cost	\$3,973.49	\$3,389.69
Total Other Cost	\$240.00	\$40.00
TOTAL COST	\$5,656.49	\$4,129.69 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	10/08/2019 11:59 AM	13/08/2019 3:05 PM
Signature		
Remarks	P/P repair, take before spray. Finalize sent to stevechen@lkkauto.com.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1908-0519	Invoice Number	
Quotation Date	29.08.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	\$507.00	\$300.00 ✓
Total Labour	\$507.00	\$300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00 ✗
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 ✓
Total Spray Painting & Panel Beating	\$936.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 ✓
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00 ✓
TO WASH AND VACUUM	\$60.00	\$0.00 ✗
Total Other Costs	\$240.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace ✓
		52116470 50	SUPPORT, FR BUMPER LH	0.00	\$82.30	0.00	\$0.00	Replace	Not Given ✗
		52128479 06	COVER, FR BUMPER LH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given ✗
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace ✓
		81185476 91	UNIT, HEADLAMP, LH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace ✓
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$318.80	0.00	\$0.00	Replace	Not Given ✗
		52592470 40	SEAL, RR BUMPER, LH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given ✗
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given ✗
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given ✗
		53214470 50	SUPPORT, RADIATOR UPPER LH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given ✗
		53301471 10	HOOD SUB-ASSY	1.00	\$938.40	25.00	\$703.80	Replace	Replace ✓
Total					\$4,772.70		\$3,389.69		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3389.69
+ 300.00
+ 440.00
4129.69

DD
NN
NN
NEC
BR
NN
NN
NN
NN
NN
DD