

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 4873P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRUMPLED	1,050.20	1,050.20
10	FRONT BUMPER CLIP @\$3.90	NECESSARY	39.00	30.00
1	FRONT BUMPER RETAINER (RH)	BROKEN	25.00	25.00
1	FRONT BUMPER LOWER AIR GRILLE	CRUMPLED	145.00	145.00
1	FRONT BUMPER TOW COVER	SERVICEABLE	28.00	-
1	FRONT FOG LAMP COVER (RH)	CRUMPLED	165.00	64.50
1	FRONT FOG LAMP (RH)	SERVICEABLE	220.00	-
1	FRONT GRILLE BASE	SERVICEABLE	395.00	-
1	FRONT GRILLE CHROME	SERVICEABLE	305.50	-
1	FRONT GRILLE CHROME (LOWER)	SERVICEABLE	220.70	-
1	FRONT HEADLAMP (RH)	SERVICEABLE	2,450.00	-
1	FRONT HEADLAMP BRACKET (RH)	SERVICEABLE	38.50	-
1	FRONT FENDER (RH)	SERVICEABLE	435.00	-
1	FRONT FENDER BRACKET (RH)	SERVICEABLE	49.00	-
1	FRONT FENDER INNER SHIELD (RH)	SERVICEABLE	110.50	-
10	FRONT FENDER INNER SHIELD CLIP @\$3.90	SERVICEABLE	39.00	-
1	FRONT REINFORCEMENT	BENT	297.00	297.00
1	WASHER TANK	CRUMPLED	145.00	145.00
1	FRONT SUPPORT PANEL (ADDITIONAL)	BENT	785.00	785.00
	LESS 20% DISCOUNT		-1,388.48	-508.34
			5,553.92	2,033.36
	<u>LABOUR</u>			
	TO DISMANTLE, CUT AND WELD FRONT PANEL, CHANGE FRONT RH HEADLAMP, FRONT REINFORCEMENT, FRONT BUMPER, KNOCKING & PULL STRAIGHT FRONT RH CHASSIS FRAME AND ALL AREA AFFECTED BY ACCIDENT.		900.00	600.00
	TO PERFORM WIRE CHECKING.		20.00	20.00
	TO DISMANTLE & REFIT FRONT RADIATOR, AIRCON CONDENSOR AND TOP UP AIRCON GAS.		100.00	100.00

Report Ref No. CS/FCI19014173/Qsf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY FRONT BUMPER, FRONT REINFORCEMENT, FRONT SUPPORT PANEL, FRONT RH FENDER AND BONNET.		800.00	500.00
			1,820.00	1,220.00
GRAND TOTAL			7,373.92	3,253.36
RECOMMENDED COST OF REPAIRS				3,253.36

Report Ref No. CS/FCI19014173/Qsf3e2

OI SUN PIN

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.